RJO'CONNELL & ASSOCIATES, INC.

CIVIL ENGINEERS, SURVEYORS & LAND PLANNERS

 80 Montvale Ave., Suite 201
 Stoneham, MA 02180

 phone
 781-279-0180
 fax
 781-279-0173

February 18, 2020

Juliet Walker, Planning Director Planning Department City of Portsmouth 1 Junkins Ave, 3rd Floor Portsmouth, NH 03801

Regarding: Durgin Square, 1600 Woodbury Ave

Dear Ms. Walker,

Attached please find the complete set of site plans dated 02/18/2020 as well as the Stormwater Summary for the project. In cooperation with Stephen G. Pernaw & Company, Inc., R.J. O'Connell & Associates, Inc. has summarized the following comments received from the TAC via email on January 7th, 2020. We have reviewed the comments listed below in italics with responses following:

1. The National Cooperative Highway Research Program, in their Report 457, provides guidance for when a right turn bay should be provided at an intersection. Based on the speed and volume of traffic on Woodbury Avenue, together with the expected volume of right turns into the proposed driveway, a right turn bay should be provided. A right turn bay can significantly improve operations and safety at the intersection, as it effectively separates those vehicles that are slowing or stopped to turn, from those vehicles in the through traffic lanes. This separation minimizes turn-related collisions such as angle, rear-end, and same-direction-sideswipe, and eliminates unnecessary delay to through vehicles.

Response: The warrants for requiring a right-turn lane are satisfied based on NCHRP 457 guidelines however, according to the right-of-way line on the Traffic Control Plan, there is not sufficient right-of-way width to accomplish this. Additionally, it would require the relocation of at least 2 utility poles and one mast arm foundation. The design has been revised to provide a longer taper for incoming right turns and the right-out has been eliminated.

2. The traffic memo states that a driveway on Woodbury would allow direct access to the site without impacting Durgin Lane. Given that the traffic volumes on Woodbury Ave are more than 3 times greater than the volume on Durgin Lane, and that Durgin Lane traffic is all local traffic turning in and out of commercial driveways, and that vehicle queues on Durgin Lane, as reported in the referenced Woodbury Ave Engineering Study, do not extend back past the first site driveway, the impact to Durgin Lane traffic would be negligible and not a reason to provide a major driveway on Woodbury Ave.

Response: This is correct however, the 2027 95th percentile queue in the corridor study is 140'. There is approximately 175' of storage available which is sufficient and leaves a surplus queue for approximately 1.5 cars.

3. While having several driveways helps to disperse the site traffic, the site already has 7 access points, which is more than sufficient to adequately disperse the site generated traffic. There is no need for another major access point, as the level of service and capacity at the signalized intersections is not a cause for concern.

Response: The proposal is not to increase the number of access points; the project proposes to convert one existing full-access driveway to a limited-access right-in driveway. It is not a "major access point", it is a limited access driveway.

4. The City recently completed a major signal improvement project (over \$1M) along the Woodbury Avenue corridor to improve traffic operations, flow and safety. This proposed driveway would have a negative impact on traffic flow and safety, as it creates a new major driveway between two closely spaced signals, without a right turn lane.

Response: The proposed driveway will improve traffic flow by eliminating left and right-turn departures and left-turn arrivals, which are currently allowed to/from the existing entry to GameStop.

5. While state driveway standards allow for driving spacing as stated in the memo, the state driveway standards also require 30-foot-wide driveway lanes with a minimum of 20 feet between the entering and exiting lanes of a driveway such as this. There is no separation between the lanes in the proposed driveway design, and the lanes are only 12 feet wide.

Response: The project complies with the 30' throat width guideline, but not the 20' between inbound and outbound lanes. The project proposes a "single drive" per NHDOT Figure III (not Figure IV). The design has been modified to include a single 16' wide incoming right turn lane into the site.

6. If the median island were extended beyond the right-turn-out portion of the proposed driveway, a right-turn-out only driveway may be considered, but not the right turn entering in the presently proposed configuration.

Response: The plans have been revised to include an extended median island along Woodbury Ave.

7. Fire Department still has concerns regarding access to the rear of the building. Particularly with trucks at the loading docks.

Response: A fire lanes has been added to the plans and will be delineated by new pavement markings adjacent to the building at the fire department connection.

8. A line of shade trees should be considered for the wide landscape areas adjacent the proposed driveway. In order to maintain views into the site the trees could be planted toward the rear of the landscape area.

Response: Shade trees would inhibit the view corridor to the proposed supermarket. The Planting Plan provides areas of shrubs and shorter plantings.

We believe these responses adequately address the City's comments received from the Technical Advisory Committee. Refer to the attached exhibits for additional information. Revised plans and documents are attached to address the comments as described herein.

Please call me if you have any questions at 781-279-0180.

Sincerely,

RJO'CONNELL & ASSOCIATES

Stephen P. Glowacki Associate Principal

Cory M asar

Cory Mason, PE Project Engineer

cc: Alicia Busconi (KeyPoint), Rachel Cormier (KeyPoint), Christopher Mulligan, Esq. (Bosen), John Bosen, Esq. (Bosen), Stephen Pernaw (Pernaw)

GOVERNMENT/UTILITY CONTACTS

OFFICE OF THE MAYOR: CITY HALL 1 JUNKINS AVENUE PORTSMOUTH, NH 03801 ATTN: RICK BECKSTED, MAYOR PHONE: (603) 610-7200

CITY CLERK'S OFFICE: CITY HALL 1 JUNKINS AVENUE PORTSMOUTH, NH 03801 ATTN: KELLI BARNABY, CITY CLERK PHONE: (603) 610-7245

HEALTH DEPARTMENT: CITY HALL 1 JUNKINS AVENUE PORTSMOUTH, NH 03801 ATTN: KRISTIN SHAW, HEALTH OFFICER PHONE: (603) 610-4187

COMMUNITY DEVELOPMENT DEPARTMENT: CITY HALL 1 JUNKINS AVENUE PORTSMOUTH, NH 03801 ATTN: ELISE ANNUNZIATA PHONE: (603) 610-7281

DEPARTMENT OF PUBLIC WORKS: 680 PEVERLY HILL ROAD PORTSMOUTH, NH 03801 ATTN: PETER RICE, DIRECTOR PHONE: (603) 427-1530

INSPECTION DEPARTRMENT: CITY HALL 1 JUNKINS AVENUE PORTSMOUTH, NH 03801 ATTN: ROBERT MARSILIA, CHIEF BUILDING INSPECTOR PHONE: (603) 610-7243 ASSESSOR'S OFFICE: CITY HALL 1 JUNKINS AVENUE PORTSMOUTH, NH 03801 ATTN: ROSANN MAURICE-LENTZ, CITY ASSESSOR PHONE: (603) 610-7249

ZONING BOARD OF ADJUSTMENT: CITY HALL 1 JUNKINS AVENUE PORTSMOUTH, NH 03801 ATTN: PETER STITH, PRINCIPAL PLANNER PHONE: (603) 610-4188

CONSERVATION COMMISSION: CITY HALL 1 JUNKINS AVENUE PORTSMOUTH, NH 03801 ATTN: PETER BRITZ, PLANNER/COORDINATOR PHONE: (603) 610-7215

CITY ENGINEER: 680 PEVERLY HILL ROAD PORTSMOUTH, NH 03801 ATTN: TERRY DESMARAIS P.E., CITY ENGINEER PHONE: (603) 427-1530

PLANNING BOARD: CITY HALL 1 JUNKINS AVENUE PORTSMOUTH, NH 03801 ATTN: JULIET WALKER, PLANNING DIRECTOR PHONE: (603) 610-7216

POLICE DEPARTMENT: 3 JUNKINS AVENUE PORTSMOUTH, NH 03801 ATTN: ROBERT MERNER, CHIEF OF POLICE PHONE: (603) 427-1500 FIRE DEPARTMENT: 170 COURT STREET PORTSMOUTH, NH 03801 ATTN: TODD GERMAIN, FIRE CHIEF PHONE: (603) 427-1515

RECREATION DEPARTMENT: 155 PARROT AVENUE PORTSMOUTH, NH 03801 ATTN: RUS WILSON, RECREATION DIRECTOR PHONE: (603) 427-1548

WATER AND WASTEWATER AND SEWER: 680 PEVERLY HILL ROAD PORTSMOUTH, NH 03801 ATTN: TERRY DESMARAIS P.E., CITY ENGINEER PHONE: (603) 427-1530

ELECTRIC - EVERSOURCE 265 CALEF HIGHWAY EPPING, NH 03042 PHONE: (800) 662-7764

GAS - UNITIL 6 LIBERTY LANE W HAMPTON, NH 03842 PHONE: (888) 301-7700

TELEPHONE - CONSOLIDATED COMMUNICATIONS 56 ISLINGTON STREET PORTSMOUTH, NH 03801 PHONE: (844) 968-7224


CONSULTANTS

TRAFFIC: STEVEN G. PERNAW & COMPANY, INC. P.O. BOX 1721 CONCORD, NH 03302 PHONE: (603) 731-8500

LANDSCAPING: MDLA MICHAEL D'ANGELO LANDSCAPE ARCHITECTS, LLC 732 EAST BROADWAY BOSTON, MA 02127 PHONE: (203) 592-4788

ARCHITECT: DEAN ASSOCIATES ARCHITECTS, INC. 7 KIMBALL LANE SUITE E6 LYNNFIELD, MA 01940 PHONE: (781) 397-8092

SITE PLAN FOR DURGIN SQUARE PORTSMOUTH, NH



Drawing Date Last Revision		Drawing	Drawing Description		
02/18/2020	-	-	COVER SHEET		
02/18/2020	-	EX-1	EXISTING CONDITIONS PLAN		
02/18/2020	-	0S-1	OVERALL SITE PLAN		
02/18/2020	-	C-1	DEMOLITION PLAN AND EROSION CONTROL		
02/18/2020	-	C-2	GRADING, DRAINAGE AND UTILITY PLAN		
02/18/2020	-	C-3	PARKING AND TRAFFIC CONTROL PLAN		
02/18/2020	-	L-1	PLANTING PLAN (BY MDLA)		
02/18/2020	-	FT-1	FIRE TRUCK TURNING PLAN		
02/18/2020	-	C-4	SITE DETAILS - I		
02/18/2020	-	C-5	SITE DETAILS - II		
02/18/2020	-	SP-1	SITE LAYOUT PLAN (FOR RCRD RECORDING)		
02/18/2020	-	SP-2	OVERALL PLAN (FOR RCRD RECORDING)		

PREPARED BY:

RJO'CONNELL & Associates, Inc.

CIVIL ENGINEERS, SURVEYORS & LAND PLANNERS 80 MONTVALE AVENUE STONEHAM, MA 02180 PHONE: 781-279-0180 FAX: 781-279-0173


PREPARED FOR:

KEYPOINT™ PARTNERS Unlocking Value in Commercial Real Estate ONE BURLINGTON WOODS DRIVE BURLINGTON, MA 01803 ATTN: ALICIA BUSCONI PHONE: (781) 418-6203

ISSUED FOR TAC REVIEW FEBRUARY 18, 2020

Drawing Index

Planning Board	
Chair	
Member	
Member	
Member	NOTICE OF INTENT
Hardon	NOT FOR CONSTRUCTION
Member	SSUED FOR REVIEW
Member	ISSUED FOR PERMIT
	ISSUED FOR BID/PRICING
DATE APPROVED:	ISSUED FOR CONSTRUCTION



CONSTRUCTION CALL "DIG SAFE" 811.

D-<u>32485</u>

- SQUARE" BY ODONE SURVEYING & MAPPING ON 05/16/2014.
- OF DEEDS. THE VERTICAL DATUM IS NVD88. DATUM WAS ESTABLISHED USING RTK GPS METHODS.
- DATE MAY 17, 2005.
- 7. CONTOUR INTERVAL IS ONE FOOT (1').

		PROPERTY LINE	
c	s	SEWER LINE	
-	S	DRAIN LINE	
W	W	WATER LINE	
	G	GAS LINE	
G —	6		
	E		c
		STOCIVIDE TENO	
UP	UTILITY POLE	CC	CONCRETE CURB
☆ - <i>LP</i>	LIGHT POLE	VGC	VERTICAL GRANITE CURB
<i>□ EM</i>	ELECTRIC METER	BCB	BITUMINOUS CONC. CURB
হ	SEWER MANHOLE	LS	LANDSCAPE AREA
D	DRAIN MANHOLE	HC	HANDICAP
⊞	CATCH BASIN	CONC.	CONCRETE
•	BOLLARD	EOP	EDGE OF PAVEMENT
п <i>GM</i>	GAS METER	IR	IRON ROD
\bowtie	GAS VALVE	RRS	RAILROAD SPIKE
🗆 RD	ROOF DRAIN	▼	DOOR
□ ICV	IRRIGATION CONTROL VALVE	þ	SIGN
		التوجع المراجع	DECIDUOUS TREE
		لان +) لافن م	DECIDOOOS TREE
	20 0	10 20	40
		C SCALE IN FEET	



NOTES

1. UNDERGROUND UTILITIES SHOWN ARE FROM OBSERVED SURFACE INDICATIONS, SUBSURFACE INDICATIONS, AND COMPILED FROM AVAILABLE RECORD PLANS OF UTILITY COMPANIES AND PUBLIC AGENCIES AND ARE APPROXIMATE ONLY. AS OF THE DATE OF THIS SURVEY, NO INFORMATION REGARDING RECORD UTILITIES HAS BEEN PROVIDED BY ELECTRIC AND GAS PROVIDERS. BEFORE

2. FEATURES LOCATED WITHIN THE LIMIT OF SURVEY ARE THE RESULT OF AN ACTUAL SURVEY MADE ON THE GROUND BY RJ O'CONNELL & ASSOC. USING TOTAL STATION METHODS ON 01/08/2020. FEATURES OUTSIDE OF THE LIMIT OF SURVEY WERE COMPILED FROM PLAN ENTITLED "DPF DURGIN

3. THE HORIZONTAL DATUM IS REFERENCED FROM PLAN D-32485 FROM ROCKINGHAM COUNTY REGISTRY

4. THE POSITIONAL ACCURACY OF THE DATA AND PHYSICAL IMPROVEMENTS ON THIS PLAN MAY BE APPROXIMATE. ANY USE OF ELECTRONIC DATA CONTAINED IN AUTOCAD VERSIONS OF THIS PLAN TO GENERATE COORDINATES OR DIMENSIONS NOT SHOWN ON THE PLAN IS NOT AUTHORIZED.

5. THE PARCEL SHOWN IS LOCATED IN ZONE X, AS SHOWN ON "FLOOD INSURANCE RATE MAP, ROCKINGHAM COUNTY, NEW HAMPSHIRE," PANEL 260 OF 681, MAP NUMBER 33015C0260E, EFFECTIVE

6. THE PARCEL IS LOCATED IN THE GATEWAY CORRIDOR ZONE, (G1) AS REFERENCED FROM THE CITY OF PORTSMOUTH PLANNING DEPARTMENT.

LEGEND

	DATE
	REVISION
	N
02/18/2020	DATE
ISSUED FOR TAC REVIEW	REVISION

PREPARED BY: **RJO'CONNELL** & ASSOCIATES, INC. CIVIL ENGINEERS, SURVEYORS & LAND PLANNERS 80 MONTVALE AVENUE, SUITE 201 STONEHAM, MA 02180

PHONE: 781.279.0180 RJOCONNELL.COM PREPARED FOR:

PARTNERS Unlocking Value in Commercial Real Estate

ONE BURLINGTON WOODS DRIVE BURLINGTON, MA 01803 781-418-6203

PROJECT NAME:



DRAWING NAME:

EXISTING CONDITIONS PLAN THIS PLAN IS THE RESULT OF AN ON THE GROUND SURVEY PERFORMED ON 01/08/2020.

Jut Filmi 02/18/2020 DATE PROFESSIONAL LAND SURVEYOR FOR **RJ O'CONNELL & ASSOCIATES, INC** DRAWN BY TDB **REVIEWED BY:** SML 1" = 20'


SCALE:	1" = 20'
FIELD BOOK:	FIELD BOOK: 35 / PG: 60
FIELD CREW:	TDB / RJK
DATE:	02/18/2020

DRAWING NUMBER: **EX-1**


PROJECT NUMBER:


16030

Copyright © 2019 by R.J. O'Connell & Associates, Inc





awing name: G:\NH\Portsmouth\KeyPoint\Durgin Square\Main\16030_OS-1 Overall Site Pla





ame: G:\NH\Portsmouth\KeyPoint\Durgin Square\Main\16030_C-2 Grading and Drai







PROJECT NUMBER:

Copyright © 2020 by R.J. O'Connell & Associates, Inc.

16030






PLANTING:

Ĵ.

- 1. DURING CONSTRUCTION, PROTECT ALL EXISTING SITE FEATURES, STRUCTURES AND UTILITIES.
- 2. PLANTS SHALL BE TRUE TO SPECIES AND VARIETY SPECIFIED AND NURSERY GROWN IN ACCORDANCE WITH THE AMERICAN STANDARD FOR NURSERY STOCK UNDER CLIMATIC CONDITIONS SIMILAR TO THOSE IN THE LOCALITY OF THE PROJECT. SUBSTITUTIONS WILL BE PERMITTED ONLY IF APPROVED BY THE LANDSCAPE ARCHITECT.
- 3. LANDSCAPE ARCHITECT APPROVAL IS REQUIRED BEFORE PLANT MATERIAL IS PURCHASED. LANDSCAPE ARCHITECT RESERVES THE RIGHT TO SEE ALL MATERIAL IN
- PERSON AT THE NURSERY. IF TRAVEL OUTSIDE OF MA IS REQUIRED, LANDSCAPE ARCHITECT'S TRAVEL COSTS SHALL BE PAID FOR BY THE CONTRACTOR. 4. ALL EXPOSED BURLAP, WIRE BASKETS AND OTHER MATERIALS ATTACHED TO PLANTS SHALL BE REMOVED PRIOR TO PLANTING. CARE SHALL BE TAKEN NOT TO DISTURB THE ROOT BALL OF PLANTS.
- 5. THOROUGHLY WATER ALL PLANTS IMMEDIATELY AFTER PLANTING.
- 6. WHERE DISCREPANCIES IN QUANTITIES OCCUR, DRAWINGS SUPERCEDE PLANT NOTES AND SCHEDULE.
- 7. TRANSPLANTING SHALL BE DONE IN ACCORDANCE WITH THE AMERICAN STANDARD FOR NURSERY STOCK.
- 8. LOAM USED IN PLANT BEDS SHALL BE UNIFORM IN COMPOSITION, FREE FROM SUBSOIL, STONES LARGER THAN 1", NOXIOUS SEEDS AND SUITABLE FOR THE SUPPORT OF VEGETATIVE GROWTH. THE pH VALUE SHALL BE BETWEEN 5.5 AND 6.5.
- 9. MULCH IN TREE AND SHRUB BEDS SHALL BE NATURAL, NATIVE HEMLOCK MULCH FREE OF GROWTH OR GERMINATION INHIBITING INGREDIENTS. SUBMIT SAMPLES FOR APPROVAL.
- 10.LOCATIONS FOR PLANTS AND/OR OUTLINE OF AREAS TO BE PLANTED ARE TO BE STAKED OUT AT THE SITE FOR APPROVAL BY THE LANDSCAPE ARCHITECT. 11. SOIL DEPTHS: a.) SHRUBS AND PERENNIAL BEDS: 18" MIN.; b.) GROUNDCOVER: 6" MIN.; c.) TREES: SEE DETAIL; d.) SOD/SEED: 6"MIN. 12. PROVIDE A SUBSURFACE ROOTBALL ANCHOR BY PLATIPUS EARTH ANCHORS, SIZE FOR CALIPER

YMBOL	QTY.	LATIN NAME	COMMON NAME	SIZE	NOTES
SHRUBS /	AND GROUN	IDCOVER	•	-	
RG	53	RHUS AROMATICA 'GRO-LOW'	GRO-LOW FRAGRANT SUMAC	3 GAL	36" O.C.
IG	19	ILEX GLABRA 'SHAMROCK'	SHAMROCK INKBERRY	5 GAL	36" O.C.
CS	18	CORNUS SERICEA 'ARCTIC FIRE'	ARCTIC FIRE DOGWOOD	5 GAL	36" O.C.
PERENNI					
	ALS				
СК	ALS 9	CALAMAGROSTIS A. 'KARL FOERSTER'	KARL FOERSTER SWITCH GRASS	1 GAL	24" O.C. CONTAINER
СК НН	ALS 9 108	CALAMAGROSTIS A. 'KARL FOERSTER' HEMEROCALLIS 'HAPPY RETURNS'	KARL FOERSTER SWITCH GRASS HAPPY RETURN DAYLILLYS	1 GAL 1 GAL	24" O.C. CONTAINER 18" O.C. CONTAINER
CK HH LS	ALS 9 108 75	CALAMAGROSTIS A. 'KARL FOERSTER' HEMEROCALLIS 'HAPPY RETURNS' LIRIOPE SPICATA	KARL FOERSTER SWITCH GRASS HAPPY RETURN DAYLILLYS CREEPING LIRIOPE	1 GAL 1 GAL 1 GAL	24" O.C. CONTAINER 18" O.C. CONTAINER 15" O.C. CONTAINER
СК НН	ALS 9 108	CALAMAGROSTIS A. 'KARL FOERSTER' HEMEROCALLIS 'HAPPY RETURNS' LIRIOPE SPICATA PENNISETUM A. 'HAMELN'	KARL FOERSTER SWITCH GRASS HAPPY RETURN DAYLILLYS	1 GAL 1 GAL	24" O.C. CONTAINER 18" O.C. CONTAINER
CK HH LS PH	ALS 9 108 75 42	CALAMAGROSTIS A. 'KARL FOERSTER' HEMEROCALLIS 'HAPPY RETURNS' LIRIOPE SPICATA	KARL FOERSTER SWITCH GRASS HAPPY RETURN DAYLILLYS CREEPING LIRIOPE HAMELN FOUNTAIN GRASS	1 GAL 1 GAL 1 GAL 2 GAL	24" O.C. CONTAINER 18" O.C. CONTAINER 15" O.C. CONTAINER 24" O.C. CONTAINER

10'-0"		
5' 2.5' 0		
5 2.5 0	10	Z



	PLAN
\frown	
$\mathbf{>}$	DRAWING NUMBER:

PLANTI	N(;	Ы	AN

Copyright © 2019 by R.J. O'Connell & Associates, Inc.



PROJECT NUMBER:

16030

MD

MD

MD

1"=10'-0"

01/23/2020

MDLA

MICHAEL D'ANGELO LANDSCAPE ARCHITECTURE LLC

732 EAST BROADWAY

BOSTON, MA 02127

203-592-4788

Unlocking Value in Commercial Real Estate

ONE BURLINGTON WOODS DRIVE

BURLINGTON, MA 01803

781-418-6203

DPF DURGIN SQUARE

PORTSMOUTH, NH

PARTNERS

PREPARED BY:

PREPARED FOR:

PROJECT NAME:

SEAL:

DESIGNED BY:

REVIEWED BY:


DRAWING NAME:

DRAWN BY:

SCALE:

DATE:


NOTE: NO IRRIGATION AT THIS TIME



ig name: G:NH\Portsmouth\KeyPoint\Durgin Square\Main\16030_FT-1 Fire Truck Turni


.


.



wing name: G:/NH/Portsmouth/KeyPoint/Durgin Square/Main/16030_C-4 Site Details - I.dwg

Drawing name: G:\NH\Por Feb 14, 2020 - 10:33am





NOTES

 THIS INFORMATION IS NOT COMPLETE. FOR A COMPLETE SET OF SITE PLANS, SEE THE CITY OF PORTSMOUTH PLANNING DEPARTMENT.

 PER THE CITY OF PORTSMOUTH REGULATIONS, SP-1 AND SP-2 HAVE BEEN PREPARED TO BE RECORDED AT THE ROCKINGHAM COUNTY REGISTRY OF DEEDS UPON APPROVAL BY THE CITY OF PORTSMOUTH PLANNING BOARD.

- 3. THESE PLANS HAVE BEEN PREPARED FROM THE FOLLOWING:
- A. "ALTA/ACSM LAND TITLE SURVEY DPF DURGIN SQUARE" BY ODONE SURVEY & MAPPING, LAST REVISED 05/16/2014.


B. "EXISTING CONDITIONS PLAN" BY R.J. O'CONNELL & ASSOCIATES, INC; DATED 02/18/2020.

4. THE CONTRACTOR IS SPECIFICALLY CAUTIONED THAT THE LOCATION AND/OR ELEVATION OF EXISTING UTILITIES AND STRUCTURES AS SHOWN ON THESE PLANS IS BASED ON RECORDS OF VARIOUS UTILITY COMPANIES AND WHERE POSSIBLE, MEASUREMENTS TAKEN IN THE FIELD. THIS INFORMATION IS NOT TO BE RELIED ON AS BEING EXACT OR COMPLETE. THE LOCATION OF ALL UNDERGROUND UTILITIES AND STRUCTURES ESPECIALLY WHERE NEW WORK CONNECTS TO EXISTING SHALL BE VERIFIED IN THE FIELD BY THE CONTRACTOR PRIOR TO THE START OF CONSTRUCTION. THE CONTRACTOR MUST CONTACT THE APPROPRIATE UTILITY COMPANY, ANY GOVERNING PERMITTING AUTHORITY, AND "DIG SAFE" (1-800-344-7233) AT LEAST TWO (2) WEEKS PRIOR TO ANY EXCAVATION WORK TO REQUEST EXACT FIELD LOCATION OF UTILITIES AND THE ENGINEER SHALL BE NOTIFIED IN WRITING OF ANY UTILITIES INTERFERING WITH THE PROPOSED CONSTRUCTION AND APPROPRIATE REMEDIAL ACTION TAKEN BEFORE PROCEEDING WITH THE WORK. IT SHALL BE THE RESPONSIBILITY OF THE CONTRACTOR TO RELOCATE ALL EXISTING UTILITIES WHICH CONFLICT WITH THE PROPOSED IMPROVEMENTS SHOWN ON THE PLANS.

- 5. THE CONTRACTOR SHALL BE RESPONSIBLE FOR ESTABLISHING AND MAINTAINING ALL HORIZONTAL CONTROL POINTS AND VERTICAL BENCH MARKS NECESSARY FOR THE WORK.
- 6. THE CONTRACTOR IS RESPONSIBLE FOR OBTAINING AND PAYING FOR ANY PERMITS AND/OR CONNECTION FEES REQUIRED TO CARRY OUT THE WORK INCLUDING BUT NOT LIMITED TO DEMOLITION.
- 7. THE CONTRACTOR SHALL BE RESPONSIBLE FOR VERIFICATION OF ALL INFORMATION SHOWN ON THESE PLANS PRIOR TO CONSTRUCTION. THE CONTRACTOR SHALL NOTIFY THE ENGINEER IN WRITING IMMEDIATELY OF ANY DISCREPANCIES BETWEEN ACTUAL SITE CONDITIONS AND EXISTING SITE CONDITIONS AS SHOWN ON THESE PLANS.
- 8. ALL CONSTRUCTION DUMPSTERS SHALL BE PROPERLY MAINTAINED. ALL DUMPSTERS SHALL BE LOCATED ON A BITUMINOUS CONCRETE OR CONCRETE SURFACE. THE CONTRACTOR SHALL BE RESPONSIBLE FOR TRASH DISPOSAL ON A REGULAR BASIS AND SHALL ENSURE THAT THE DUMPSTER AREAS ARE PROPERLY MAINTAINED.
- 9. THE GENERAL CONTRACTOR AND SUBCONTRACTORS WILL HAVE A COPY OF THE SITE PLAN APPROVAL ON SITE AT ALL TIMES AND WILL BE INCORPORATED INTO ALL CONSTRUCTION CONTRACTS.
- 10. NO AUTHORIZED ACTIVITY SHALL AFFECT ABUTTING PROPERTIES. IF THE APPLICANT MUST WORK ON AN ABUTTING PROPERTY, WRITTEN AUTHORIZATION FROM THE OWNER OF SAID LAND SHALL BE OBTAINED AND PROVIDED TO THE OWNER OR OWNER'S REPRESENTATIVE PRIOR TO THE START OF WORK.
- 11. ALL CONDITIONS ON THESE PLANS SHALL REMAIN IN EFFECT IN PERPETUITY.

12. REFER TO DRAWING SP-2, OVERALL PLAN, FOR COMPLETE PROPERTY LINE INFORMATION.

-				
No.	RE	VISIONS	BY	DATE
	SITE L	AYOUT PLAN		
	1600 W(POR	ODBURY AVENUE TSMOUTH, NH COPERTY MAP 238 MAP 239	LOT 016	
	CIVIL ENGINEE & LAND PLANN	CIATES, INC. 7 rs, surveyors F.	TONEHAM 81-279-0: AX: 781-2	79-0173
	e: 1"=20'		Date: 0	2/18/2020
For Profess For P	AAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA	Plan Chair Member Member Member Member Member DATE APPROVED:	ning Board	
DESIGNED BY:	DRAWN/CHECKE	D PROJECT No.		SHEET No.
CNM/SPG	MCR/CNM	16030		SP-1



T I			RJOC	
				BY DATE
	No.	OVE DPF DL 1600 WG POR	RALL PLAN JRGIN SQUARE DODBURY AVENUE TSMOUTH, NH ROPERTY MAP 238 LOT MAP 239 LOT	Г 016
	Prep	ared by: RJO'C & ASSO CIVIL ENGINEE & LAND PLANN	CIATES, INC. 781-7 RRS, SURVEYORS FAX:	ONTVALE AVENUE IEHAM, MA 02180 279-0180 781-279-0173
		e: 1"=60' sional Seal	D Planning	Pate: 02/18/2020 Board
	BO No. J	NSEP AL ENGINIUM	Chair Member Member Member	
120	Owner of DPF 1600 WOOI C/O MARVIN F PO 3520 PIEDMONT I ATLANTA ,	f Record DBURY AVE LLC OER & COMPANY RD NE SUITE 410 GA 30305	Member Member DATE APPROVED:	
	DESIGNED BY: CNM/SPG	DRAWN/CHECKE		SHEET No. SP-2



Stormwater Summary

Durgin Square 1600 Woodbury Ave Portsmouth, New Hampshire

Prepared for: Keypoint Partners One Burlington Woods Drive Burlington, MA 01803

Prepared by: R.J. O'Connell & Associates, Inc. 80 Montvale Ave, Suite 201 Stoneham, MA 02180

> Date: February 18, 2020



02-18-2020

This Page Intentionally Left Blank

RJO'CONNELL & ASSOCIATES, INC.

CIVIL ENGINEERS, SURVEYORS & LAND PLANNERS

 80 Montvale Ave., Suite 201
 Stoneham, MA 02180

 phone
 781-279-0180
 fax
 781-279-0173

Stormwater Summary

On behalf of the Applicant, Keypoint Partners LLC, R.J. O'Connell & Associates, Inc. has prepared this stormwater summary for the proposed project at Durgin Square shopping plaza located at 1600 Woodbury Ave, Portsmouth, NH (refer to Figure 1, USGS Map). The existing site is comprised of a 126,300 square foot shopping center building, a 5,920 square foot retail/ restaurant building, and two 2,920 retail buildings. The site is located northwest of downtown Portsmouth along Woodbury Ave between Durgin Lane and Arthur F Brady Drive.

The proposed project will demolish the 2,920 square foot retail building currently housing Gamestop and its associated parking area located at 1608 Woodbury Ave, and construct a new 16-foot-wide one-way access driveway from Woodbury Ave to the main parking field for the shopping center.

The proposed driveway will shift the existing curb cut to the south and convert it to a right-in only condition with new accessible ramps and a crosswalk at the intersection with Woodbury Ave. The existing raised center median along the centerline of Woodbury Ave will be extended further south to prevent left turns at the proposed driveway. The proposed site work will result in a net increase of pervious open space of approximately 7,500 square feet. Modifications to the shopping center building include dividing the tenant space of the former Shaws supermarket into approximately 4,147 of new retail space and the remaining 41,980 square feet into a new supermarket tenant.

As indicated on the FEMA Flood Insurance Rate Map, Panel 33015C0260E, effective May 17, 2005, the site is located in Zone X, outside the 100-year flood zone (refer to Figure 2, Flood Insurance Rate Map). The Natural Resources Conservation Service (NRCS) web soil survey indicates the on-site soil type to be Chatfield-Hollis-Canton complex, with a Hydrologic Soil Group (HSG)-B classification (refer to Figure 3, NRCS Web Soil Survey Map).

This stormwater summary will demonstrate that the proposed stormwater improvements will result in a reduction of peak rates and volumes of stormwater runoff discharging the site and will enhance water quality of stormwater runoff.

In the pre-developed condition, stormwater runoff flows to one of two points of analysis (POA). Runoff from the existing building roof and the western parking areas flow west over pavement towards the main parking field on-site (POA-1) where it is intercepted by several existing catch basins. Runoff from the eastern parking area flows over pavement to the north where it is collected by an existing catch basin and piped to the north and off-site to pipes along the shoulder of Woodbury Ave at POA-2. Refer to Figure 4, Existing Watershed Plan.

In the post-developed condition, stormwater runoff will continue to flow to the same points of analysis as under existing conditions. Runoff from the western portion of the proposed driveway will flow over pavement at POA-1 to the existing catch basins in the main parking field similar to existing conditions. Runoff from the eastern portion of the proposed driveway will be intercepted by a new deep-sump catch basin with hooded outlets and routed through an oil/particle separator to remove settleable solids and floating contaminants before discharging through the existing drain line in Woodbury Ave at POA-2. Refer to Figure 5, Proposed Watershed Plan.

This study used the computer program HydroCAD, version 10.00, to model existing and proposed hydrologic site conditions based on the Natural Resources Conservation Service (NRCS) TR-20 Computer Program for Project Formulation Hydrology. Peak pre- and post-development rates and

volumes of stormwater runoff discharged from the site were determined for the 2, 10, 25 and 50-year storm events at the POAs. Refer to Appendix A for computations.

Because the amount of pervious open space area is increased by approximately 7,500 square feet under proposed conditions as compared to existing, peak rates and volumes of stormwater discharged from the site under post-development conditions are reduced compared to pre-development rates at the POAs. The following tables summarize the calculated peak flows and volumes for the pre-redevelopment and post-redevelopment conditions.

		Storm Event						
	2-year		10-year		25-year		50-year	
	Pre	Post	Pre	Post	Pre	Post	Pre	Post
POA-1	0.77	0.44	1.24	0.84	1.57	1.14	1.75	1.31
POA-2	0.39	0.17	0.68	0.40	0.88	0.59	1.00	0.69
Total	1.16	0.61	1.92	1.24	2.45	1.73	2.75	2.00

Pre- and Post-Development Peak Rates of Runoff in Cubic Feet per Second (cfs)


Pre- and Post-Development Volumes of Runoff in Cubic Feet (cf)


	Storm Event							
	2-year		10-year		25-year		50-year	
	Pre	Post	Pre	Post	Pre	Post	Pre	Post
POA-1	2,289	1,317	3,741	2,483	4,775	3,362	5,355	3,867
POA-2	1,153	571	2,006	1,225	2,627	1,746	2,979	2,052
Total	3,442	1,888	5,747	3,708	7,402	5,108	8,334	5,919

As shown in the calculations and in the summary tables above, the increase in pervious landscaped area in the proposed condition will significantly reduce peak rates and volumes of stormwater discharged from the proposed site as compared to the existing conditions. Additionally, the proposed deep-sump catch basin with hooded outlet and oil/particle separator will improve water quality of stormwater runoff. The proposed condition represents notable improvement over the existing condition and is consistent with the stormwater management objectives set forth in the City of Portsmouth Site Plan Review Regulations.

FIGURES


This Page Intentionally Left Blank






FIRM Map.dwg \sim Figure Drawing name: G:\NH\Portsmouth\KeyPoint\Durgin Square\Reports\Stormwater Report\Figures\16030 Feb 14, 2020 - 12:00pm

DURGIN SQUARE PORTSMOUTH, NH Copyright © 2020 by R.J. O'Connell & Associates, Inc.









HYDROLOGIC SOIL GROUP					
MAP UNIT SYMBOL	MAP UNIT NAME	RATING			
140B	CHATFIELD-HOLLIS- CANTON COMPLEX, 0 TO 8 PERCENT SLOPES, ROCKY	В			
699	URBAN LAND				



Copyright © 2020 by R.J. O'Connell & Associates, Inc.






This Page Intentionally Left Blank

APPENDIX A Computations This Page Intentionally Left Blank

Pre-Development Hydrological Computations

This Page Intentionally Left Blank



16030 Existing Stormwater Prepared by R.J. O'Connell & Associates HydroCAD® 10.00-25 s/n 04881 © 2019 HydroC						
Time span=0.00-24.00 hrs, dt=0.10 hrs, 241 points Runoff by SCS TR-20 method, UH=SCS, Weighted-CN Reach routing by Stor-Ind+Trans method - Pond routing by Stor-Ind method						
Subcatchment EX-1: Subcat EX-1	Runoff Area=0.332 ac 75.49% Impervious Runoff Depth>1.90" Tc=0.0 min CN=89 Runoff=0.77 cfs 2,289 cf					
Subcatchment EX-2: Subcat EX-2	Runoff Area=9,127 sf 62.32% Impervious Runoff Depth>1.52" Tc=0.0 min CN=84 Runoff=0.39 cfs 1,153 cf					
Link POA-1: Point of Analysis 1	Inflow=0.77 cfs 2,289 cf					
Link POA-2: Point of Analysis 2	Primary=0.77 cfs 2,289 cf Inflow=0.39 cfs 1,153 cf					
Link FOA-2. Found of Analysis 2	Primary=0.39 cfs 1,153 cf					
Total Runoff Area = 23 584 s	f Runoff Volume = 3.442 cf Average Runoff Depth = 1.75"					

Total Runoff Area = 23,584 sf Runoff Volume = 3,442 cf Average Runoff Depth = 1.75" 29.61% Pervious = 6,982 sf 70.39% Impervious = 16,602 sf

Summary for Subcatchment EX-1: Subcat EX-1

Printed 1/22/2020


Page 3

Runoff 0.77 cfs @ 12.00 hrs, Volume= 2,289 cf, Depth> 1.90" =

Runoff by SCS TR-20 method, UH=SCS, Weighted-CN, Time Span= 0.00-24.00 hrs, dt= 0.10 hrs Type III 24-hr 2-Year Rainfall=3.00"

Area (ac)	CN	Description
0.183	98	Paved parking, HSG B
0.067	98	Roofs, HSG B
0.081	61	>75% Grass cover, Good, HSG B
0.332	89	Weighted Average
0.081		24.51% Pervious Area
0.251		75.49% Impervious Area

Subcatchment EX-1: Subcat EX-1



Printed 1/22/2020


Page 4

Runoff 0.39 cfs @ 12.01 hrs, Volume= 1,153 cf, Depth> 1.52" =

Runoff by SCS TR-20 method, UH=SCS, Weighted-CN, Time Span= 0.00-24.00 hrs, dt= 0.10 hrs Type III 24-hr 2-Year Rainfall=3.00"

Area (sf)	CN	Description
3,439	61	>75% Grass cover, Good, HSG B
5,688	98	Paved parking, HSG B
9,127	84	Weighted Average
3,439		37.68% Pervious Area
5,688		62.32% Impervious Area

Subcatchment EX-2: Subcat EX-2




Summary for Link POA-1: Point of Analysis 1

Printed 1/22/2020

Page 5

Inflow Are	a =	14,457 sf,	75.49% Impervious,	Inflow Depth > 1.90)" for 2-Year event
Inflow	=	0.77 cfs @	12.00 hrs, Volume=	2,289 cf	
Primary	=	0.77 cfs @	12.00 hrs, Volume=	2,289 cf, At	tten= 0%, Lag= 0.0 min


Primary outflow = Inflow, Time Span= 0.00-24.00 hrs, dt= 0.10 hrs



Link POA-1: Point of Analysis 1

Inflow Area =		9,127 sf	, 62.32% Impervious	, Inflow Depth > 1.52	for 2-Year event
Inflow	=	0.39 cfs @	12.01 hrs, Volume=	1,153 cf	
Primary	=	0.39 cfs @	12.01 hrs, Volume=	1,153 cf, Att	en= 0%, Lag= 0.0 min

Primary outflow = Inflow, Time Span= 0.00-24.00 hrs, dt= 0.10 hrs



Link POA-2: Point of Analysis 2

Printed 1/22/2020

Durgin Square - Portsmouth, NH

16030 Existing Stormwater	Durgin Square - Portsmouth, NH Type III 24-hr 10-Year Rainfall=4.30"
Prepared by R.J. O'Connell & Associates	Printed 1/22/2020
HydroCAD® 10.00-25 s/n 04881 © 2019 HydroC	CAD Software Solutions LLC Page 7
Runoff by SCS TR-2	24.00 hrs, dt=0.10 hrs, 241 points 20 method, UH=SCS, Weighted-CN ns method - Pond routing by Stor-Ind method
Subcatchment EX-1: Subcat EX-1	Runoff Area=0.332 ac 75.49% Impervious Runoff Depth>3.11" Tc=0.0 min CN=89 Runoff=1.24 cfs 3,741 cf
Subcatchment EX-2: Subcat EX-2	Runoff Area=9,127 sf 62.32% Impervious Runoff Depth>2.64"
	Tc=0.0 min CN=84 Runoff=0.68 cfs 2,006 cf
Link POA-1: Point of Analysis 1	Inflow=1.24 cfs 3,741 cf
	Primary=1.24 cfs 3,741 cf
Link POA-2: Point of Analysis 2	Inflow=0.68 cfs 2,006 cf
	Primary=0.68 cfs 2,006 cf
Total Runoff Δroa = 23 584 st	f Runoff Volume = 5.747 cf Average Runoff Denth = 2.92"

Total Runoff Area = 23,584 sf Runoff Volume = 5,747 cf Average Runoff Depth = 2.92" 29.61% Pervious = 6,982 sf 70.39% Impervious = 16,602 sf

Summary for Subcatchment EX-1: Subcat EX-1


Page 8

Runoff 1.24 cfs @ 12.00 hrs, Volume= 3,741 cf, Depth> 3.11" =

Runoff by SCS TR-20 method, UH=SCS, Weighted-CN, Time Span= 0.00-24.00 hrs, dt= 0.10 hrs Type III 24-hr 10-Year Rainfall=4.30"

A	ea (ac)	CN	Description
	0.183	98	Paved parking, HSG B
	0.067	98	Roofs, HSG B
	0.081	61	>75% Grass cover, Good, HSG B
	0.332	89	Weighted Average
	0.081		24.51% Pervious Area
	0.251		75.49% Impervious Area

Subcatchment EX-1: Subcat EX-1




Summary for Subcatchment EX-2: Subcat EX-2

Runoff 0.68 cfs @ 12.00 hrs, Volume= 2,006 cf, Depth> 2.64" =

Runoff by SCS TR-20 method, UH=SCS, Weighted-CN, Time Span= 0.00-24.00 hrs, dt= 0.10 hrs Type III 24-hr 10-Year Rainfall=4.30"


Area (sf)	CN	Description
3,439	61	>75% Grass cover, Good, HSG B
5,688	98	Paved parking, HSG B
9,127	84	Weighted Average
3,439		37.68% Pervious Area
5,688		62.32% Impervious Area

Subcatchment EX-2: Subcat EX-2



Inflow Are	a =	14,457 sf, 75.49% Impervious, Inflow Depth > 3.11" for 10-Year event	
Inflow	=	1.24 cfs @ 12.00 hrs, Volume= 3,741 cf	
Primary	=	1.24 cfs @ 12.00 hrs, Volume= 3,741 cf, Atten= 0%, Lag= 0.0 mir	٦


Primary outflow = Inflow, Time Span= 0.00-24.00 hrs, dt= 0.10 hrs



Link POA-1: Point of Analysis 1

Inflow Are	a =	9,127 sf, 62.32% Impervious, Inflow Depth > 2.64" for 10-Yea	ar event
Inflow	=	0.68 cfs @ 12.00 hrs, Volume= 2,006 cf	
Primary	=	0.68 cfs @ 12.00 hrs, Volume= 2,006 cf, Atten= 0%, Lag	= 0.0 min

Primary outflow = Inflow, Time Span= 0.00-24.00 hrs, dt= 0.10 hrs



Link POA-2: Point of Analysis 2

16030 Existing Stormwater	Durgin Square - Portsmouth, NH Type III 24-hr 25-Year Rainfall=5.20"
Prepared by R.J. O'Connell & Associates	Printed 1/22/2020
HydroCAD® 10.00-25 s/n 04881 © 2019 HydroC	
Time span=0.00-2	24.00 hrs, dt=0.10 hrs, 241 points
	20 method, UH=SCS, Weighted-CN
	ns method - Pond routing by Stor-Ind method
0.7	
Subcatchment EX-1: Subcat EX-1	Runoff Area=0.332 ac 75.49% Impervious Runoff Depth>3.96"
	Tc=0.0 min CN=89 Runoff=1.57 cfs 4,775 cf
Subcatchment EX-2: Subcat EX-2	Runoff Area=9,127 sf 62.32% Impervious Runoff Depth>3.45"
	Tc=0.0 min CN=84 Runoff=0.88 cfs 2,627 cf
Link DOA 4. Doint of Analysis 4	Inflow-1.57 of A.775 of
Link POA-1: Point of Analysis 1	Inflow=1.57 cfs 4,775 cf
	Primary=1.57 cfs 4,775 cf
Link POA-2: Point of Analysis 2	Inflow=0.88 cfs 2,627 cf
	Primary=0.88 cfs 2,627 cf
	· ·······
Total Punoff Aroa - 23 584 st	f Bunoff Volume = 7.402 cf Average Bunoff Donth = 3.77"

Total Runoff Area = 23,584 sf Runoff Volume = 7,402 cf Average Runoff Depth = 3.77" 29.61% Pervious = 6,982 sf 70.39% Impervious = 16,602 sf


Summary for Subcatchment EX-1: Subcat EX-1

Runoff = 1.57 cfs @ 12.00 hrs, Volume= 4,775 cf, Depth> 3.96"

Runoff by SCS TR-20 method, UH=SCS, Weighted-CN, Time Span= 0.00-24.00 hrs, dt= 0.10 hrs Type III 24-hr 25-Year Rainfall=5.20"

 Area (ac)	CN	Description
0.183	98	Paved parking, HSG B
0.067	98	Roofs, HSG B
 0.081	61	>75% Grass cover, Good, HSG B
0.332	89	Weighted Average
0.081		24.51% Pervious Area
0.251		75.49% Impervious Area

Subcatchment EX-1: Subcat EX-1




Summary for Subcatchment EX-2: Subcat EX-2

Runoff = 0.88 cfs @ 12.00 hrs, Volume= 2,627 cf, Depth> 3.45"

Runoff by SCS TR-20 method, UH=SCS, Weighted-CN, Time Span= 0.00-24.00 hrs, dt= 0.10 hrs Type III 24-hr 25-Year Rainfall=5.20"


Area (st	f) CN	Description
3,43	9 61	>75% Grass cover, Good, HSG B
5,68	8 98	Paved parking, HSG B
9,12	7 84	Weighted Average
3,43	9	37.68% Pervious Area
5,68	8	62.32% Impervious Area

Subcatchment EX-2: Subcat EX-2



Inflow Are	a =	14,457 sf	, 75.49% Impervious,	Inflow Depth >	3.96"	for 25-Year event
Inflow	=	1.57 cfs @	12.00 hrs, Volume=	4,775 c	of	
Primary	=	1.57 cfs @	12.00 hrs, Volume=	4,775 c	of, Atter	n= 0%, Lag= 0.0 min

Primary outflow = Inflow, Time Span= 0.00-24.00 hrs, dt= 0.10 hrs




Link POA-1: Point of Analysis 1

Page 16

Inflow Are	a =	9,127 sf,	, 62.32% Impervious	Inflow Depth >	3.45"	for 25-Year event
Inflow	=	0.88 cfs @	12.00 hrs, Volume=	2,627 0	of	
Primary	=	0.88 cfs @	12.00 hrs, Volume=	2,627 c	of, Atter	n= 0%, Lag= 0.0 min

Primary outflow = Inflow, Time Span= 0.00-24.00 hrs, dt= 0.10 hrs



Link POA-2: Point of Analysis 2

16030 Existing Stormwater Prepared by R.J. O'Connell & Associates	Durgin Square - Portsmouth, NH Type III 24-hr 50-Year Rainfall=5.70" Printed 1/22/2020
HydroCAD® 10.00-25 s/n 04881 © 2019 HydroC	
Runoff by SCS TR-2	24.00 hrs, dt=0.10 hrs, 241 points 20 method, UH=SCS, Weighted-CN ns method - Pond routing by Stor-Ind method
Subcatchment EX-1: Subcat EX-1	Runoff Area=0.332 ac 75.49% Impervious Runoff Depth>4.45" Tc=0.0 min CN=89 Runoff=1.75 cfs 5,355 cf
Subcatchment EX-2: Subcat EX-2	Runoff Area=9,127 sf 62.32% Impervious Runoff Depth>3.92" Tc=0.0 min CN=84 Runoff=1.00 cfs 2,979 cf
Link POA-1: Point of Analysis 1	Inflow=1.75 cfs 5,355 cf
	Primary=1.75 cfs 5,355 cf
Link POA-2: Point of Analysis 2	Inflow=1.00 cfs 2,979 cf Primary=1.00 cfs 2,979 cf
Total Runoff Area = 23 584 s	f Runoff Volume = 8 334 cf Average Runoff Depth = 4 24"

Total Runoff Area = 23,584 sf Runoff Volume = 8,334 cf Average Runoff Depth = 4.24" 29.61% Pervious = 6,982 sf 70.39% Impervious = 16,602 sf


Summary for Subcatchment EX-1: Subcat EX-1

Runoff = 1.75 cfs @ 12.00 hrs, Volume= 5,355 cf, Depth> 4.45"

Runoff by SCS TR-20 method, UH=SCS, Weighted-CN, Time Span= 0.00-24.00 hrs, dt= 0.10 hrs Type III 24-hr 50-Year Rainfall=5.70"

Area (ac)	CN	Description
0.183	98	Paved parking, HSG B
0.067	98	Roofs, HSG B
0.081	61	>75% Grass cover, Good, HSG B
0.332	89	Weighted Average
0.081		24.51% Pervious Area
0.251		75.49% Impervious Area

Subcatchment EX-1: Subcat EX-1




Summary for Subcatchment EX-2: Subcat EX-2

Runoff = 1.00 cfs @ 12.00 hrs, Volume= 2,979 cf, Depth> 3.92"

Runoff by SCS TR-20 method, UH=SCS, Weighted-CN, Time Span= 0.00-24.00 hrs, dt= 0.10 hrs Type III 24-hr 50-Year Rainfall=5.70"


Area (sf)	CN	Description
3,439	61	>75% Grass cover, Good, HSG B
5,688	98	Paved parking, HSG B
9,127	84	Weighted Average
3,439		37.68% Pervious Area
5,688		62.32% Impervious Area

Subcatchment EX-2: Subcat EX-2



Inflow Are	a =	14,457 sf, 75.49% Impervious, Inflow Depth > 4.45" for 50-	Year event
Inflow	=	1.75 cfs @ 12.00 hrs, Volume= 5,355 cf	
Primary	=	1.75 cfs @ 12.00 hrs, Volume= 5,355 cf, Atten= 0%, L	.ag= 0.0 min


Primary outflow = Inflow, Time Span= 0.00-24.00 hrs, dt= 0.10 hrs



Link POA-1: Point of Analysis 1

Inflow Are	a =	9,127 sf, 62.32% Impervious, Inflow Depth > 3.92" for 50-Year event	
Inflow	=	1.00 cfs @ 12.00 hrs, Volume= 2,979 cf	
Primary	=	1.00 cfs @ 12.00 hrs, Volume= 2,979 cf, Atten= 0%, Lag= 0.0 min	

Primary outflow = Inflow, Time Span= 0.00-24.00 hrs, dt= 0.10 hrs




Link POA-2: Point of Analysis 2

This Page Intentionally Left Blank

Post-Development Hydrological Computations

This Page Intentionally Left Blank



	Durgin Square - Portsmouth, NH
16030 Proposed Stormwater	Type III 24-hr 2-Year Rainfall=3.00"
Prepared by R.J. O'Connell & Associates	Printed 2/14/2020
HydroCAD® 10.00-25 s/n 04881 © 2019 Hydro	CAD Software Solutions LLC Page 2
Runoff by SCS TR	24.00 hrs, dt=0.10 hrs, 241 points 20 method, UH=SCS, Weighted-CN ans method - Pond routing by Stor-Ind method
SubcatchmentPR-1: Subcat PR-1	Runoff Area=13,997 sf 46.18% Impervious Runoff Depth>1.13" Tc=0.0 min CN=78 Runoff=0.44 cfs 1,317 cf
SubcatchmentPR-2: Subcat PR-2	Runoff Area=9,587 sf 25.56% Impervious Runoff Depth>0.71" Tc=0.0 min CN=70 Runoff=0.17 cfs 571 cf
Link POA-1: Point of Analysis 1	Inflow=0.44 cfs 1,317 cf Primary=0.44 cfs 1,317 cf
Link POA-2: Point of Analysis 2	Inflow=0.17 cfs 571 cf Primary=0.17 cfs 571 cf
Total Dunoff Area - 22 594	of Bunoff Volume = 1 997 of Average Bunoff Donth = 0.06

Total Runoff Area = 23,584 sfRunoff Volume = 1,887 cfAverage Runoff Depth = 0.96"62.20% Pervious = 14,669 sf37.80% Impervious = 8,915 sf

Printed 2/14/2020


Page 3

Runoff 0.44 cfs @ 12.01 hrs, Volume= 1,317 cf, Depth> 1.13" =

Runoff by SCS TR-20 method, UH=SCS, Weighted-CN, Time Span= 0.00-24.00 hrs, dt= 0.10 hrs Type III 24-hr 2-Year Rainfall=3.00"

Area (sf)	CN	Description
6,464	98	Paved parking, HSG B
7,533	61	>75% Grass cover, Good, HSG B
13,997	78	Weighted Average
7,533		53.82% Pervious Area
6,464		46.18% Impervious Area

Subcatchment PR-1: Subcat PR-1



Printed 2/14/2020


Page 4

Runoff 0.17 cfs @ 12.02 hrs, Volume= 571 cf, Depth> 0.71" =

Runoff by SCS TR-20 method, UH=SCS, Weighted-CN, Time Span= 0.00-24.00 hrs, dt= 0.10 hrs Type III 24-hr 2-Year Rainfall=3.00"

Area (sf)	CN	Description
7,136	61	>75% Grass cover, Good, HSG B
2,451	98	Paved parking, HSG B
9,587	70	Weighted Average
7,136		74.44% Pervious Area
2,451		25.56% Impervious Area

Subcatchment PR-2: Subcat PR-2




Durgin Square - Portsmouth, NH

Printed 2/14/2020

Page 5

Inflow Are	a =	13,997 sf,	46.18% Impervious,	Inflow Depth > 1.13"	for 2-Year event
Inflow	=	0.44 cfs @	12.01 hrs, Volume=	1,317 cf	
Primary	=	0.44 cfs @	12.01 hrs, Volume=	1,317 cf, Atte	en= 0%, Lag= 0.0 min


Primary outflow = Inflow, Time Span= 0.00-24.00 hrs, dt= 0.10 hrs



Link POA-1: Point of Analysis 1

Inflow Are	a =	9,587 sf, 25.56%	6 Impervious,	Inflow Depth >	0.71"	for 2-Year event
Inflow	=	0.17 cfs @ 12.02 h	rs, Volume=	571 c	of	
Primary	=	0.17 cfs @ 12.02 h	rs, Volume=	571 c	of, Atter	n= 0%, Lag= 0.0 min

Primary outflow = Inflow, Time Span= 0.00-24.00 hrs, dt= 0.10 hrs



Link POA-2: Point of Analysis 2

Printed 2/14/2020

	Durgin Square - Portsmouth, NH
16030 Proposed Stormwater	Type III 24-hr 10-Year Rainfall=4.30"
Prepared by R.J. O'Connell & Associates	Printed 2/14/2020
HydroCAD® 10.00-25 s/n 04881 © 2019 Hydro	CAD Software Solutions LLC Page 7
Runoff by SCS TR	24.00 hrs, dt=0.10 hrs, 241 points 20 method, UH=SCS, Weighted-CN
Reach routing by Stor-Ind+Tra	ans method - Pond routing by Stor-Ind method
SubcatchmentPR-1: Subcat PR-1	Runoff Area=13,997 sf 46.18% Impervious Runoff Depth>2.13" Tc=0.0 min CN=78 Runoff=0.84 cfs 2,483 cf
SubcatchmentPR-2: Subcat PR-2	Runoff Area=9,587 sf 25.56% Impervious Runoff Depth>1.53"
	Tc=0.0 min CN=70 Runoff=0.40 cfs 1,225 cf
Link POA-1: Point of Analysis 1	Inflow=0.84 cfs 2,483 cf
	Primary=0.84 cfs 2,483 cf
Link POA-2: Point of Analysis 2	Inflow=0.40 cfs 1,225 cf
	Primary=0.40 cfs 1,225 cf
Total Dupoff Area - 22 594 c	f Bunoff Volume = 2 708 of Average Bunoff Donth = 1 88

Total Runoff Area = 23,584 sfRunoff Volume = 3,708 cfAverage Runoff Depth = 1.89"62.20% Pervious = 14,669 sf37.80% Impervious = 8,915 sf


Summary for Subcatchment PR-1: Subcat PR-1

Runoff = 0.84 cfs @ 12.01 hrs, Volume= 2,483 cf, Depth> 2.13"

Runoff by SCS TR-20 method, UH=SCS, Weighted-CN, Time Span= 0.00-24.00 hrs, dt= 0.10 hrs Type III 24-hr 10-Year Rainfall=4.30"

Area (sf)	CN	Description
6,464	98	Paved parking, HSG B
7,533	61	>75% Grass cover, Good, HSG B
13,997	78	Weighted Average
7,533		53.82% Pervious Area
6,464		46.18% Impervious Area

Subcatchment PR-1: Subcat PR-1




Summary for Subcatchment PR-2: Subcat PR-2

Runoff = 0.40 cfs @ 12.01 hrs, Volume= 1,225 cf, Depth> 1.53"

Runoff by SCS TR-20 method, UH=SCS, Weighted-CN, Time Span= 0.00-24.00 hrs, dt= 0.10 hrs Type III 24-hr 10-Year Rainfall=4.30"


Area (sf)	CN	Description
7,136	61	>75% Grass cover, Good, HSG B
2,451	98	Paved parking, HSG B
9,587	70	Weighted Average
7,136		74.44% Pervious Area
2,451		25.56% Impervious Area

Subcatchment PR-2: Subcat PR-2



Inflow Are	a =	13,997 sf, 46.18% Impervious, Inflow Depth > 2.13" for 10-Year event
Inflow	=	0.84 cfs @ 12.01 hrs, Volume= 2,483 cf
Primary	=	0.84 cfs @ 12.01 hrs, Volume= 2,483 cf, Atten= 0%, Lag= 0.0 min

Primary outflow = Inflow, Time Span= 0.00-24.00 hrs, dt= 0.10 hrs




Link POA-1: Point of Analysis 1

Page 11

Inflow Are	a =	9,587 sf, 25.56% Impervious, Inflow Depth > 1.53" for 10-Year ever	nt
Inflow	=	0.40 cfs @ 12.01 hrs, Volume= 1,225 cf	
Primary	=	0.40 cfs @ 12.01 hrs, Volume= 1,225 cf, Atten= 0%, Lag= 0.0 n	nin

Primary outflow = Inflow, Time Span= 0.00-24.00 hrs, dt= 0.10 hrs



Link POA-2: Point of Analysis 2

	Durgin Square - Portsmouth, NH
16030 Proposed Stormwater	Type III 24-hr 25-Year Rainfall=5.20"
Prepared by R.J. O'Connell & Associates	Printed 2/14/2020
HydroCAD® 10.00-25 s/n 04881 © 2019 Hydro	CAD Software Solutions LLC Page 12
Runoff by SCS TR	24.00 hrs, dt=0.10 hrs, 241 points 20 method, UH=SCS, Weighted-CN ans method - Pond routing by Stor-Ind method
SubcatchmentPR-1: Subcat PR-1	Runoff Area=13,997 sf 46.18% Impervious Runoff Depth>2.88" Tc=0.0 min CN=78 Runoff=1.14 cfs 3,362 cf
SubcatchmentPR-2: Subcat PR-2	Runoff Area=9,587 sf 25.56% Impervious Runoff Depth>2.19"
Subcatchinentr N-2. Subcat F N-2	Tc=0.0 min CN=70 Runoff=0.59 cfs 1,746 cf
Link POA-1: Point of Analysis 1	Inflow=1.14 cfs 3,362 cf
	Primary=1.14 cfs 3,362 cf
	, -,
Link POA-2: Point of Analysis 2	Inflow=0.59 cfs 1,746 cf
	Primary=0.59 cfs 1,746 cf
Total Bunoff Area = 22 594 /	F Bunoff Volume = 5 109 of Average Bunoff Donth = 2 60"

Total Runoff Area = 23,584 sfRunoff Volume = 5,108 cfAverage Runoff Depth = 2.60"62.20% Pervious = 14,669 sf37.80% Impervious = 8,915 sf


Summary for Subcatchment PR-1: Subcat PR-1

Runoff = 1.14 cfs @ 12.01 hrs, Volume= 3,362 cf, Depth> 2.88"

Runoff by SCS TR-20 method, UH=SCS, Weighted-CN, Time Span= 0.00-24.00 hrs, dt= 0.10 hrs Type III 24-hr 25-Year Rainfall=5.20"

Area (sf)	CN	Description
6,464	98	Paved parking, HSG B
7,533	61	>75% Grass cover, Good, HSG B
13,997	78	Weighted Average
7,533		53.82% Pervious Area
6,464		46.18% Impervious Area

Subcatchment PR-1: Subcat PR-1




Summary for Subcatchment PR-2: Subcat PR-2

Runoff = 0.59 cfs @ 12.01 hrs, Volume= 1,746 cf, Depth> 2.19"

Runoff by SCS TR-20 method, UH=SCS, Weighted-CN, Time Span= 0.00-24.00 hrs, dt= 0.10 hrs Type III 24-hr 25-Year Rainfall=5.20"


Area (sf)	CN	Description
7,136	61	>75% Grass cover, Good, HSG B
2,451	98	Paved parking, HSG B
9,587	70	Weighted Average
7,136		74.44% Pervious Area
2,451		25.56% Impervious Area

Subcatchment PR-2: Subcat PR-2



Inflow Are	a =	13,997 sf	, 46.18% Impervious,	Inflow Depth >	2.88"	for 25-Year event
Inflow	=	1.14 cfs @	12.01 hrs, Volume=	3,362 c	f	
Primary	=	1.14 cfs @	12.01 hrs, Volume=	3,362 c	of, Atter	n= 0%, Lag= 0.0 min


Primary outflow = Inflow, Time Span= 0.00-24.00 hrs, dt= 0.10 hrs



Link POA-1: Point of Analysis 1

Inflow Are	a =	9,587 sf,	25.56% Impervious,	Inflow Depth >	2.19"	for 25-Year event
Inflow	=	0.59 cfs @	12.01 hrs, Volume=	1,746 c	f	
Primary	=	0.59 cfs @	12.01 hrs, Volume=	1,746 c	f, Atter	n= 0%, Lag= 0.0 min

Primary outflow = Inflow, Time Span= 0.00-24.00 hrs, dt= 0.10 hrs



Link POA-2: Point of Analysis 2

	Durgin Square - Portsmouth, NH
16030 Proposed Stormwater	Type III 24-hr 50-Year Rainfall=5.70"
Prepared by R.J. O'Connell & Associates	Printed 2/14/2020
HydroCAD® 10.00-25 s/n 04881 © 2019 Hydro	CAD Software Solutions LLC Page 17
Runoff by SCS TR	24.00 hrs, dt=0.10 hrs, 241 points 20 method, UH=SCS, Weighted-CN ans method - Pond routing by Stor-Ind method
SubcatchmentPR-1: Subcat PR-1	Runoff Area=13,997 sf 46.18% Impervious Runoff Depth>3.32" Tc=0.0 min CN=78 Runoff=1.31 cfs 3,867 cf
Subcatchment PR-2: Subcat PR-2	Runoff Area=9,587 sf 25.56% Impervious Runoff Depth>2.57"
Subcatchinenter N-2. Subcater N-2	Tc=0.0 min CN=70 Runoff=0.69 cfs 2,052 cf
Link DOA de Daint of Analysis d	
Link POA-1: Point of Analysis 1	Inflow=1.31 cfs 3,867 cf
	Primary=1.31 cfs 3,867 cf
Link POA-2: Point of Analysis 2	Inflow=0.69 cfs 2,052 cf
	Primary=0.69 cfs 2,052 cf
Total Dunoff Area = 22 594	f Bunoff Volume = 5.020 of Average Bunoff Douth = 2.04

Total Runoff Area = 23,584 sfRunoff Volume = 5,920 cfAverage Runoff Depth = 3.01"62.20% Pervious = 14,669 sf37.80% Impervious = 8,915 sf


Summary for Subcatchment PR-1: Subcat PR-1

Runoff = 1.31 cfs @ 12.00 hrs, Volume= 3,867 cf, Depth> 3.32"

Runoff by SCS TR-20 method, UH=SCS, Weighted-CN, Time Span= 0.00-24.00 hrs, dt= 0.10 hrs Type III 24-hr 50-Year Rainfall=5.70"

Area (sf)	CN	Description
6,464	98	Paved parking, HSG B
7,533	61	>75% Grass cover, Good, HSG B
13,997	78	Weighted Average
7,533		53.82% Pervious Area
6,464		46.18% Impervious Area

Subcatchment PR-1: Subcat PR-1




Summary for Subcatchment PR-2: Subcat PR-2

Runoff = 0.69 cfs @ 12.01 hrs, Volume= 2,052 cf, Depth> 2.57"

Runoff by SCS TR-20 method, UH=SCS, Weighted-CN, Time Span= 0.00-24.00 hrs, dt= 0.10 hrs Type III 24-hr 50-Year Rainfall=5.70"

Area (sf)	CN	Description
7,136	61	>75% Grass cover, Good, HSG B
2,451	98	Paved parking, HSG B
9,587	70	Weighted Average
7,136		74.44% Pervious Area
2,451		25.56% Impervious Area


Subcatchment PR-2: Subcat PR-2



Summary for Link POA-1: Point of Analysis 1

Inflow Are	a =	13,997 sf, 46.18% Impervious, Inflow Depth > 3.32" for 50-Year even	nt
Inflow	=	1.31 cfs @ 12.00 hrs, Volume= 3,867 cf	
Primary	=	1.31 cfs @ 12.00 hrs, Volume= 3,867 cf, Atten= 0%, Lag= 0.0 m	nin

Primary outflow = Inflow, Time Span= 0.00-24.00 hrs, dt= 0.10 hrs




Link POA-1: Point of Analysis 1

Summary for Link POA-2: Point of Analysis 2

Inflow Are	a =	9,587 sf, 25.56% Impervious, Inflow Depth > 2.5	7" for 50-Year event
Inflow	=	0.69 cfs @ 12.01 hrs, Volume= 2,052 cf	
Primary	=	0.69 cfs @ 12.01 hrs, Volume= 2,052 cf, A	tten= 0%, Lag= 0.0 min

Primary outflow = Inflow, Time Span= 0.00-24.00 hrs, dt= 0.10 hrs



Link POA-2: Point of Analysis 2

APPENDIX B Inspection and Maintenance Manual (I&M)



Inspection and Maintenance Manual

Durgin Square 1600 Woodbury Ave Portsmouth, NH

Prepared for: Keypoint Partners One Burlington Woods Drive Burlington, MA 01803

Prepared by: R.J. O'Connell & Associates, Inc. 80 Montvale Ave, Suite 201 Stoneham, MA 02180

> Date: February 18, 2020

TABLE OF CONTENTS

Introduction

Section 1 - Stormwater Management System - Inspection and Maintenance

Section 2 - Source Control Plan

A. Materials Covered

- **B.** Materials Management Practices
- C. Spill Prevention and Response Procedures

Section 3 - Snow Management and Disposal Plan

Figures

Drawing C-2 – Grading and Drainage Plan Figure BMP-1 – BMP Location Plan Figure SMP-1 – Snow Management Plan

Appendices

Appendix A - Maintenance and Inspection Forms

Activity Guide Comprehensive Annual Evaluation and Inspection Report Annual Training Signoff Sheet

Weekly Inspection Checklist

Monthly Inspection Checklist

Quarterly Inspection Checklist

Semi-Annually Inspection Checklist

Spill and Leak History

Appendix B – CDS Treatment Unit Operations and Maintenance Guidelines

Inspection and Maintenance Manual

INTRODUCTION

This Inspection and Maintenance Manual has been prepared to ensure that the proposed stormwater management system for the proposed driveway at Durgin Square functions properly and to develop and carry out suitable practices for source control and pollution prevention. It consists of four sections:

Section 1 - Stormwater Management System - Inspection and Maintenance, which describes the various components of the stormwater management system, identifies the inspection and maintenance tasks to be undertaken and a schedule for implementing these tasks to insure the proper, long-term operation of the system.

Section 2 – Source Control Plan which identifies and implements suitable measures, practices and procedures for source control and pollution prevention.

Section 3 - Snow Management and Disposal Plan which describes how snow removal will be managed and de-icing operations performed.

SECTION 1 – STORMWATER MANAGEMENT SYSTEM - INSPECTION AND MAINTENANCE

The aim of this stormwater Inspection and Maintenance Manual is to ensure the ongoing proper operation and maintenance of the stormwater system and individual Best Management Practices (BMPs) to effectively remove pollutants as designed and meet the New Hampshire water quality objectives. To accomplish this objective, the following BMPs are included in the stormwater management system for Durgin Square:

- Sweeping of paved surface areas to remove solids and reduce suspended solids in surface runoff.
- Installation of a catch basin with deep sump and hood to reduce the discharge of sediment and pollutants.
- Installation of a oil/particle separator for removal of Total Suspended Solids (TSS), oil and grease.

In consideration of the foregoing, it is the ongoing responsibility of the Landowner, his successors and assignees to adequately maintain the on-site stormwater management/BMP facilities. Adequate maintenance is herein defined as good working condition so that these facilities are performing their design functions.

Based on this, the Landowner, his successors and assignees are required to create a Pollution Prevention Team (PPT) that will be responsible for implementing the Inspection and Maintenance Manual. Upon transfer of ownership of the property, the Landowner is required to notify the new owner of the presence of the stormwater management system and the requirements of this Inspection and Maintenance Manual.

Property Information

Address:	1600 Woodbury Ave		
	Portsmouth, NH 03801		

Landowner and Pollution Prevention Team Leader

Owner's Name: DSQ Holding, LLC Team Leader: Rachel E. Cormier Title: Senior Property Manager Office Phone: 781-273-5555 Email: rcormier@keypointpartners.com

<u>Responsibilities</u>: Coordinate all aspects of the Inspection and Maintenance Manual, coordinate and hire the other Pollution Prevention team members in order to conduct inspections, keep all records, coordinate with contractors for maintenance and repairs of the stormwater management system.

Spill Prevention & Control Contractor

The following contacts shall be notified:

Emergency Contact: Company Name: TBD Contact Name: TBD Emergency Phone: TBD

Consultant Contact: Company Name: TBD. Contact Name: TBD Phone: TBD

New Hampshire Department of Environmental Services (DES) Contact Spill Emergency Coordinator Contact Name: TBD Phone: TBD

Municipal Contacts

Department of Public Works (DPW) Contact Name: Peter Rice, Director of Public Works Phone: 603-427-1530

Engineering Contact Name: Terry Desmarais, P.E., City Engineer Phone: 603-766-1421

Planning Department Contact Name: Juliet Walker, Planning Director Phone: 603-610-7296

Other Pollution Prevention Team Members

Member: Qualified Engineering and/or Environmental Consulting Firm(s) <u>Responsibilities</u>: Conduct scheduled inspections, maintain records, advise the Team Leader of maintenance needs, ensure inspection maintenance and repairs are completed, keep and maintain all records and inspection reports. Company Name(s): TBD Address: TBD Office Phone: TBD

Team Member Training

The Pollution Prevention Team Leader will coordinate an annual in-house training session with the qualified Engineering and/or Environmental Consulting Firm to discuss the Inspection and

Maintenance Manual, ongoing inspection and maintenance and preventative maintenance procedures.

Annual training session will generally include the following:

- Discuss the Inspection and Maintenance Manual
 - What it is- identify potential sources of stormwater pollution and methods of reducing or eliminating that pollution
 - What it contains- emphasize good housekeeping measures and location of potential pollution sources.
 - Pollution Prevention Team-introduce the team and describe their responsibilities, explain that the objective is to continually monitor the stormwater management system and encourage input and assistance from all.
- Review and explain the storm drainage system, how it works and its components, note the receiving resource area in which the storm drainage system discharges into and the role each one of these components play.
- Emphasize the importance of maintaining current and up-to-date inspection reports and maintenance records of BMPs. Documentation shall include any changes to the O&M Plan's procedures to accommodate changes and revisions to BMPs.

The components of the stormwater management system must be inspected, monitored and maintained in accordance with the following in order to ensure that the on-site stormwater management/BMPs are functioning as designed. Routine inspection and proper maintenance of these individual components is essential to providing the long-term operation of the drainage system.

Catch Basin with Deep Sump and Hooded Outlet:

Stormwater runoff from pavement areas is directed to catch basins via curbing and site grading. The catch basin is equipped with a deep (4 foot) sump and hood. The sump is designed to capture sediment and coarse particles and the hoods prevent hydrocarbons and other floatable debris from entering the drainage system. To ensure proper functioning of the catch basins, they will be inspected and maintained as follows:

<u>Inspection</u>: At least twice a year and after major storm events (2.5 inches or more in a 24-hour period). Structural damage and other malfunctions are to be noted and reported. Grates and hoods are to be inspected to ensure they are not clogged and functioning properly.

<u>Maintenance</u>: Jet cleaned and power washed semi-annually or when the sump is half full by a licensed contractor. Sediment and hydrocarbons will be properly handled and legally disposed of off-site in accordance with local, state, and federal guidelines and regulations. Any structural damage to catch basins, castings and/or hoods will be repaired or replaced upon discovery.

Oil/Particle Separators:

Oil/Particle separators are precast concrete structures designed to treat incoming stormwater runoff, removing suspended solids, thereby preventing the transfer of pollutants downstream. Particle separators will be inspected and maintained as follows:

<u>Inspection:</u> Quarterly and after major storm events (2.5 inches or more in a 24 hour period). The level of accumulated pollutants and indications of vector infestation are to be noted and reported.

<u>Maintenance</u>: Jet vacuumed, and power washed by a licensed contractor semi-annually or as determined by the inspections. Accumulated sediment and hydrocarbons will be disposed of in accordance with applicable local, state, and federal guidelines and regulations. Particle separators will also be cleaned when observed sediment depth is at 80% of the sump capacity. All maintenance will be performed in accordance with manufacturer recommendations.

Sweeping and Site Clean-Up:

Routine sweeping of paved areas is an effective method to provide important nonpoint source pollution control and will be performed by mechanical sweepers. Most stormwater pollutants travel with the suspended solids contained in the stormwater runoff and regular sweeping will help reduce a portion of this load. Sweeping, especially during the period immediately following winter snowmelt (March/April) when road sand and other debris has accumulated on the pavement, will capture a peak sediment load before spring rains wash residual sand from winter applications into nearby resource areas.

<u>Inspection</u>: Paved areas will be inspected for litter on a <u>weekly basis</u> and picked up and disposed of immediately.

<u>Maintenance</u>: All parking areas, sidewalks, driveways and other impervious surfaces (except roofs) will be swept clean of sand, litter, trash, etc. at least twice a year. A log of land/lot sweeping, and cleanup will be kept. Housekeeping concerns noted by residents, guests, PPT members, and others will be noted and acted upon. Separate cleanup services will be conducted at least twice a year, once between November 14 and December 15 (after leaf fall) and once during the month of April (after snow melt). Additional cleanup services will be conducted as necessary.

Open Space/Landscaped Area

Landscaped areas provide groundwater recharge and a buffer between paved areas.

Inspection: Twice a year and after major storm events.

<u>Maintenance:</u> Note and repair any erosion or uneven grades. Remove trash and debris. Rake and seed to maintain vegetative cover.

Curbing:

Although the site grading design generally directs runoff away from curbing, it is still important for the curbing to be in good working order to delineate edge of pavement from grass and landscaped areas.

Inspection: Inspect site curbing semi-annually to ensure sound structural condition.

Maintenance: Repair/replace as needed.

Please refer to Appendix A for the Inspection Forms, which are to be used by the Pollution Prevention Team member responsible for conducting the scheduled inspections.

SECTION 2 – SOURCE CONTROL PLAN

A. MATERIALS COVERED

The following materials or substances are expected to be present onsite after construction:

Cleaning solvents	Petroleum based products
Detergents	Pesticides/Insecticides
Paints/Solvents	Fertilizers/Herbicides
Acids	Pet waste
Solid Waste	Contaminated Soil

B. MATERIALS MANAGEMENT PRACTICES

The following are the material management practices that will be used to reduce the risk of spills or other accidental exposure of materials and substances to stormwater runoff. The Pollution Prevention Team Leader will be responsible for ensuring that these procedures are followed:

1. Good Housekeeping

The following good housekeeping practices will be followed onsite after construction:

- a) An effort will be made to store only enough products required to do the job.
- b) All materials stored onsite will be stored in a neat, orderly manner and, if possible, under a roof or in a containment area. At a minimum, all containers will be stored with their lids on when not in use. Drip pans shall be provided under all dispensers.
- c) Products will be kept in their original containers with the original manufacturer's label in legible condition.
- d) Substances will not be mixed with one another unless recommended by the manufacturer.
- e) Whenever possible, all of a product will be used up before disposing of the container.
- f) Manufacturer's recommendations for proper use and disposal will be followed.
- g) A Pollution Prevention Team Member will be responsible for daily inspections to ensure proper use and disposal of materials.
- 2. Hazardous Substances

These practices will be used to reduce the risks associated with Hazardous Substances. Material Safety Data Sheets (MSDS's) for each product with hazardous properties that is used at the Project will be obtained and used for the proper management of potential wastes that may result from these products. An MSDS will be posted in the immediate area where such product is stored and/or used and another copy of each MSDS will be maintained on-site, in the management office. Each employee who must handle a

Hazardous Substance will be instructed on the use of MSDS sheets and the specific information in the applicable MSDS for the product he/she is using, particularly regarding spill control techniques.

- a) Products will be kept in original containers with the original labels in legible condition.
- b) Original labels and MSDS's will be procured and used for each product.
- c) If surplus product must be disposed of, the manufacturer's and local/state/federal required methods for proper disposal must be followed.
- 3. Hazardous Waste

It is imperative that all Hazardous Waste be properly identified and handled in accordance with all applicable Hazardous Waste Standards, including the storage, transport and disposal of the Hazardous Wastes. There are significant penalties for the improper handling of Hazardous Wastes. It is important that the Pollution Prevention Team Leader seeks appropriate assistance in making the determination of whether a substance or material is a Hazardous Waste. For example, Hazardous Waste may include certain Hazardous Substances, as well as pesticides, paints, paint solvents, cleaning solvents, contaminated soils, and other materials, substances or chemicals that have been discarded (or are to be discarded) as being out-of-date, contaminated, or otherwise unusable. The Pollution Prevention Team Leader is responsible for ensuring that all Pollution Prevention Team Members are instructed as to these Hazardous Waste requirements and also that the requirements for handling and disposal are being followed.

4. Product Specific Practices

The following product specific practices will be followed on the job site:

a) Petroleum Products

Petroleum products will be stored in tightly sealed containers which are clearly labeled. Petroleum storage tanks shall be located a minimum of 100 linear feet from wetland resource areas, drainage ways, inlets and surface waters unless stored within a building. Any petroleum storage tanks stored onsite will be located within a containment area that is designed with an impervious surface between the tank and the ground. The secondary containment must be designed to provide a containment volume that is equal to 110% of the volume of the largest tank. Drip pans shall be provided for all dispensers. Any asphalt substances used onsite will be applied according to the manufacturer's recommendations. The location of any fuel tanks and/or equipment storage areas must be identified on the Erosion Control Plan by the Contractor once the locations have been determined. b) Fertilizers, Herbicides, Pesticides, and Insecticides

Fertilizers, herbicides, pesticides, insecticides and/or pool chemicals will be applied only in the minimum amounts recommended by the manufacturer. Once applied, they will be worked so as to limit exposure to storm water. Storage will be in a covered shed. The contents of any partially used bags or containers will be transferred to a sealable plastic bin to avoid spills.

c) Paints, Paint Solvents, and Cleaning Solvents

All containers will be tightly sealed and stored when not in use. Excess paint and solvents will not be discharged to the storm sewer system but will be properly disposed of according to manufacturer's instructions or state and federal regulations.

5. Solid Waste

All waste materials will be collected and stored in an appropriately covered container and/or securely contained metal dumpster rented from a local waste management company which must be a licensed solid waste management company. The dumpster will comply with all local and state solid waste management regulations.

All trash and debris from the site will be deposited in dumpsters. The dumpsters will be emptied a minimum of once per week or more often if necessary. All personnel will be instructed regarding the correct procedures for waste disposal.

All waste dumpsters and roll-off containers will be located in an area where the likelihood of the containers contributing to storm water discharges is negligible. No debris, refuse or other materials, including but not limited to landscaping debris, leaves, shrubs and tree trimmings, logs, bricks stone or trash shall be deposited within the vegetated wetland or within 25 feet of the vegetated wetland.

6. Contaminated Soils

Any contaminated soils (resulting from spills of Hazardous Substances or Oil) will be contained and cleaned up immediately in accordance with the procedures given in the Materials Management Plan and in accordance with applicable state and federal regulations. If there is a release, it should be reported as a spill, if it otherwise meets the requirements for a reportable spill.

7. Pet Waste

The site will be inspected weekly for pet waste. Pet waste will be collected, placed in a closed, tied trash bag and disposed of in accordance with applicable code requirements.

SPILL PREVENTION AND RESPONSE PROCEDURES

The Pollution Prevention Team Leader will train all personnel in the proper handling and cleanup of spilled Hazardous Substances or Oil. No spilled Hazardous Substances or Oil will

be allowed to come in contact with storm water discharges. If such contact occurs, the storm water discharge will be contained on site until appropriate measures in compliance with state and federal regulations are taken to dispose of such contaminated storm water. It shall be the responsibility of the Pollution Prevention Team Leader to be properly trained, and to train all personnel in spill prevention and clean up procedures.

- i. In order to prevent or minimize the potential for a spill of Hazardous Substances or Oil to come into contact with storm water, the following steps will be implemented:
 - a) All Hazardous Substances or Oil (such as pesticides, petroleum products, fertilizers, detergents, acids, paints, paint solvents, cleaning solvents, etc.) will be stored in a secure location, with their lids on, preferably under cover, when not in use.
 - b) The minimum practical quantity of all such materials will be kept on site.
 - c) A spill control and containment kit (containing, for example, absorbent materials, acid neutralizing powder, brooms, dust pans, mops, rags, gloves, goggles, plastic and metal trash containers, etc.) will be provided on site.
 - d) Manufacturer's recommended methods for spill cleanup will be clearly posted and site personnel will be trained regarding these procedures and the location of the information and cleanup supplies.
 - e) It is the Pollution Prevention Team Leader's responsibility to ensure that all Hazardous Waste on site is disposed of properly by a licensed hazardous material disposal company. The Pollution Prevention Team Leader is responsible for not exceeding Hazardous Waste storage requirements mandated by the EPA or state and local authority.
- ii. In the event of a spill of Hazardous Substances or Oil, the following procedures must be followed:
 - a) All measures must be taken to contain and abate the spill and to prevent the discharge of the Hazardous Substance or Oil to storm water or off-site. (The spill area must be kept well ventilated and personnel must wear appropriate protective clothing to prevent injury from contact with the Hazardous Substances.)
 - b) For spills of less than five (5) gallons of material, proceed with source control and containment, clean-up with absorbent materials or other applicable means unless an imminent hazard or other circumstances dictate that the spill should be treated by a professional emergency response contractor.
 - c) For spills greater than five (5) gallons of material immediately contact the NH DES Spill Response and Complaint Investigation Section at (603) 271-3899 Monday – Friday, 8am to 4pm or the NH State Police at (603) 223-4381 on weekends and evenings, and an approved emergency response contractor. Provide information on the type of material spilled, the location of the spill, the quantity spilled, and the time of the spill to the emergency response contractor or coordinator, and proceed with prevention, containment and/or clean-up if so desired.
 - d) If there is a Reportable Quantity (RQ) release, then the National Response Center will be notified immediately at (800) 424-8802; within 14 days a report will be submitted

to the EPA regional office describing the release, the date and circumstances of the release and the steps taken to prevent another release. This Pollution Prevention Plan must be updated to reflect any such steps or actions taken and measures to prevent the same from reoccurring.

iii. The Pollution Prevention Team Leader will be the spill prevention and response coordinator. He/she will designate the individuals who will receive spill prevention and response training. These individuals will each become responsible for a particular phase of prevention and response. The names of these personnel will be posted in the material storage area and in the management office.

SECTION 3 - SNOW MANAGEMENT AND DISPOSAL PLAN

Snow management will be overseen by a full-time Property Manager who will implement this plan and be authorized to utilize additional resources should unusual events occur. The Snow Management Contractor (SMC) shall be responsible for maintaining all roads, driveways, parking lots, sidewalks and pedestrian access areas for clear and safe travel. The SMC shall report directly to the Property Manager and maintain communication via cell phones 24 hours per day, 7 days per week. All roads, drives, entrances and exits are the first priority. During extreme events, the first priority will be to clear and maintain proper access for residents and public safety vehicles. The next priority is parking areas, sidewalks, fire hydrants, and delivery areas. Snow will not be piled around light bases and handicap parking areas shall be cleared frequently.


The anti-icing operations typically precede snow plowing and will be provided when conditions warrant. Within 12 months of concrete walks, pads, or other features being poured, no de-icers shall be placed on those surfaces. After the materials have cured for 12 months, a combination of calcium chloride de-icers and sand (washed, fine to medium grade) shall be utilized. Parking areas shall receive spot treatment only when and where needed in a similar manner. The sand/calcium chloride mixture shall consist of 20 parts calcium chloride to 80 parts sand.


Snow plowing shall commence upon accumulation of two inches ("2") or more. Snow shall be deposited in designated areas, refer to SMP-1, Snow Management Plan. The SMC shall keep existing catch basins open for drainage or water resulting from melting.

Once the storm is over, the SMC shall monitor all areas on-site for icy spots and snowdrifts. If needed, an application of sand and salt will be applied to all streets and roads so that the riding surface remains drivable. When the ambient temperature drops below 25 degrees F, all major areas will receive an application of pre-wetted salt with calcium chloride to maintain melting action and an ice-free surface for as long as possible. Salt loses its effectiveness at temperatures below 25 degrees F.

Deicing chemicals will be kept in original containers with the original product label in legible condition. When not in use, deicing materials will be stored in a neat, orderly manner under cover with their container lids on.


Figures






GRAPHIC SCALE IN FEET










GRAPHIC SCALE IN FEET





RJO'CONNELL

& ASSOCIATES, INC. CIVIL ENGINEERS, SURVEYORS & LAND PLANNERS

DATE: 02/18/2020

SCALE: 1"=120'

SNOW MANAGEMENT PLAN

DURGIN SQUARE

PORTSMOUTH, NH

Copyright © 2020 by R.J. O'Connell & Associates, Inc.

Appendix A Inspection and Maintenance Forms

Durgin Square Inspection and Maintenance Manual Activity Guide

The table below is a list of the minimum inspection and maintenance activities the Pollution Prevention Team needs to conduct as part of the Stormwater Inspection and Maintenance Plan and who is responsible for the activity. The Activity Guide is provided to assist the Pollution Prevention Team Leader and ensure that the activities are being conducted as scheduled.

Timing	Activity	Responsible Party
Weekly	Inspect lot/land	PPT
	Pet waste management	PPT
Monthly	Inspect and clean parking lot and paved areas	PPT
	Inspect outside storage areas	PPT
Quarterly	Inspect catch basins	PPT
	Inspect oil/particle separators	PPT/Contractor
Semi-Annually	Inspect and clean catch basins	Contractor
	Parking lot sweeping	Contractor
	Clean oil/particle separators	Contractor
	Inspect and repair landscaping areas	PPT/Contractor
Annually	Pollution Prevention Team training	PPT Leader
	Comprehensive annual stormwater evaluation and	PPT Leader
	inspection report	
April	Spring clean-up,	PPT/Contractor
Between	Fall clean-up	PPT/Contractor
November 14 and		
December 15		

Durgin Square Inspection and Maintenance Manual Comprehensive Annual Evaluation and Inspection Report

Once a year, the Pollution Prevention Team Leader must inspect and evaluate all aspects and provisions of the Inspection and Maintenance Plan, complete the following report and keep a copy on file at the site.

Inspector/Reviewers:_____ Date of Inspection/Review: Note any changes to the Plan in the space below and in the appropriate section of the Plan. 1. Review the Pollution Prevention Team list and update if necessary. Does the Pollution Prevention Team list need updating? (circle one) Yes No 2. Review the Inspection and Maintenance Plan (I&M Plan). Are there sections of the I&M Plan that need updating? (circle one) Yes No 3. Review Monthly and Weekly Checklists. Update these as necessary. - Are there any updates needed to Spill and Leak History and/or the checklists? (circle one) Yes No 4. Review site drawings and update if necessary - Are there updates needed to any of the drawings? (circle one) Yes No **Requested Changes** (attach revisions)

Durgin Square Inspection and Maintenance Manual Annual Training Signoff Sheet

For each Inspection and Maintenance Plan training session, the Team Leader should keep records of all attending Team Members using the signoff sheet below, as well as the training agenda, notes, etc.

Training Date:	Торіс:
Trainer:	
Team Member Name	Team Member Signature

Durgin Square Inspection and Maintenance Manual Weekly Inspection Checklist

The site will be checked each week for trash and debris by a member of the Pollution Prevention Team. If any trash or debris is observed in the specified area, write "yes" in the 2^{nd} column and note the problem and corrective measures taken in the appropriate space. Make a new copy of this checklist each week.

Date: _____

Checklist completed by: _____

GROUNDS AREA TO CHECK	TRASH OR DEBRIS PRESENT?	DESCRIPTION OF PROBLEM	CORRECTIVE MEASURES TAKEN
Parking Lot &			
Roadways			
Landscaped Areas			
Dumpster/Loading			
Areas			
Perimeter of Property			

Durgin Square Inspection and Maintenance Manual Monthly Inspection Checklist

The following will be checked each month for sources of pollutants by a member of the Pollution Prevention Team. If the condition in the "check for" column is observed, note the problem and corrective measures taken in the appropriate space. Make a new copy of the checklist each month.

Date: Checklist completed by:			
ВМР	ACTIVITY	DESCRIPTION OF PROBLEM (IF PRESENT)	CORRECTIVE MEASURES TAKEN
Sweeping	Sweep Parking Lot and Paved Areas Spillage and Trash		
Outside Storage Areas (Dumpsters/Loading Area)	Check for leaking liquid		

Durgin Square Inspection and Maintenance Manual Quarterly Inspection Checklist

The following will be checked each quarter for sources of pollutants by a member of the Pollution Prevention Team. If the condition in the "check for" column is observed, note the problem and corrective measures taken in the appropriate space. Make a new copy of the checklist each quarter.

Date:	Checklist com	pleted by:	
BMP	ACTIVITY	DESCRIPTION OF PROBLEM (IF PRESENT)	CORRECTIVE MEASURES TAKEN
Catch Basins	Check for trash, excessive sediment, oil sheen, hood (securely fastened)		
Oil/Particle Separators	Check for accumulated sediment and floatable debris and trash		

Durgin Square Inspection and Maintenance Manual Semi-Annual Inspection Checklist

The following will be checked each quarter for sources of pollutants by a member of the Pollution Prevention Team. If the condition in the "check for" column is observed, note the problem and corrective measures taken in the appropriate space. Make a new copy of the checklist semi-annually.

Date: _____

Checklist completed by: _____

ВМР	ACTIVITY	DESCRIPTION OF PROBLEM (IF PRESENT)	CORRECTIVE MEASURES TAKEN
Catch Basins	Jet vacuum and power wash, remove trash, debris, and excessive sediment. Check for oil sheen and hood being securely fastened		
Oil/Particle Separators	Jet vacuum and power wash		
Curbing	Inspect structural condition		
Landscaping Areas	Remove trash and debris. Inspect and repair erosion and washout areas, reseed as necessary		

Durgin Square Inspection and Maintenance Manual Annual Inspection Checklist

The following will be checked each quarter for sources of pollutants by a member of the Pollution Prevention Team. If the condition in the "check for" column is observed, note the problem and corrective measures taken in the appropriate space. Make a new copy of the checklist each year.

Date:	Checklist com	pleted by:	
BMP	ACTIVITY	DESCRIPTION OF PROBLEM (IF PRESENT)	CORRECTIVE MEASURES TAKEN
Pollution Prevention Team Training	Prepare annual stormwater evaluation and inspection report		

Durgin Square Inspection and Maintenance Manual Spill and Leak History (_____ to ____)

Date	Spill	Leak	Location		Des	cription		Response Procedures	Measures to Prevent Reoccurrence	Reporting Pollution Prevention Team Member
(<i>MM/DD/YY</i>)	(check	one)	(as indicated on Site Map)	Type of Material	Quantity	Source, if known	Reason			

This Page Intentionally Left Blank

Appendix B CDS Treatment Unit Operations and Maintenance Guidelines This Page Intentionally Left Blank

OPERATIONS AND MAINTENANCE GUIDELINES

CDS Stormwater Treatment Unit

INTRODUCTION

The CDS unit is an important and effective component of your storm water management program and proper operation and maintenance of the unit are essential to demonstrate your compliance with local, state and federal water pollution control requirements.

The CDS technology features a patented non-blocking, indirect screening technique developed in Australia to treat water runoff. The unit is highly effective in the capture of suspended solids, fine sands and larger particles. Because of its non-blocking screening capacity, the CDS unit is un-matched in its ability to capture and retain gross pollutants such as trash and debris. In short, CDS units capture a very wide range of organic and in-organic solids and pollutants that typically result in tons of captured solids each year such as: Total suspended solids (TSS) and other sedimentitious materials, oil and greases, trash, and other debris (including floatables, neutrally buoyant, and negatively buoyant debris). These pollutants will be captured even under very high flow rate conditions.

CDS units are equipped with conventional oil baffles to capture and retain oil and grease. Laboratory evaluations show that the CDS units are capable of capturing up to 70% of the free oil and grease from storm water. CDS units can also accommodate the addition of oil sorbents within their separation chambers. The addition of the oil sorbents can ensure the permanent removal of 80% to 90% of the free oil and grease from the storm water runoff.

OPERATIONS

The CDS unit is a non-mechanical self-operating system and will function any time there is flow in the storm drainage system. The unit will continue to effectively capture pollutants in flows up to the design capacity even during extreme rainfall events when the design capacity may be exceeded. Pollutants captured in the CDS unit's separation chamber and sump will be retained even when the units design capacity is exceeded.

CDS UNIT INSPECTION

Access to the CDS unit is typically achieved through two manhole access covers – one allows inspection (and clean out) of the separation chamber (screen/cylinder) & sump and another allows inspection (and cleanout) of sediment captured and retained behind the screen.

The unit should be periodically inspected to determine the amount of accumulated pollutants and to ensure that the cleanout frequency is adequate to handle the predicted pollutant load being processed by the CDS unit. The unit should be periodically inspected for indications of vector infestation, as well. The recommended cleanout of

solids within the CDS unit's sump should occur at 75% to 85% of the sump capacity. However, the sump may be completely full with no impact to the CDS unit's performance.

CONTECH Stormwater Solutions (previously CDS Technologies) recommends the following inspection guidelines: For new initial operation, check the condition of the unit after every runoff event for the first 30 days. For ongoing operations, the unit should be inspected after the first six inches of rainfall at the beginning of the rainfall season and at approximately 30-day intervals. The visual inspection should ascertain that the unit is functioning properly (no blockages or obstructions to inlet and/or separation screen), evidence of vector infestation, and to measure the am ount of solid materials that have accumulated in the sump, fine sediment accumulated behind the screen, and floating trash and debris in the separation chamber. This can be done with a calibrated dipstick, tape measure or other measuring instrument so that the depth of deposition in the sump can be tracked.

CDS UNIT CLEANOUT

The frequency of cleaning the CDS unit will depend upon the generation of trash and debris and sediments in your application. Cleanout and preventive maintenance schedules will be determined based on operating experience unless precise pollutant loadings have been determined.

Access to the CDS unit is typically achieved through two manhole access covers – one allows cleanout of the separation chamber (screen/cylinder) & sump and another allows cleanout of sediment captured and retained behind the screen. For units possessing a sizable depth below grade (depth to pipe), a single manhole access point would allow both sump cleanout and access behind the screen.

CONTECH Stormwater Solutions Recommends The Following:

<u>NEW INSTALLATIONS</u>: Check the condition of the unit after every runoff event for the first 30 days. The visual inspection should ascertain that the unit is functioning properly (no blockages or obstructions to inlet and/or separation screen), measuring the amount of solid materials that have accumulated in the sump, the amount of fine sediment accumulated behind the screen, and determining the amount of floating trash and debris in the separation chamber. This can be done with a calibrated "dip stick" so that the depth of deposition can be tracked. Refer to the "Cleanout Schematic" (**Appendix B**) for allowable deposition depths and critical distances. Schedules for inspections and cleanout should be based on storm events and pollutant accumulation.

<u>ONGOING OPERATION:</u> During the rainfall season, the unit should be inspected at least once every 30 days. The floatables should be removed and the sump cleaned when the sump is 75-85% full. If floatables accumulate more rapidly than the settleable solids, the floatables should be removed using a vactor truck or dip net before the layer thickness exceeds approximately one foot.

Cleanout of the CDS unit at the end of a rainfall season is recommended because of the nature of pollutants collected and the potential for odor generation

from the decomposition of ma terial collected and retai ned. This end of season cleanout will assist in preventing the discharge of pore water from the CDS [®] unit during summer months.

<u>USE OF SORBENTS</u> –The addition of sorbents is **not a requirement** for CDS units to effectively control oil and grease from storm water. The conventional oil baffle within a unit assures satisfactory oil and grease removal. However, the addition of sorbents is a unique enhancement capability unique to CDS units, enabling increased oil and grease capture efficiencies beyond that obtainable by conventional oil baffle systems.

Under normal operations, CDS units will provide effluent concentrations of oil and grease that are less than 15 parts per million (ppm) for all dry weather spills where the volume is less than or equal to the spill capture volume of the CDS unit. During wet weat her flows, the oil baffle system can be expected to remove between 40 and 70% of the free oil and grease from the storm water runoff.

CONTECH Stormwater Solutions only recommends the addition of sorbents to the separation chamber if there are specific land use activities in the catchment watershed that could produce exceptionally large concentrations of oil and grease in the runoff, concentration levels well above typical amounts. If site evaluations merit an increased control of free oil and grease then oil sorbents can be added to the CDS unit to thoroughly address these particular pollutants of concern.

Recommended Oil Sorbents

Rubberizer® Particulate 8-4 mesh or OARS [™] Particulate for Filtration, HPT4100 or equal. Rubberizer is supplied by Haz-Mat Response Technologies, Inc. 4626 Sant a Fe Street, San Diego, CA 92109 (800) 542-3036. OARS is supplied by AbTech Industries, 4110 N. Scottsdale Road, Suite 235, Scottsdale, AZ 85251 (800) 545-8999.

The amount of sorbent to be added to the CDS separation chamber can be determined if sufficient information is k nown about the concentration of oil and grease in the runoff. Frequent ly the actual concentrati ons of oil and grease are too variable and the amount to be added and frequency of cleaning will be determined by periodic observation of the sorbent. As an initial application, CDS recommends that approximately 4 to 8 pounds of sorbent material be added to the separation chamber of the CDS units per acre of parking lot or road surface per year. Typically this amount of sorbent results in a ½ inch to one (1") inch depth of sorbent material on the liquid surface of the separation chamber. The oil and grease loading of the sorbent material should be observed after major storm events. Oil Sorbent material may also be furnished in pillow or boom configurations.

The sorbent material should be replaced when it is fully discolore d by skim ming the sorbent from the surface. The sorbent may require disposal as a spec ial or hazardous waste, but will depend on local and state regulatory requirements.

CLEANOUT AND DISPOSAL

A vactor truck is recommended for cleanout of the CDS unit and can be easily accomplished in less than 30-40 minutes for most installations. Standard vactor operations should be employed in the cleanout of the CDS unit. Disposal of material from the CDS unit should be in accordance with the local municipalit y's requirements. Disposal of the decant material to a POTW is recommended. Field decanting to the storm drainage system is not recommended. Solids can be disposed of in a similar fashion as those materials collected from street sweeping operations and catch-basin cleanouts.

MAINTENANCE

The CDS unit should be pumped down at least once a year and a thorough inspection of the separation chamber (inlet/cylinder and separation screen) and oil baffle performed. The unit's inter nal components should not show any signs of damage or any loosening of the bolts used to fasten the various components to the manhole structure and to each other. Ideally, the screen should be power washed for the inspection. If any of the internal components is damaged or if any fasteners appear to be damaged or missing, please contact CONTECH at 800.338.2211 to make arrangements to have the damaged items repaired or replaced.

The screen assembly is fabricated from Type 316 stainless steel and fastened with Type 316 stainless steel fasteners that are easily removed and/or replaced with conventional hand tools. The damaged screen assembly should be replaced with the new screen assembly placed in the same orientation as the one that was removed.

CONFINED SPACE

The CDS unit is a confined space environ ment and only properly trained personn el possessing the neces sary safety equipment s hould enter the unit to perform particular maintenance and/or inspection activities beyond normal procedure. Inspections of the internal components can, in most cases, be accomplished by observations from the ground surface.

VECTOR CONTROL

Most CDS units do not readily facilitate vector infestation. However, for CDS units that may experience extended periods of non-operation (stagnant flow conditions for more than approximately one week) ther e may be the potential for vector infestation. In the event that these conditions exist, the CDS unit may be designed to minimize potential vector habitation through the use of physical barriers (such as seals, plugs and/or netting) to seal out potential vectors. The CDS unit may also be configured to allow drain-down under favorable soil conditions where infiltration of storm water runoff is permissible. For standard CDS units that show evidence of mosquito infestation, the

application of larvicide is one control strategy that is recommended. Typical larvicide applications are as follows:

<u>SOLID B.t.i. LARVICIDE</u>: ½ to 1 briquet (typically treats 50-100 sq. ft.) one time per month (30-days) or as directed by manufacturer.

<u>SOLID METHOPRENE LARVICIDE</u> (not recommended for some locations): $\frac{1}{2}$ to 1 briquet (typically treats 50-100 sq. ft.) one time per month (30-days) to once every $4-\frac{1}{2}$ to 5-months (150-days) or as directed by manufacturer.

RECORDS OF OPERATION AND MAINTENANCE

CONTECH Stormwater Solutions recomme nds that the owner m aintain annual records of the operation and maintenance of the CDS unit to document the effective maintenance of this import ant component of your storm water management program. The attached **Annual Record of Operations and Maintenance** form (see **Appendix A**) is suggested and should be retained for a minimum period of three years.

APPENDIX A ANNUAL RECORDS OF OPERATIONS & MAINTENANCE AND INSPECTION CHECKLISTS

ANNUAL RECORD OF **OPERATION AND MAINTENANCE**

OWNER	
ADDRES	S

OWNER REPRESENTATIVE PHONE

INSTALLATION:

MODEL DESIGNATION

SITE LOCATION

DATE_____

INSPECTIONS

INSPECTIO	N3:				
DATE/ INSPECTOR	SCREEN/INLET INTEGRITY	FLOATABLES DEPTH	DEPTH TO SEDIMENT (inches)	SEDIMENT VOLUME* (CUYDS)	SORBENT DISCOLORATION

DEPTH FROM COVER TO BOTTOM OF SUMP (SUMP INVERT)

DEPTH FROM COVER TO SUMP @ 75% FULL _____

VOLUME OF SUMP @ 75% FULL = _ CUYD

VOLUME/INCH DEPTH CUFT/IN OF SUMP

VOLUME/FOOT DEPTH CUYD/FT OF SUMP

Calculate Sediment Volume = (Depth to Sump Invert – Depth to Sediment)(Volume/inch)

OBSERVATIONS OF FUNCTION: _____

CLEANOUT:

DATE	VOLUME	VOLUME	METHOD OF DISPOSAL OF FLOATABLES, SEDIMENTS, DECANT
	FLOATABLES	SEDIMENTS	AND SORBENTS

OBSERVATIONS:

SCREEN MAINTENANCE:

DATE OF POWER WASHING, INSPECTION AND OBSERVATIONS:

CERTIFICATION:_____ TITLE:____

DATE:_____

INSPECTION CHECKLIST

- 1. During the rainfall season, inspect and check condition of unit at east once every 30 days
- 2. Ascertain that the unit is funcioning properly (no blockages or obstructions to inlet and/or separation screen)
- 3. Measure amount of solid material s that have accumulated in the sump (Unit should be cleaned when the sump is 75-85% full)

- 4. Measure amount of fine sediment accumulated behind the screen
- 5. Measure amount of floating trash and debris in the separation chamber

MAINTENANCE CHECKLIST

- 1. Cleanout unit at the end and beginning of the rainfall season
- 2. Pump down unit (at least once a year) and thoroughly inspect separation chamber, separation screen and oil baffle
- No visible signs of damage or loosening of bolts to internal components observed *
 - * If there is any damage to the internal components or any fasteners are damaged or missing please contact CONTECH (800.338.1122).



Transportation: Engineering • Planning • Design

MEMORANDUM

Ref: 1995A

To: Juliet Walker, Planning Director, City of Portsmouth Eric Eby, P.E., City of Portsmouth

From: Stephen G. Pernaw, P.E., PTOE

Subject: Supplemental Traffic Analysis - Durgin Square Portsmouth, New Hampshire


Date: February 18, 2020

<u>Background</u> – At our meeting with City staff on 2/13/20 to discuss driveway alternatives at the GameStop driveway on Woodbury Avenue, the City requested that our office: 1) conduct Saturday midday traffic counts at the five site driveways that provide access to Durgin Square, 2) to conduct a supplemental count at the Federal Savings Bank driveway on Woodbury Avenue, and 3) to prepare updated traffic projections for the right-turn entrance only driveway at the Game Stop site. The purpose of this memorandum is to summarize the results of the recent traffic counts, the trip generation analysis for the new supermarket, and the anticipated traffic volumes at the right-turn entrance only driveway on Woodbury Avenue. To summarize:

<u>Driveway Counts</u> – The turning movement counts were conducted simultaneously on Saturday, February 15, 2020 from 10:00 AM to 2:00 PM at the six study area intersections. Analysis of the count data revealed that the highest one-hour period occurred from 12:00 to 1:00 PM. Figure 1 summarizes the turning movement volumes at each driveway. The following table ranks the site driveways in terms of utilization:

DRIVEWAY UTILIZATION - Sa	turday Peak Hou	r
Rank / Drivew ay	Saturday Trips	Percentage
1. Woodbury / Commerce Way / Durgin Square	257	38%
2. Arthur Brady Drive / Durgin Square Drivew ay	169	25%
3. Durgin Lane / Durgin Square (East Drivew ay)	157	23%
4. Durgin Lane / Durgin Square (West Drivew ay)	92	14%
5. Woodbury / Federal Saving Bank Drivew ay	4	0%
6. Woodbury / GameStop Drivew ay	0	0%
	679	100%

As an aside, during the four-hour driveway count at the Federal Savings Bank driveway (on Woodbury Avenue) 4 illegal high-risk traffic movements were observed: each of the four involved a northbound vehicle on Woodbury Avenue that veered to the left of the raised median island (on Woodbury Avenue) to enter the bank site via the right-out only bank driveway. This results in potential head-on conflicts with not only southbound vehicles on Woodbury Avenue, but also with vehicles exiting from the bank site. This situation will be rectified by the proposed extension of the median island on Woodbury Avenue by DPF Durgin Square.



1995A

Figure 1

Traffic Evaluation, Durgin Square, Portsmouth, New Hampshire



The complete four-hour turning movement count data is summarized on Figure 2 and was utilized for determining the trip distribution patterns for Durgin Square. The following tabulation summarizes the following travel patterns that were derived from the turning movement count data.

GATEWAY	INBOUND	OUTBOUND
Durgin Lane - West	11%	11%
Ocean State - North	2%	2%
Woodbury Ave - North	37%	35%
Commerce Way - East	4%	9%
Woodbury Ave - South	34%	34%
Arthur Brady Dr - West	12%	9%
	100%	100%

EXISTING TRIP DISTRIBUTION PATTERNS

It should be noted, that the existing trip distribution patterns observed in the field are significantly different from that which was utilized in our previous memorandum. Our previous analysis underestimated the amount of traffic to/from the site via points west on Durgin Lane and south on Woodbury Avenue.


<u>Trip Generation</u> – The following table summarizes the trip generation estimates for Durgin Square Plaza. The driveway counts for the existing site (85,163 sf occupied) resulted in slightly higher traffic volumes than would be expected using the ITE trip generation equations for Land Use Code 820 (Shopping Center). For this reason, the vacant space within the existing Plaza (7,535 sf) was accounted for using the observed trip generation rate, rather than ITE. The trips associated with the new supermarket are based on ITE Land Use Code 850 (Supermarket).

Table 1			Trip Gener	ation Summ	ary	
		Existing Site ¹	Vacant Space ²	Subtotal	New Food Store ³	Total
Saturday Peak Hour (1	2:00 - 1:00 PM)					
	Entering	351 veh	30 veh	381 veh	249 veh	630 veh
	Exiting	<u>328</u> veh	<u>30 veh</u>	<u>358 veh</u>	<u>239 veh</u>	<u>597</u> veh
	Total	679 trips	60 trips	739 trips	488 trips	1,227 trips

¹Driveway Counts Conducted on Saturday February 15, 2020 - See Attachment 1


²Vacant Space Adjustment (based on Durgin Square trip generation rate > ITE trip generation rate)

³ITE Land Use Code 850 - Supermarket (42,041sf) - See Attachment 2




Traffic Evaluation, Durgin Square, Portsmouth, New Hampshire

1995A



<u>Driveway Volumes</u> – The proposed "right-turn enter-only" driveway at the GameStop site will be utilized by supermarket customers as well as other patrons of the Durgin Square Plaza. The post-development traffic projections for the proposed right-in only driveway at the GameStop site on Woodbury Avenue is summarized below schematically:




It should be noted that the right-turn entering volume is not critical as this movement encounters no conflicting traffic stream; therefore there is unlimited capacity for this traffic movement and vehicle delays will be nil.

Conclusions:

- 1. Converting the existing full-access driveway on Woodbury Avenue at the GameStop site to the proposed "right-turn enter-only" driveway will reduce the number of basic conflict points from six to one.
- 2. This driveway will be beneficial for southbound drivers on Woodbury Avenue who may not be familiar with the site, and the need to turn right onto Durgin Lane in advance of the site.
- 3. Extending the raised median island on Woodbury Avenue beyond the "right-turn enter-only" driveway will eliminate the illegal high-risk traffic movements that were observed at the Federal Savings Bank driveway, as well as the bank's concern with occasional left-turn departure movements from this bank driveway.
- 4. Providing an additional well-defined point of <u>access</u> on Woodbury Avenue (for southbound vehicles only) has the potential to lessen the traffic demand on Durgin Lane and will enable drivers to choose their access route depending upon local traffic conditions.
- 5. The proposed "right-turn enter-only" driveway will operate safely and efficiently from a transportation planning and traffic engineering standpoint, and will not significantly impact the flow of southbound through traffic on the corridor.

CC: Alicia C. Busconi, Vice President, KeyPoint Partners, LLC Steve Glowacki, R. J. O'Connell & Associates, Inc. John K. Bosen, Esquire





ATTACHMENTS

Stephen G. Pernaw & Company, Inc

Durgin Square Driveway Counts - Saturday, February 15, 2020

		Inter	Intersection A	Αu		5	Iterse	Intersection B	മ		Int. C	с	Intel	rsecti	Intersection D		<u> </u>	Intersection F	ction	ш			Ţ	Prep	Intersection F						
	_ m	IN OUT	al NBR	EBR NBL NBR WBL IN OUT OUT IN	EBR N		NBL NBL	SBT WBL NBR NBT IN IN OUT OUT	NBR NBT OUT OUT	NBL	SBR EBR IN OUT	-	SBR EI	EBL EI OUT O	EBR NBL OUT IN	SBR SBR	N N	NBL NBL	EBR			SBR	SBT		WBR I		ו ב <u>ש</u> ק	Ē	TOTAL	TOT	
10:00 - 10:15		50	0	4	0	0	9	4	~	-	0	0	0	0	0	~	-	2	3	ო	~			9	~	0	4		-	53	
10:15 - 10:30		5 1	-	4	-	2	S	12	7	5	0	0	0	0	0	4	ო	15	7	ი	ę	ო	0	4	თ	0	10	58	41	66	
10:30 - 10:45	5	7 4	-	5	0	4	7	ი	-	ю	-	-	0	0	0 0	7	7	6	7	-	с	4	0	5	ø	0	9	57	39	96	
10:45 - 11:00	-	4	3	5	0	7	9	9	0	7	-	0	0	0	0 0	e	പ	6	2	ი	0	2	0	2	7	0	7	50	45	95	343
11:00 - 11:15	•	4	~	4	2	0	10	12	-	ო	0	0	0	0	0	9	2	14	16	4	9	4	0	5	12	0	7	62	54	116	406
11:15 - 11:30		6 3	÷	6	7		10	10	~	ო	0	0	0	0	0	5	7	20	14	4	4	5	0	10	9	0	2	63	55	118	425
11:30 - 11:45		12 5	ŝ	10	-	0	15	10	~	-	0	0	0	0	0	œ	2	22	13	S	ъ	12	~	ŧ	9	0	11	87	65	152	481
11:45 - 12:00		9 6	2	10	e	7	21	13	٢	5	0	0	0	0	0 0	10	7	17	13	ø	e	10	~	6	ø	0	10	92	72	164	550
12:00 - 12:15		4	5	5	2	7	16	19	-	3	-	0	0	0	0	œ	~	17	17	ω	10	ი	-	13	11	-	10	79	06	169	603
12:15 - 12:30		5 4	~	8	-	0	13	20	7	7	0	-	0	0	0	13	9	17	9	Ŝ	œ	თ	2	14	9	-	80	78	84	162	647
12:30 - 12:45		13 6	ŝ	7	-		18	13	0	7	0	~	0	0	0 0	1	2	25	15	4	6	9	0	80	4	0	10	102	66	168	663
12:45 - 13:00		8	4	5	-	-	2	19	4	5	0	0	0	0	0	7	ø	18	18	10	5	9	~	12	12	0	15	91	88	179	678
13:00 - 13:15		8	5	ø	2	0	18	18	с	5	0	0	0	0	0	7	0	15	4	2	12	۵	0	1	4	-	8	75	83	158	667
13:15 - 13:30		9	4	11	0	-	10	17	2	2	0	0	0	0	0	12	4	16	18	5	13	4	0	ø	17	0	10	06	77 1	167	672
13:30 - 13:45		9 6	7	4	ო	2	18	13	0	-	0	0	0	0	0 0	12	9	23	16	10	7	9	0	6	თ	~-	7	94	76 1	170	674
13:45 - 14:00		4	2	7	0	ი	11	26	-	7	0	0	0	õ	0 0	10	2	20	15	4	6	4		13	5	0	12	76	81	157	652
	÷	114 63	3 45	111	19	21	191	220	21	50	б	ю	0	0	0	132	49	264	202	06	96	92	~	147	141	4	137 1	1187 1	1036 2	2223	
Generator Peak Hour 12:00 - 13:00 3	k Hour 0 3	r 30 18	3 14	30	Ŋ	4	54	20	7	17	-	7	0	0	0	43	18	77	60	27	32	30	4	47	43	2	43	350	328 6	678	
Intersection A =		in Lan	e / Du	Durgin Lane / Durgin Square West Drivewav	uare V	'est C)rivew	Vav																							

intersection A =

Durgin Lane / Durgin Square West Driveway Durgin Lane / Durgin Square East Driveway / Ocean State Job Lot Driveway Woodbury Avenue / Federal Savings Bank Driveway Intersection B =

Intersection C =

Woodbury Avenue / Game Stop Driveway Intersection D = V Intersection E = V Intersection F = A

Woodbury Avenue / Durgin Square Driveway / Commerce Way Arthur F. Brady Drive / Durgin Square Driveway / Applebees Driveway

Attachment 1


Trip Generation Summary

Saturday Peak Hour of Generator

Phase: Project: 1995A 021820			٨	Open Da nalysis Da		
ITE Land Use	Size	Units	*	Enter	Exit	Total
850 SUPERMARKET 1	42.04	1000 Sq. Ft. GFA		249	239	488
	Unadjus	sted Volume		249	239	488
	Internal	Capture Trips		0	0	0
	Pass-By	y Trips		0	0	0
	Volume	Added to Adjacent Streets		249	239	488

Total Saturday Peak Hour of Generator Internal Capture = 0 Percent


* - Custom rate used for selected time period.



Attachment 3

1995A

Traffic Evaluation, Durgin Square, Portsmouth, New Hampshire



1995A

Traffic Evaluation, Durgin Square, Portsmouth, New Hampshire