

CITY OF PORTSMOUTH

Facility Condition Assessment

Municipal Complex

Asset 0001

Inspected January 23, 2014



TABLE OF CONTENTS

SECTION 1 ASSET OVERVIEW

| | |
|---------------------------------|-------|
| Asset Executive Summary..... | 1.1.1 |
| Asset Summary | 1.2.1 |
| Inspection Team Data..... | 1.3.1 |
| Definitions | 1.4.1 |
| Overview | 1.4.1 |
| Recurring Costs | 1.4.2 |
| Non-Recurring Costs | 1.4.3 |
| Drawings/Project Locations..... | 1.4.6 |
| Photographs | 1.4.6 |
| Category Code Report | 1.5.1 |

SECTION 2 FACILITY PLANNING COSTS AND TOTALS

| | |
|---|-------|
| Facilities Renewal Budget Pro-Forma | 2.1.1 |
| Facilities Renewal Needs by System | 2.2.1 |
| Facilities Renewal Plan | 2.3.1 |
| Project List by Project Classification..... | 2.4.1 |
| Project List by Category/System Code | 2.5.1 |

SECTION 3 SPECIFIC PROJECT DETAILS..... 3.1.1

SECTION 4 LIFECYCLE COMPONENT INVENTORY

| | |
|--|-------|
| Asset Component Inventory..... | 4.1.1 |
| Recurring Component Renewal Schedule | 4.2.1 |
| Recurring Component Expenditure Projections Graph..... | 4.3.1 |

SECTION 5 DRAWINGS/PROJECT LOCATIONS

SECTION 6 PHOTOGRAPHS..... 6.1.1

FACILITY CONDITION ASSESSMENT

SECTION 1

ASSET OVERVIEW


EXECUTIVE SUMMARY - MUNICIPAL COMPLEX

Building Code: 0001
Building Name: MUNICIPAL COMPLEX
Year Built: 1929
Building Use: Office / Administrative
Square Feet: 92,827

Non-Recurring Project Costs by Priority
Near-Term: \$107,065
Short-Term: \$1,482,042
Long-Term: \$188,422


Current Replacement Value: \$27,623,000 **Total Non-Recurring Project Costs:** \$1,777,530

Recurring Component Replacement Cost By Year



Recurring Facilities Renewal Cost By System

| | |
|------------------|---------------------|
| Exterior | \$406,039 |
| Interior | \$3,835,169 |
| Plumbing | \$961,423 |
| HVAC | \$3,209,359 |
| Fire/Life Safety | \$429,190 |
| Electrical | \$2,925,273 |
| Site | \$4,638 |
| Conveying | \$865,812 |
| Equipment | \$629,181 |
| Total | \$13,266,082 |



| | |
|------------------------------------|---------------------|
| Non-Recurring Project Cost | \$1,777,530 |
| Current Needs Cost | \$11,295,590 |
| Projected Facility Renewal Cost | \$1,970,493 |
| Total 10-Year Facility Cost | \$15,043,612 |

| FCNI | FCI | 10-Yr \$/SqFt |
|------|-------|---------------|
| 0.54 | 0.409 | \$162.06 |

ASSET SUMMARY

The Municipal Complex for the City of Portsmouth, New Hampshire is a combined 92,827 square foot facility consisting of three main buildings and multiple connectors and additions. The three main buildings were constructed at different times and for different original purposes and have been partially renovated and modified to meet evolving needs. The southernmost building, also referred to as the Seybolt Building, was constructed in 1929 as a hospital. The middle or administrative building is a 1950s expansion of the hospital. The 1988 revisions converted the entire building to the City Hall. The northernmost building is the Police Department building. It was constructed in 1962 as a hospital and renovated in 1990 to its current configuration. Several other additions and partial renovations have been completed to join the three buildings into one functioning complex. Recently, significant interior finish improvements and updates have been completed on the fourth floor of the complex.

Although multiple generations of construction comprise the total complex, all are of a similar general construction type, which is concrete masonry unit (CMU) walls and poured concrete floors and foundations. Partial drawings provided by the City dated three main periods of renovation and construction. These dates were used to estimate the installation dates or last significant repairs to the building elements.

Information for this report was gathered during a site visit conducted on January 23, 2014.

Site

The site around this complex is relatively flat, but does slope towards South Mill Pond from approximately the intersection of the 1950s building and the 1962 building and additions, causing grade changes towards the north end of the complex. Landscaping is adequate and consists of grass and minimal shrubbery and flora. There are shared asphalt parking areas to the west side of the building and small parking areas and asphalt drives to the east of the building. Asphalt drives and shared parking areas to the west of the building are in need of minor repairs but are not a part of this evaluation. Joints in concrete walks serving the building are in need of repair. Minor surface repairs, crack sealing and re-striping, are needed at the east side drives and parking areas.

Exterior Structure

The roof systems consist of three different types and three main dates of construction. The 1929 and 1950s buildings have pitched, slate tile roofs with copper gutters and downspouts. Minor isolated repairs are needed throughout on these roofs. The 1962 building and connectors have flat, ballasted single-ply membrane roofs with interior roof drains. Significant portions of the ballasted roof system were replaced in 2009 and are in good condition. The remaining portions of the flat, ballasted roof, gutters and downspouts are older and need to be replaced. There are two small sections of flat roof, one at the conference room to the west of the 1929 and 1950s buildings connector and one at the

fourth floor office at the east side of the 1929 building, that have non-ballasted, flat, single-ply membrane roofs. These are in good condition.

The exterior walls are CMU block with mostly brick veneer and are in fair condition. Minor to moderate mortar joint tuck-pointing repairs are needed throughout. The mechanical penthouse on the roof of the 1962 building has metal panel exterior wall panels that are in overall fair condition and in need of some repairs. Building windows in the 1962 wing are metal-framed units in overall fair to poor condition. The remaining windows in this complex are metal-framed insulating units in overall good to fair condition.

Exterior pedestrian doors are either fully metal or metal with insulated glass panes and are in good condition. However, the door hardware is in need of replacement. Glass storefront doors and vestibules at the 1950s building main (west) entry and at the 1962 building main (west) entry need to be replaced. Two commercial, metal, roll-up overhead doors at the east side Police Department addition are in average condition and are expected to need replacement within the next ten years.

Interior Finishes/Systems

Suspended, acoustical tile ceilings vary in condition depending on age and location, but have generally been replaced as needed. This type of as-needed replacement has created a lack of uniformity in the tile color, suspended grid construction, and, in some areas, tile size. Newer tiles, particularly in the Police Department and on the fourth floor, are serviceable for the next ten years. Older tile systems are in poor condition and should be replaced. This should be coordinated with recommended mechanical system upgrades. Care should be taken during removal of the adhered ceiling tiles, as they or the tile mastic typically are asbestos-containing materials (ACM). Painted or exposed structure ceilings are in need of repainting.

Painted walls throughout the complex have been well maintained and are in good condition but are expected to require renewal within the next ten years. Areas of vinyl wall covering have exceeded their expected life and should be replaced. Restroom walls are ceramic tile or a combination of painted gypsum and ceramic tile. Most of these finishes are aging, in overall fair to poor condition and in need of replacement, especially in view of the necessity of many restroom upgrades for handicapped accessibility issues.

Carpeted floors vary in condition, and all carpeting except on the fourth floor should be replaced within the next ten years. Vinyl composite tile (VCT) flooring is in poor to average condition and sheet vinyl flooring is in poor condition. Replacement is recommended. Concrete floors are serviceable but due for surface treatment. Ceramic and quarry tile floors have been well maintained but are well past their expected lifecycle and should be replaced.

Interior doors on the upper level have been substantially replaced with solid wood doors and commercial-grade ADA compliant level hardware. Interior doors and hardware throughout the remainder of the building are past the end of their expected lifecycle and are in need of replacement. The basement level of the Police Department has specialty sliding doors at the jail and controlled access doors at the entries. These specialty doors have reached or exceeded their expected lifecycle and are in need of replacement.

Wood casework, including kitchen base cabinetry, is in average to poor condition, as are the prefabricated kitchenette units. Also, the existing kitchen base cabinetry does not provide wheelchair access. Install new cabinetry that meets current ADA requirements.

Accessibility

Handicapped access into the buildings of this complex is at the main (west) entry of the 1950s building, which has an interior wheelchair lift, and to the main public entrance (west) to the Police Department lobby, which has grade level entry.

ADA legislation requires that goods and services offered in buildings be generally accessible to all persons. In multiple locations throughout the complex, elevation changes in the corridors are not easily navigable by someone in a wheelchair. It is recommended that a ramp with associated ADA compliant, painted metal or stainless handrails, as the City chooses, be installed at all such locations. The Seybolt Building elevator control systems lack accessible features. It is recommended that the controls be upgraded with a package consisting of a hands-free, two-way telephone, Braille signage, and audible signals. Steps and sloped floors throughout the complex do not have compliant handrails. It is recommended that all handrails that are not ADA-compliant be modified or replaced.

Current legislation requires that building amenities be generally accessible to all persons. Kitchen sinks are not equipped with wheelchair accessible cabinetry, and service counters, particularly at the probate and tax offices and at the main complex reception area, lack a wheelchair accessible counter height. Install wheelchair accessible kitchenette cabinetry, and a wheelchair accessible section should be incorporated into each non-compliant service counter. Also, water fountains are single level bubblers. The installation of ADA compliant, dual level drinking fountains is recommended.

Interior doors typically have knob hardware and lack ADA compliant directional signage. The doors are recommended for lifecycle replacement, and the new units should include compliant hardware. However, if the doors remain in service, the knob hardware should be replaced with ADA compliant levers. Also install room and directional signage that complies with ADA requirements.

Most restrooms do not meet current ADA standards. There are a few handicapped accessible restrooms, but they are not accessible from all areas of the complex. Several restrooms contain showers that are also not ADA compliant, either for the public or for building occupants. All restrooms should be properly equipped with handicapped accessible fixtures and accessories and have wheelchair accessible layouts.

Men's and women's locker rooms in the basement of the Police Department building contain dressing rooms, restrooms, and shower facilities. None of these areas are ADA compliant. Renovations to bring each facility to compliance with ADA requirements are recommended.

Current accessibility legislation requires that stairs have graspable handrails on both sides, that the rails have a specific end geometry, and that the handrails continue horizontally at the landings. In addition, guardrails must prevent the passage of a 4 inch diameter sphere (6 inches in the triangle formed by the lower rail and tread/riser angle). Stairs throughout the facility are not compliant with these ADA standards, as they lack wall rails and the correct geometry. In addition, guardrails lack adequate infill,

and elevated surfaces at multiple locations around the building exterior have missing or inadequate guardrails. Future renovation efforts should include comprehensive railing upgrades.

Health

Rodents were reported by the employees of the complex. Extermination plans should be enacted immediately to eradicate this infestation. Conditions should be closely monitored and concerns addressed as they arise. The adhered ceiling tiles, and possibly other building finishes and systems, apparently contain asbestos. Proper abatement is recommended. Workers present during any remodeling should be made aware of the hazards of working with such materials.

Fire/Life Safety

The elevator lobbies do not have rated vestibules. The present floor plan arrangement has the elevator lobbies opening into the existing hall corridors. IBC 2000 states that elevators opening into a fire resistant corridor shall be provided with an elevator lobby at each floor containing such a corridor. The lobby should completely separate the elevators from the corridor with rated partitions. Elevator lobbies need to have at least one means of egress and contain smoke detectors. The construction of fire resistant barriers with automatically closing fire doors between the elevator lobbies and the corridors is recommended to provide the required separation and protection.

Unsealed penetrations are present throughout the complex, primarily where electrical or mechanical piping passes through. Although the penetrations were mainly observed in the basement, other fire separation compromises may exist elsewhere in the complex. Moderate structural separation repairs and intumescent passive firestopping should be accomplished promptly.

The exterior enclosed emergency egress stair at the south end of the Seybolt Building is constructed of metal grating treads, has non-compliant handrails and guardrails, and is aging, with significant corrosion to welded joints and structural elements. Due to the extent of the compliance issues with this stair, along with its structural condition, it needs to be replaced with a compliant stairwell or stairway.

Access to the mechanical penthouse roof is by a ladder attached to the penthouse exterior wall. The ladder does not have the requisite safety cage. For the protection of personnel accessing the penthouse, install a new ladder, cage, and platform.

This facility has a central fire alarm system with a panel located in the first floor electrical room. The devices that serve this system include manual pull stations and associated audible devices. This system is reportedly less than ten years old, but the lay-out and devices look older and should be replaced with a modern fire alarm system. If the systems and devices can be determined to be 2010 installations, or later, their replacement(s) should be able to be scheduled for closer to 2030.

This facility is protected by an automatic, comprehensive, wet-pipe sprinkler system with fusible-link and glass bulb sprinkler heads. This system is adequate and in good condition. A dry-pipe system is used for areas that are exposed to below freezing conditions.

Chemical fire suppression systems are used for the Archives room, Dispatch, and a third floor IT server room. The system in Dispatch uses Inergen. The systems in the other rooms use Halon. Halon is no longer being produced in the United States due to environmental concerns. In the event of a discharge, the system would likely have to be retrofitted or replaced with an approved extinguishing agent. A budget for replacement with such a system is provided.

Exit signs vary in type, age, and condition. Most are connected to the emergency power network, and a small amount have unitary battery packs. The recently renovated areas contain LED illuminated signs. The older signs have fluorescent lamps or are non-illuminated placards. Emergency lighting is available through standard interior light fixtures connected to the emergency power network. Several unitary battery pack emergency lights are in place for areas not served by the emergency power network or are in critical areas that need redundant sources of emergency lighting. The older exit signs and older battery pack emergency lights should be replaced.

HVAC

Heating hot water is supplied by the nearby Boiler Plant. Heating hot water is supplied to air handling unit coils, unit heaters, two-pipe fan coils, and two-pipe unit ventilators to provide heating in colder months. Chilled water for comfort cooling is provided by water-cooled, screw chillers. The chiller has a capacity of 143 tons. A single-cell cooling tower on the roof rejects building heat. Chilled water is supplied to air handling unit coils, two-pipe fan coils, and two-pipe unit ventilators to provide comfort cooling in warmer months. The room housing the chiller is not equipped with a refrigeration safety system to safely evacuate refrigerant in the event of a leak. Install an emergency ventilation system activated by a refrigerant leak detection system. This upgrade is necessary to comply with the latest ASHRAE Safety Code for Mechanical Refrigeration.

Code-required ventilation for the Police Department is provided by constant volume, central station air handling units (AHUs) located in the mechanical rooms and ceiling plenums. The air handling units have heating water coils, with some also containing chilled water or DX cooling coils. Perimeter two-pipe fan coils heat and cool the Police Department. Code required ventilation in City Hall and the Seybolt Building is provided by unit ventilators via outdoor air penetrations in the exterior wall. The two-pipe unit ventilators were updated/installed in 1999. Heating and cooling in City Hall and the Seybolt Building is provided through the two-pipe unit ventilators. The building is exhausted with utility set fans in penthouses and attics and powered rooftop ventilators on the flat roofs. The control system is electric with unitary thermostats controlling the fan coils and unit ventilators.

Packaged HVAC units are in place for the Council Chambers and the SERT area. Ducted and ductless split DX units are used for supplemental cooling for Dispatch, the firing range, and the IT server room. Statistically, and by visually evaluation, these systems will require replacement within ten years.

The amount of outdoor air supplied to the building is less than required by modern standards. The equipment is aged, and the building control system is inadequate. The two-pipe changeover system is an outdated design, and the distribution piping is corroded and leaking. It should be anticipated that the majority of the HVAC equipment will need replacement within ten years. It is recommended that the

packaged and split DX systems be removed and that the areas that they serve be included in the central HVAC system.

Electrical

Power is supplied to this facility at 120/208 volts from a utility-owned, oil-filled transformer. Two main distribution switchboards, rated at 2,500 and 1,200 amps, distribute the 120/208 volt power throughout the facility. Although several areas have been updated, the majority of the electrical distribution panels date back to original construction. The switchboards and older electrical panels are aging and should be replaced.

The interior spaces are illuminated by suspended and lay-in fixtures with fluorescent lamps. The ages of the fixtures vary greatly by location. Energy-efficient ballasts and lamps were retrofitted into the fixtures in a building-wide energy efficiency project. The exterior areas adjacent to the building are illuminated by recessed canned lights near the main entrance, wall-mounted HID lights, wall-mounted incandescent lights, a roof-mounted HID light, and pole-mounted fixtures around the walkways. The interior and exterior lighting systems are currently sufficient but will mostly need replacement within ten years.

Standby and continuous emergency power is produced by two diesel-fired emergency generators. They are both approximately 40 kW and generate 120/208 volt power. The Cummins generator dates to the construction of the 1962 portion of the complex, and Onan unit was installed in 1989. There are also two automatic transfer switches (ATS) and emergency distribution panels. The generators and transfer switches are recommended for replacement.

Plumbing

There are backflow preventers on the incoming domestic water and sprinkler mains. Domestic water is distributed throughout this facility via a copper piping network. Sanitary waste and stormwater piping is cast-iron, bell-and-spigot, with partial upgrades to no-hub cast-iron and plastic. Leaks in the water supply piping and connections to the fixtures were reported during the inspection. There is evidence of repaired drain pipe leaks. The older sections of supply and drain piping are recommended for replacement.

The plumbing fixtures vary in age and condition, and many need to be replaced. Domestic hot water service is supplied by a gas-fired, commercial-grade Laars boiler with an insulated storage tank. Both were installed within the past five years. The laundry room and nearby spaces have 50 gallon, electric water heaters. An instantaneous, electric water heater is used for a fourth floor restroom in Seybolt. No upgrade of this water heating equipment is deemed necessary within the next ten years.

Vertical Transportation

Vertical transportation is provided by three traction passenger elevators. The two in the Police Department have five stops and capacities of 6,500 pounds. The one in Seybolt has four stops and a

capacity of 2,500 pounds. The elevator cabs, controllers, hoist motors, cables, floor indicators, and call buttons in the two Police Department elevators were reportedly updated in 2011. Statistically, some components will likely need another update within ten years. A complete, in-depth elevator equipment condition analysis would provide more specific information, based on the analysis of individual components. Such an analysis may indicate that some other of the elevator components should also be modernized.

Note: The deficiencies outlined in this report were noted from a visual inspection. ISES engineers and architects developed projects with related costs that are needed over the next ten-year period to bring the facility to “like-new” condition. The costs developed do not represent the cost of a complete facility renovation. Soft costs not represented in this report include telecommunications, security, furniture, window treatment, space change, program issues, relocation, swing space, contingency, or costs that could not be identified or determined from the visual inspection and available building information. However, existing fixed building components and systems were thoroughly inspected. The developed costs (shown in Sections 3 and 4) represent correcting existing deficiencies and anticipated lifecycle failures (within a ten-year period) to bring the facility to modern standards without any anticipation of change to facility space layout or function.

INSPECTION TEAM DATA

Report Development

ISES Corporation
2165 West Park Court, Suite N
Stone Mountain, GA 30087

Project Manager

Norm Teahan, RA, AIA, NCARB
770.674.3153
normant@isescorp.com

Date of Inspection

January 23, 2014

Inspection Team Personnel

| NAME | POSITION | SPECIALTY |
|-----------------------------|--------------------------|---|
| Mike Sabo | Senior Project Engineer | Mechanical, Electrical, Plumbing, Energy, Fire/Life Safety, Health |
| Norm Teahan, RA, AIA, NCARB | Senior Project Architect | Interior Finishes, Exterior Structure, ADA Compliance, Site, Fire/Life Safety, Health |
| Jerry Watkins | Senior Project Engineer | Interior Finishes, Exterior Structure, ADA Compliance, Site, Fire/Life Safety, Health |

Client Contact

| NAME | POSITION |
|----------------|--|
| Mark Nelson | Director, Division of Parking and Transportation |
| Rick Dolce, PE | Engineering Project Manager |

DEFINITIONS

The following information is a clarification of the Facility Condition Assessment report using example definitions.

Overview

Recurring and Non-Recurring Facility Renewal Costs

Facility renewal costs are divided into two main categories – recurring and non-recurring. Recurring costs are cyclical and consist primarily of major repairs to or replacement/rebuilding of facility systems and components (e.g., roof or HVAC system replacement at or past the end of its normal useful life). The tool for projecting the recurring renewal costs is the Lifecycle Component Inventory, which is explained in detail below. Non-recurring costs typically consist of modifications or repairs necessary to comply with fire/life safety or accessibility code requirements or to address isolated, non-recurring deficiencies that could negatively affect the structure of the facility or the systems and components within. For these non-recurring costs, projects have been developed and include estimated material and labor costs.

Facility Condition Needs Index (FCNI)

The FCNI provides a lifecycle cost comparison. It is a ratio of the sum of the recurring and non-recurring facilities renewal costs over ten years to the current replacement value of the asset. The current replacement value is based on replacement with current construction standards for the facility use type, and not original design parameters. This index gives the city a comparison within all buildings for identifying worst case/best case building conditions.

$$\text{FCNI} = \frac{\text{Non-Recurring Projects} + \text{10-Year Recurring Component Renewal}}{\text{Current Replacement Value}}$$

Facility Condition Index (FCI)

The FCI is a ratio of the Current Needs facilities renewal costs to the current replacement value.

$$\text{FCI} = \frac{\text{Current Needs}}{\text{Current Replacement Value}}$$

Material and Labor Cost Factors and Additional Markups

The project costs are adjusted from the national averages to reflect conditions in the City of Portsmouth, New Hampshire, using the R. S. Means City Cost Index for material and labor cost factors. The percentage adjustment of the national average is shown in the table below. Typical general contractor fees (which could include profit, overhead, bonds, and insurance) and professional fees (architect or engineer design fees and in-house design costs) are also included in the project costs.

| GLOBAL MARKUP | % |
|---------------------------|------|
| Local Labor Index | 94.5 |
| Local Materials Index | 97.3 |
| General Contractor Markup | 20.0 |
| Professional Fees | 16.0 |

Recurring Costs

Asset Component Inventory and Cost Projections

The Asset Component Inventory (starting on page 4.1.1) is based on industry standard lifecycle expectancies applied to an inventory of major building systems and major components within a facility. This is a list of all major systems and components within the facility. Each indicated component has the following associated information:

| CATEGORY | DEFINITION |
|----------------------------|---|
| Uniformat Code | The standard Uniformat Code that applies to the component |
| Component Description | This line item describes the individual component |
| Identifier | Unique identifying information entered for a component as necessary |
| Quantity | The quantity of the listed component |
| Units | The unit of measure associated with the quantity |
| Unit Cost | The cost to replace each individual component unit (this cost is in today's dollars) |
| Complexity Adjustment | A factor utilize to adjust component replacement costs accordingly when it is anticipated that the actual cost will deviate from the average for that component |
| Total Cost | Unit cost multiplied by quantity, in today's dollars. Note that this is a one-time renewal/replacement cost |
| Install Date | Year that the component was or is estimated to have been installed. When this data is not available, it defaults to the year the asset was constructed |
| Life Expectancy | Average life expectancy for each individual component |
| Life Expectancy Adjustment | Utilized to adjust the first lifecycle of the component and to express when the next replacement should occur |

The component listing forms the basis of the Recurring Component Renewal Schedule, which provides a year-by-year list of projected recurring renewal costs over the next ten years. Each individual component is assigned a replacement year based on lifecycles, and the costs for each item are in future year dollars. For items that are already past the end of their lifecycle, the replacement year is shown as Current Needs.

For a longer term perspective, the Recurring Component Expenditure Projections Graph presents recurring renewal cost projections over a 50-year period (starting from the date the report is run) based on each individual item's renewal cost and life span. Some components might require renewal several times within the 50-year model, while others might not occur at all. The vertical bars on the graph represent the accumulated total costs for each individual year. The average annual cost per gross square foot (\$/GSF) is shown at the bottom of the graph. In this calculation, costs are not escalated. This figure can be utilized to assess the adequacy of existing capital renewal and repair budgets.

Recurring Cost Classifications

- **Current Needs**
Recurring repairs, generated by the Lifecycle Component Inventory, that are past due for completion but have not yet been accomplished as part of normal maintenance or capital repair efforts. Further deferral of such renewal could impair the proper functioning of the facility. Costs estimated for Current Needs projects should include compliance with applicable codes, even if such compliance requires expenditures beyond those essential to effect the needed repairs.
- **Recurring Component Replacement**
Recurring renewal efforts, generated by the Lifecycle Component Inventory, that will be due within the scope of the assessment. These projects represent regular or normal facility maintenance, repair, or renovation that should be planned in the near future.

Non-Recurring Costs

As previously mentioned, modifications or repairs necessary to comply with fire/life safety or accessibility code requirements and those that address isolated, non-recurring deficiencies that could negatively affect the structure of the facility or the systems and components within are not included in the Lifecycle Component Inventory. For each such deficiency identified during the facility inspection, a project with an estimated cost to rectify said deficiency is recommended. These projects each have a unique identifier and are categorized by system type, priority, and classification, which are defined below. The costs in these projects are also indexed to local conditions and markups applied as the situation dictates.

Project Number

Each project has a unique number consisting of three elements, the asset identification number, system code, and a sequential number assigned by the FCA software. For example, the third fire/life safety project identified for asset 0001 would have a project number of 0001FS03 (0001 for the asset number, FS for fire/life safety, and 03 being the next sequential number for a fire/life safety project).

Project Classifications

- **Plant/Program Adaption**
Non-recurring expenditures, stored in the Projects module, required to adapt the physical plant to the evolving needs of the institution and to changing codes or standards. These are expenditures beyond normal maintenance. Examples include compliance with changing codes (e.g., accessibility), facility alterations required by changed teaching or research methods, and improvements occasioned by the adoption of modern technology (e.g., the use of personal computer networks).
- **Corrective Action**
Non-recurring expenditures, stored in the Projects module, for repairs needed to correct random and unpredictable deficiencies. Such projects are not related to aligning a building with codes or standards. Deficiencies classified as Corrective Action could have an effect on building aesthetics, safety, or usability.

Priority Classes

Recurring renewal needs do not receive individual prioritization, as the entire data set of needs in this category is year-based. Each separate component has a distinct need year, rendering further prioritization unnecessary. Each non-recurring renewal project, however, has a priority assigned to indicate the criticality of the recommended work. The prioritization utilized for this subset of the data is as follows.

- **Priority 1 – Near Term**
Projects in this category require action within the very near future to:
 - a. correct a cited safety hazard
 - b. stop accelerated deterioration
 - c. and/or return a facility to normal operation

- **Priority 2 – Short Term**

Projects in this category include actions that must be addressed in the short-term:

- a. repairs to prevent further deterioration
- b. improvements to facilities associated with critical accessibility needs
- c. potential safety hazards

- **Priority 3 – Long Term**

Projects in this category include:

- a. improvements to facilities associated with non-critical accessibility needs
- b. actions to bring a facility into compliance with current building codes as grandfather clauses expire
- c. actions to improve the usability of a facility following an occupancy or use change

Category Codes

| CATEGORY CODE* | SYSTEM DESCRIPTION |
|----------------|---------------------------|
| AC1A – AC4B | ACCESSIBILITY |
| EL1A – EL8A | ELECTRICAL |
| ES1A – ES6E | EXTERIOR STRUCTURE |
| FS1A – FS6A | FIRE/LIFE SAFETY |
| HE1A – HE7A | HEALTH |
| HV1A – HV8B | HVAC |
| IS1A – IS6D | INTERIOR FINISHES/SYSTEMS |
| PL1A – PL5A | PLUMBING |
| SI1A – SI4A | SITE |
| SS1A – SS7A | SECURITY SYSTEMS |
| VT1A – VT7A | VERTICAL TRANSPORTATION |

| <i>Example:</i> Category Code = EL5A | |
|---|-----------------------|
| EL | System Description |
| 5 | Component Description |
| A | Element Description |

**Refer to the Category Code Report starting on page 1.6.1.*

Priority Sequence

A Priority Sequence number is automatically assigned to each project to rank the projects in order of relative criticality and show the recommended execution order. This number is calculated based on the Priority Class and identified system of each project.

Example:

| Priority Class | Category Code | Project Number | Priority Sequence |
|----------------|---------------|----------------|-------------------|
| 1 | HV2C | 0001HV04 | 01 |
| 1 | PL1D | 0001PL02 | 02 |
| 2 | IS1E | 0001IS06 | 03 |
| 2 | EL4C | 0001EL03 | 04 |

Project Subclass Type

- **Energy Conservation**
Projects with energy conservation opportunities, based on simple payback analysis.

Drawings/Project Locations

The drawings for this facility are marked with icons (see legend on plans) denoting the specific location(s) for each project. Within each icon are the last four characters of the respective project number (e.g., 0001IS01 is marked on the plan as IS01).

Photographs

A code shown on the Photo Log identifies the asset number, photo sequence, and a letter designation for architect (a) or engineer (e).

| <i>Example:</i> Photo Number: 0001006e | |
|---|-------------------|
| 0001 | Asset Number |
| 006 | Photo Sequence |
| e | Engineering Photo |

CATEGORY CODE REPORT

ACCESSIBILITY

| CODE | COMPONENT DESCRIPTION | ELEMENT DESCRIPTION | DEFINITION |
|------|-------------------------|--------------------------------|---|
| AC1A | Site | Stair and Railings | Includes exterior stairs and railings which are not part of the building entrance points. |
| AC1B | Site | Ramps and Walks | Includes sidewalks, grade change ramps (except for a building entrance), curb ramps, etc. |
| AC1C | Site | Parking | Designated parking spaces, including striping, signage, access aisles and ramps, etc. |
| AC1D | Site | Tactile Warnings | Raised tactile warnings located at traffic crossing and elevation changes. |
| AC2A | Building Entry | General | Covers all aspects of entry into the building itself, including ramps, lifts, doors and hardware, power operators, etc. |
| AC3A | Interior Path of Travel | Lifts/Ramps/Elevators | Interior lifts, ramps and elevators designed to accommodate level changes inside a building. Includes both installation and retrofitting. |
| AC3B | Interior Path of Travel | Stairs and Railings | Upgrades to interior stairs and handrails for accessibility reasons. |
| AC3C | Interior Path of Travel | Doors and Hardware | Accessibility upgrades to the interior doors including widening, replacing hardware power, assisted operators, etc. |
| AC3D | Interior Path of Travel | Signage | Interior building signage upgrades for compliance with THE ADA. |
| AC3E | Interior Path of Travel | Restrooms/Bathrooms | Modifications to and installation of accessible public restrooms and bathrooms. Bathrooms that are an integral part of residential suites are catalogued under HC4A. |
| AC3F | Interior Path of Travel | Drinking Fountains | Upgrading/replacing drinking fountains for reasons of accessibility. |
| AC3G | Interior Path of Travel | Phones | Replacement/modification of public access telephones. |
| AC4A | General | Functional Space Modifications | This category covers all necessary interior modifications necessary to make the services and functions of a building accessible. It includes installation of assistive listening systems, modification of living quarters, modifications to laboratory workstations, etc. Bathrooms that are integral to efficiency suites are catalogued here. |
| AC4B | General | Other | All accessibility issues not catalogued elsewhere. |

ELECTRICAL

| CODE | COMPONENT DESCRIPTION | ELEMENT DESCRIPTION | DEFINITION |
|------|--------------------------|------------------------|--|
| EL1A | Incoming Service | Transformer | Main building service transformer. |
| EL1B | Incoming Service | Disconnects | Main building disconnect and switchgear. |
| EL1C | Incoming Service | Feeders | Incoming service feeders. Complete incoming service upgrades, including transformers, feeders, and main distribution panels are catalogued here. |
| EL1D | Incoming Service | Metering | Installation of meters to record consumption and/or demand. |
| EL2A | Main Distribution Panels | Condition Upgrade | Main distribution upgrade due to deficiencies in condition. |
| EL2B | Main Distribution Panels | Capacity Upgrade | Main distribution upgrades due to inadequate capacity. |
| EL3A | Secondary Distribution | Step-Down Transformers | Secondary distribution step-down and isolation transformers. |
| EL3B | Secondary Distribution | Distribution Network | Includes conduit, conductors, sub-distribution panels, switches, outlets, etc. Complete interior rewiring of a facility is catalogued here. |

| | | | |
|------|------------------------|---------------------------|---|
| EL3C | Secondary Distribution | Motor Controllers | Mechanical equipment motor starters and control centers. |
| EL4A | Devices and Fixtures | Exterior Lighting | Exterior building lighting fixtures, including supply conductors and conduit. |
| EL4B | Devices and Fixtures | Interior Lighting | Interior lighting fixtures (also system wide emergency lighting), including supply conductors and conduits. |
| EL4C | Devices and Fixtures | Lighting Controllers | Motion sensors, photocell controllers, lighting contactors, etc. |
| EL4D | Devices and Fixtures | GFCI Protection | Ground fault protection, including GFCI receptacles and breakers. |
| EL4E | Devices and Fixtures | Lightning Protection | Lightning arrestation systems including air terminals and grounding conductors. |
| EL5A | Emergency Power System | Generation/ Distribution | Includes generators, central battery banks, transfer switches, emergency power grid, etc. |
| EL6A | Systems | UPS/DC Power Supply | Uninterruptible power supply systems and DC motor-generator sets and distribution systems. |
| EL7A | Infrastructure | Above Ground Transmission | Includes poles, towers, conductors, insulators, fuses, disconnects, etc. |
| EL7B | Infrastructure | Underground Transmission | Includes direct buried feeders, ductbanks, conduit, manholes, feeders, switches, disconnects, etc. |
| EL7C | Infrastructure | Substations | Includes incoming feeders, breakers, buses, switchgear, meters, CTs, PTs, battery systems, capacitor banks, and all associated auxiliary equipment. |
| EL7D | Infrastructure | Distribution Switchgear | Stand-alone sectionalizing switches, distribution switchboards, etc. |
| EL7F | Infrastructure | Area and Street Lighting | Area and street lighting systems, including stanchions, fixtures, feeders, etc. |
| EL8A | General | Other | Electrical system components not catalogued elsewhere. |

EXTERIOR STRUCTURE

| CODE | COMPONENT DESCRIPTION | ELEMENT DESCRIPTION | DEFINITION |
|------|-------------------------|-----------------------------|---|
| ES1A | Foundation/ Footing | Structure | Structural foundation improvements involving structural work on foundation wall/footing, piers, caissons, and piles, including crack repairs, shoring, and pointing |
| ES1B | Foundation/ Footing | Dampproofing/ Dewatering | Foundation/footing waterproofing work, including, damp-proofing, dewatering, insulation, etc. |
| ES2A | Columns/Beams/ Walls | Structure | Structural work to primary load-bearing structural components aside from floors, including columns, beams, bearing walls, lintels, arches, etc. |
| ES2B | Columns/Beams/ Walls | Finish | Work involving restoration of the appearance and weatherproof integrity of exterior wall/structural envelope components, including masonry/pointing, expansion joints, efflorescence and stain removal, grouting, surfacing, chimney repairs, etc. |
| ES3A | Floor | Structure | Work concerning the structural integrity of the load supporting floors, both exposed and unexposed, including deformation, delamination, spalling, shoring, crack repair, etc. |
| ES4A | Roof | Repair | Work on waterproof horizontal finish (roof) involving repair and/or limited replacement (<40% total), including membrane patching, flashing repair, coping caulk/resetting, PPT wall parging/coating, walkpad installation, skylight and roof hatch R&R, etc. |
| ES4B | Roof | Replacement | Work involving total refurbishment of roofing system, including related component rehab. |
| ES5A | Fenestrations | Doors | Work on exterior exit/access door, including storefronts, airlocks, air curtains, vinyl slat doors, all power/manual operating hardware (except handicapped), etc. |
| ES5B | Fenestrations | Windows | Work on exterior fenestration closure and related components, including glass/metal/wood curtain walls, fixed or operable window sashes, glazing, frames, sills, casings, stools, seats, coatings, treatments, screens, storm windows, etc. |

| | | | |
|------|---------|--------------------|--|
| ES6A | General | Attached Structure | Work on attached exterior structure components not normally considered in above categories, including porches, stoops, decks, monumental entrance stairs, cupolas, tower, etc. |
| ES6B | General | Areaways | Work on attached grade level or below structural features, including subterranean lightwells, areaways, basement access stairs, etc. |
| ES6C | General | Trim | Work on ornamental exterior (generally non-structural) elements, including beltlines, quoins, porticos, soffits, cornices, moldings, trim, etc. |
| ES6D | General | Superstructure | Finish and structural work on non-standard structures with exposed load-bearing elements, such as stadiums, bag houses, bleachers, freestanding towers, etc. |
| ES6E | General | Other | Any exterior work not specifically categorized elsewhere, including finish and structural work on freestanding boiler stacks. |

| FIRE/LIFE SAFETY | | | |
|------------------|-----------------------|------------------------------|--|
| CODE | COMPONENT DESCRIPTION | ELEMENT DESCRIPTION | DEFINITION |
| FS1A | Lighting | Egress Lighting/Exit Signage | R&R work on exit signage and packaged AC/DC emergency lighting. |
| FS2A | Detection/Alarm | General | Repair or replacement of fire alarm/detection system/components, including alarms, pull boxes, smoke/heat detectors, annunciator panels, central fire control stations, remote dialers, fire station communications, etc. |
| FS3A | Suppression | Sprinklers | Repair or installation of water sprinkler type automatic fire suppressions, including wet-pipe and dry-pipe systems, heads, piping, deflectors, valves, monitors, associated fire pump, etc. |
| FS3B | Suppression | Standpipe/Hose | Repair or installation of standpipe system or components, including hardware, hoses, cabinets, nozzles, necessary fire pumping system, etc. |
| FS3C | Suppression | Extinguishers | Repairs or upgrades to F.E. cabinets/wall fastenings and handheld extinguisher testing/replacement. |
| FS3D | Suppression | Other | Other fire suppression items not specifically categorized elsewhere, including fire blankets, carbon dioxide automatic systems, Halon systems, dry chemical systems, etc. |
| FS4A | Hazardous Materials | Storage Environment | Installation or repair of special storage environment for the safe holding of flammable or otherwise dangerous materials/supplies, including vented flammables storage cabinets, holding pens/rooms, cages, fire safe chemical storage rooms, etc. |
| FS4B | Hazardous Materials | User Safety | Improvements, repairs, installation, or testing of user safety equipment, including emergency eyewashes, safety showers, emergency panic/shut-down system, etc. |
| FS5A | Egress Path | Designation | Installation, relocation or repair of posted diagrammatic emergency evacuation routes. |
| FS5B | Egress Path | Distance/Geometry | Work involving remediation of egress routing problems, including elimination of dead end corridors, excessive egress distance modifications, and egress routing inadequacies. |
| FS5C | Egress Path | Separation Rating | Restoration of required fire protective barriers, including wall rating compromises, fire-rated construction, structural fire proofing, wind/safety glazing, transom retrofitting, etc. |
| FS5D | Egress Path | Obstruction | Clearance of items restricting the required egress routes. |
| FS5E | Egress Path | Stairs Railing | Retrofit of stair/landing configurations/structure, railing heights/geometries, etc. |
| FS5F | Egress Path | Fire Doors/Hardware | Installation/replacement/repair of fire doors and hardware, including labeled fire doors, fire shutters, closers, magnetic holders, panic hardware, etc. |
| FS5G | Egress Path | Finish/Furniture Ratings | Remediation of improper fire/smoke ratings of finishes and furniture along egress routes. |
| FS6A | General | Other | Life/fire safety items not specifically categorized elsewhere. |

| HEALTH | | | |
|--------|-----------------------|--------------------------|--|
| CODE | COMPONENT DESCRIPTION | ELEMENT DESCRIPTION | DEFINITION |
| HE1A | Environmental Control | Equipment and Enclosures | Temperature control chambers (both hot and cold) for non-food storage. Includes both chamber and all associated mechanical equipment. |
| HE1B | Environmental Control | Other | General environmental control problems not catalogued elsewhere. |
| HE2A | Pest Control | General | Includes all measures necessary to control and destroy insects, rodents, and other pests. |
| HE3A | Refuse | General | Issues related to the collection, handling, and disposal of refuse. |
| HE4A | Sanitation Equipment | Laboratory and Process | Includes autoclaves, cage washers, steam cleaners, etc. |
| HE5A | Food Service | Kitchen Equipment | Includes ranges, grilles, cookers, sculleries, etc. |
| HE5B | Food Service | Cold Storage | Includes the cold storage room and all associated refrigeration equipment. |
| HE6A | Hazardous Material | Structural Asbestos | Testing, abatement, and disposal of structural and building finish materials containing asbestos. |
| HE6B | Hazardous Material | Mechanical Asbestos | Testing, abatement, and disposal of mechanical insulation materials containing asbestos. |
| HE6C | Hazardous Material | PCBs | Includes testing, demolition, disposal, and cleanup of PCB contaminated substances. |
| HE6D | Hazardous Material | Fuel Storage | Includes monitoring, removal, and replacement of above and below ground fuel storage and distribution systems. Also includes testing and disposal of contaminated soils. |
| HE6E | Hazardous Material | Lead Paint | Testing, removal, and disposal of lead-based paint systems. |
| HE6F | Hazardous Material | Other | Handling, storage, and disposal of other hazardous materials. |
| HE7A | General | Other | Health related issues not catalogued elsewhere. |

| HVAC | | | |
|------|-----------------------|------------------------------|---|
| CODE | COMPONENT DESCRIPTION | ELEMENT DESCRIPTION | DEFINITION |
| HV1A | Heating | Boilers/Stacks/Controls | Boilers for heating purposes, including their related stacks, flues, and controls. |
| HV1B | Heating | Radiators/Convectors | Including cast-iron radiators, fin tube radiators, baseboard radiators, etc. |
| HV1C | Heating | Furnace | Furnaces and their related controls, flues, etc. |
| HV1D | Heating | Fuel Supply/Storage | Storage and/or distribution of fuel for heating purposes, including tanks and piping networks and related leak detection/monitoring. |
| HV2A | Cooling | Chillers/Controls | Chiller units for production of chilled water for cooling purposes, related controls (not including mods for CFC compliance). |
| HV2B | Cooling | Heat Rejection | Repair/replacement of cooling towers, dry coolers, air-cooling, and heat rejection. Includes connection of once-through system to cooling tower. |
| HV3A | Heating/Cooling | System Retrofit/Replace | Replacement or major retrofit of HVAC systems. |
| HV3B | Heating/Cooling | Water Treatment | Treatment of hot water, chilled water, steam, condenser water, etc. |
| HV3C | Heating/Cooling | Package/Self-Contained Units | Repair/replacement of self-contained/package type units, including stand-up units, rooftop units, window units, etc; both air conditioners and heat pumps. |
| HV3D | Heating/Cooling | Conventional Split Systems | Repair, installation, or replacement of conventional split systems, both air conditioners and heat pumps, including independent component replacements of compressors and condensers. |

| | | | |
|------|--------------------------------|-----------------------------------|---|
| HV4A | Air Moving/ Ventilation | Air Handlers/ Fan Units | Includes air handlers and coils, fan coil units, unit ventilators, filtration upgrades, etc., not including package/self-contained units, split systems, or other specifically categorized systems. |
| HV4B | Air Moving/ Ventilation | Exhaust Fans | Exhaust fan systems, including fans, range and fume hoods, controls, and related ductwork. |
| HV4C | Air Moving/ Ventilation | Other Fans | Supply, return, or any other fans not incorporated into a component categorized elsewhere. |
| HV4D | Air Moving/ Ventilation | Air Distribution Network | Repair, replacement, or cleaning of air distribution network, including ductwork, terminal reheat/cool, VAV units, induction units, power induction units, insulation, dampers, linkages, etc. |
| HV5A | Steam/Hydronic Distribution | Piping Network | Repair/replacement of piping networks for heating and cooling systems, including pipe, fittings, insulation, related components, etc. |
| HV5B | Steam/Hydronic Distribution | Pumps | Repair or replacement of pumps used in heating and cooling systems, related control components, etc. |
| HV5C | Steam/Hydronic Distribution | Heat Exchangers | Including shell-and-tube heat exchangers and plate heat exchangers for heating and cooling. |
| HV6A | Controls | Complete System Upgrade | Replacement of HVAC control systems. |
| HV6B | Controls | Modifications/ Repairs | Repair or modification of HVAC control system. |
| HV6C | Controls | Air Compressors/ Dryers | Repair or modification of control air compressors and dryers. |
| HV7A | Infrastructure | Steam/Hot Water Generation | Generation of central steam and/or hot water, including boilers and related components. |
| HV7B | Infrastructure | Steam/Hot Water Distribution | Distribution system for central hot water and/or steam. |
| HV7C | Infrastructure | Chilled Water Generation | Generation of central chilled water, including chillers and related components. |
| HV7D | Infrastructure | Chilled Water Distribution | Distribution system for central chilled water. |
| HV7E | Infrastructure | Tunnels/ Manholes/ Trenches | Repairs, installation, or replacement of utility system access chambers. |
| HV7F | Infrastructure | Other | HVAC infrastructure issues not specifically categorized elsewhere. |
| HV8A | General | CFC Compliance | Chiller conversions/replacements for CFC regulatory compliance, monitoring, etc. |
| HV8B | General | Other | HVAC issues not catalogued elsewhere. |

INTERIOR FINISHES/SYSTEMS

| CODE | COMPONENT DESCRIPTION | ELEMENT DESCRIPTION | DEFINITION |
|------|-----------------------|---------------------|--|
| IS1A | Floor | Finishes-Dry | R&R of carpet, hardwood strip flooring, concrete coating, vinyl linoleum and tile, marble, terrazzo, rubber flooring, and underlayment in predominantly dry areas ("dry" includes non-commercial kitchens) |
| IS1B | Floor | Finishes-Wet | Flooring finish/underlayment work in predominantly "wet" areas, including work with linoleum, rubber, terrazzo, concrete coating, quarry tile, ceramic tile, epoxy aggregate, etc. |
| IS2A | Partitions | Structure | Structural work on full height permanent interior partitions, including wood/metal stud and drywall systems, CMU systems, structural brick, tile, glass block, etc. |
| IS2B | Partitions | Finishes | Work on full height permanent interior partitions, including R&R, to gypsum board, plaster, lath, wood paneling, acoustical panels, wall coverings, column coverings, tile, paint, etc. |
| IS3A | Ceilings | Repair | Repair of interior ceilings (<40% of total), including tiles, gypsum board, plaster, paint, etc. |
| IS3B | Ceilings | Replacement | Major refurbishments (>40% of total) to interior ceiling systems, including grid system replacements, structural framing, new suspended systems, paint, plastering, etc. |

| | | | |
|------|---------|-----------|---|
| IS4A | Doors | General | Any work on interior non-fire-rated doors, roll-up counter doors, mechanical/plumbing access doors, and all door hardware (except for reasons of access improvement). |
| IS5A | Stairs | Finish | Any finish restorative work to stair tower walking surfaces, including replacement of rubber treads, safety grips, nosings, etc. (except as required to accommodate disabled persons). |
| IS6A | General | Molding | R&R to interior trim/molding systems, including rubber/vinyl/wood base, crown/chair/ornamental moldings, cased openings, etc. |
| IS6B | General | Cabinetry | R&R work to interior casework systems, including cabinets, countertops, wardrobes, lockers, mail boxes, built-in bookcases, lab/work benches, reagent shelving, etc. (except as required for access by the disabled). |
| IS6C | General | Screening | Work on temporary or partial height partitioning systems, including toilet partitions, urinal/vanity screens, etc. |
| IS6D | General | Other | Any work on interior elements not logically or specifically categorized elsewhere, including light coves, phone booths, interior lightwells, etc. |

| PLUMBING | | | |
|----------|-----------------------|--|---|
| CODE | COMPONENT DESCRIPTION | ELEMENT DESCRIPTION | DEFINITION |
| PL1A | Domestic Water | Piping Network | Repair or replacement of domestic water supply piping network, insulation, hangers, etc. |
| PL1B | Domestic Water | Pumps | Domestic water booster pumps, circulating pumps, related controls, etc. |
| PL1C | Domestic Water | Storage/ Treatment | Equipment or vessels for storage or treatment of domestic water. |
| PL1D | Domestic Water | Metering | Installation, repair, or replacement of water meters. |
| PL1E | Domestic Water | Heating | Domestic water heaters, including gas, oil, and electric water heaters, shell-and-tube heat exchangers, tank type, and instantaneous. |
| PL1F | Domestic Water | Cooling | Central systems for cooling and distributing drinking water. |
| PL1G | Domestic Water | Fixtures | Plumbing fixtures, including sinks, drinking fountains, water closets, urinals, etc. |
| PL1H | Domestic Water | Conservation | Alternations made to the water distribution system to conserve water. |
| PL1I | Domestic Water | Backflow Protection | Backflow protection devices, including backflow preventers, vacuum breakers, etc. |
| PL2A | Wastewater | Piping Network | Repair or replacement of building wastewater piping network. |
| PL2B | Wastewater | Pumps | Pump systems used to lift wastewater, including sewage ejectors and other sump systems. |
| PL3A | Special Systems | Process Gas/Fluids | Generation and/or distribution of process steam, compressed air, natural and LP gas, process water, vacuum, etc. |
| PL4A | Infrastructure | Potable Water Storage/ Treatment | Storage and treatment of potable water for distribution. |
| PL4B | Infrastructure | Industrial Water Distribution/ Treatment | Storage and treatment of industrial water for distribution. |
| PL4C | Infrastructure | Sanitary Water Collection | Sanitary water collection systems and sanitary sewer systems, including combined systems. |
| PL4D | Infrastructure | Stormwater Collection | Stormwater collection systems and storm sewer systems; storm water only. |
| PL4E | Infrastructure | Potable Water Distribution | Potable water distribution network. |
| PL4F | Infrastructure | Wastewater Treatment | Wastewater treatment plants, associated equipment, etc. |
| PL5A | General | Other | Plumbing issues not categorized elsewhere. |

| SITE | | | |
|------|-----------------------|---------------------|--|
| CODE | COMPONENT DESCRIPTION | ELEMENT DESCRIPTION | DEFINITION |
| SI1A | Access | Pedestrian | Paved pedestrian surfaces, including walks, site stairs, step ramps, paths, pedestrian signage, sidewalk bridges/canopies, pedestrian plaza/mall areas, etc. |
| SI1B | Access | Vehicular | Paved vehicular surfaces, including roads, paths, curbs, guards, bollards, bridges, skyways, joints, shoulder work, culverts, ditches, vehicular signage, etc. |
| SI2A | Landscape | Grade/Flora | Landscape related work, including new grass/turf refurbishment, grade improvements, catch basins, swales, berms, pruning, new ornamental flora, etc. |
| SI3A | Hardscape | Structure | Permanent hard site features, predominantly ornamental, including terraces, fences, statues, freestanding signage, fountains, benches, etc. |
| SI4A | General | Other | Other site work not specifically categorized elsewhere. |

| SECURITY SYSTEMS | | | |
|------------------|-----------------------|---------------------|---|
| CODE | COMPONENT DESCRIPTION | ELEMENT DESCRIPTION | DEFINITION |
| SS1A | Lighting | Exterior | Fixtures, stanchions, foliage interference, cleanliness, locations, etc. |
| SS2A | Site | Fencing | Perimeter campus fencing, individual building fencing, includes both pedestrian and vehicular control fences. |
| SS2B | Site | General | Hidden areas due to foliage, fencing, parking, walls, etc. |
| SS3A | Communications | Emergency Phones | Access, locations, visibility, function, reliability, etc. |
| SS4A | Access Control | Doors | Access, locks, keys, two-way speakers, reliability, redundancy, etc. |
| SS4B | Access Control | Windows | Locks, screens, access, reliability, etc. |
| SS4C | Access Control | Systems | Card key, proximity devices, data control, data use, reliability, system design, etc. |
| SS5A | Monitoring | Systems | Cameras, audio communication, monitoring stations, locations, system design, etc. |
| SS6A | Circulation | Pedestrian | On campus as well as to and from off-campus housing and class locations, etc. |
| SS6B | Circulation | Vehicular | Guard gates, access, systems, data control and use, identification, etc. |
| SS7A | General | Other | General information/projects pertaining to security issues. |

| VERTICAL TRANSPORTATION | | | |
|-------------------------|-----------------------|---------------------|---|
| CODE | Component Description | Element Description | DEFINITION |
| VT1A | Machine Room | General | Machine, worm gear, thrust bearing, brake, motors, sheaves, generator, controller, selector, governor, pump(s), valves, oil, access, lighting, ventilation, and floor. |
| VT2A | Car | General | Position indicator, lighting, floor, gate-doors, operation devices, safeties, safety shoe, light ray/detection, emergency light, fire fighter service, car top, door operator, stop switch, car frame, car guides, sheaves, phone, and ventilation. |
| VT3A | Hoistway | General | Enclosure, fascia, interlock, doors, hangers, closers, sheaves, rails, hoistway switches, ropes, traveling cables, selector tape, weights, and compensation. |
| VT4A | Hall Fixtures | General | Operating panel, position indicator, hall buttons, lobby panel, hall lanterns, fire fighter service, audible signals, and card/key access. |
| VT5A | Pit | General | Buffer(s), guards, sheaves, hydro packing, floor, lighting, and safety controls. |
| VT6A | Operating Conditions | General | Door open time, door close time, door thrust, acceleration, deceleration, leveling, dwell time, speed, OFR time, and nudging. |
| VT7A | General | Other | General information/projects relating to vertical transportation system components. |

FACILITY CONDITION ASSESSMENT

SECTION 2

FACILITY PLANNING COSTS AND TOTALS

Facility Planning Costs
Facilities Renewal Budget Pro-Forma
0001 : MUNICIPAL COMPLEX

| | Non-Recurring Project Costs | | | Recurring Component Replacement Cost | | | | | | | | | | | | Total |
|------------------|-----------------------------|------------|-----------|--------------------------------------|---------|------|---------|---------|--------|--------|------|---------|-------|---------|--------------|-------|
| | Near-Term | Short-Term | Long-Term | Current Needs | 2015 | 2016 | 2017 | 2018 | 2019 | 2020 | 2021 | 2022 | 2023 | 2024 | | |
| Accessibility | 0 | 1,303,450 | 154,368 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | \$1,457,818 | |
| Exterior | 0 | 0 | 34,054 | 88,580 | 0 | 0 | 288,523 | 28,936 | 0 | 0 | 0 | 0 | 0 | 0 | \$440,093 | |
| Interior | 0 | 0 | 0 | 2,805,619 | 407,354 | 0 | 0 | 578,329 | 0 | 0 | 0 | 0 | 0 | 43,866 | \$3,835,169 | |
| Plumbing | 0 | 0 | 0 | 743,463 | 0 | 0 | 0 | 0 | 0 | 18,180 | 0 | 0 | 0 | 199,780 | \$961,423 | |
| HVAC | 0 | 16,601 | 0 | 3,203,551 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 5,807 | 0 | \$3,225,959 | |
| Fire/Life Safety | 107,065 | 161,992 | 0 | 429,190 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | \$698,247 | |
| Electrical | 0 | 0 | 0 | 2,689,734 | 133,447 | 0 | 0 | 68,604 | 33,488 | 0 | 0 | 0 | 0 | 0 | \$2,925,273 | |
| Site | 0 | 0 | 0 | 0 | 0 | 0 | 4,638 | 0 | 0 | 0 | 0 | 0 | 0 | 4,638 | \$9,276 | |
| Conveying | 0 | 0 | 0 | 706,272 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 159,540 | 0 | 0 | \$865,812 | |
| Equipment | 0 | 0 | 0 | 629,181 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | \$629,181 | |
| | 107,065 | 1,482,042 | 188,422 | 11,295,590 | 540,801 | 0 | 293,161 | 675,869 | 33,488 | 18,180 | 0 | 159,540 | 5,807 | 248,284 | \$15,048,250 | |

| | |
|---|---------------------|
| Non-Recurring Project Cost | \$1,777,530 |
| Recurring Component Replacement Cost | \$13,270,720 |
| Total 10-Year Facility Cost | \$15,048,250 |

| | |
|-------------|---------------------|
| CRV | \$27,623,000 |
| FCNI | 0.54 |
| FCI | 0.41 |

| | |
|------------------------|-----------------|
| Building SqFt. | 92,827 |
| 10-Yr \$ / SqFt | \$162.11 |

All costs shown as Present Value

**Facility Planning Costs
Facilities Renewal Needs by System
0001 : MUNICIPAL COMPLEX**

| | Non-Recurring Project Costs | Recurring Component Replacement Cost | Total 10-Yr. Facility Renewal Costs |
|-------------------------|--|---|--|
| Accessibility | \$1,457,818 | \$0 | \$1,457,818 |
| Exterior | \$34,054 | \$406,039 | \$440,093 |
| Interior | \$0 | \$3,835,169 | \$3,835,169 |
| Plumbing | \$0 | \$961,423 | \$961,423 |
| HVAC | \$16,601 | \$3,209,359 | \$3,225,959 |
| Fire/Life Safety | \$269,057 | \$429,190 | \$698,247 |
| Electrical | \$0 | \$2,925,273 | \$2,925,273 |
| Site | \$0 | \$4,638 | \$4,638 |
| Conveying | \$0 | \$865,812 | \$865,812 |
| Equipment/Other | \$0 | \$629,181 | \$629,181 |
| | \$1,777,530 | \$13,266,082 | \$15,043,612 |

**Facility Planning Costs
Facilities Renewal Plan
0001 : MUNICIPAL COMPLEX**

Non-Recurring Project Costs

| Project Number | Title | Uniformat | Priority Class | Project Classification | Project Cost (Present Val.) |
|----------------|---|-----------|----------------|------------------------|-----------------------------|
| 0001FS02 | ELEVATOR LOBBY CORRECTIONS | C1010 | Near-Term | Plant Adaption | 101,209 |
| 0001FS03 | ELIMINATE FIRE RATING COMPROMISES | C1010 | Near-Term | Plant Adaption | 3,316 |
| 0001FS05 | INSTALL COMPLIANT LADDER WITH SAFETY CAGE | C1010 | Near-Term | Plant Adaption | 2,541 |
| 0001AC06 | STAIR AND RAILING SAFETY UPGRADES | C2020 | Short-Term | Plant Adaption | 254,436 |
| 0001FS04 | REPLACE SOUTH STAIR WITH NEW SECONDARY EGRESS STAIR | C2010 | Short-Term | Plant Adaption | 123,046 |
| 0001FS01 | REPLACE HALON FIRE SUPPRESSION SYSTEM | D4090 | Short-Term | Plant Adaption | 38,945 |
| 0001HV01 | INSTALL REFRIGERATION SAFETY SYSTEMS AND EQUIPMENT | D3030 | Short-Term | Plant Adaption | 16,601 |
| 0001AC01 | INTERIOR PATH OF TRAVEL ACCESSIBILITY UPGRADES | C1010 | Short-Term | Plant Adaption | 111,428 |
| 0001AC03 | INTERIOR DOOR ACCESSIBILITY UPGRADES | C1010 | Short-Term | Plant Adaption | 287,040 |
| 0001AC04 | RESTROOM ACCESSIBILITY UPGRADES | D2010 | Short-Term | Plant Adaption | 465,910 |
| 0001AC05 | LOCKER ROOM ACCESSIBILITY UPGRADES | D2010 | Short-Term | Plant Adaption | 184,637 |
| 0001ES01 | REPAIR TILE ROOF | B3010 | Long-Term | Corrective Action | 34,054 |
| 0001AC02 | INTERIOR AMENITY ACCESSIBILITY UPGRADES | C1010 | Long-Term | Plant Adaption | 154,368 |
| | | | | | 1,777,530 |

Recurring Component Replacement Cost

| Component | Uniformat | Repl. Year | Repl. Cost (Present Val.) |
|--|---------------------|---------------|---------------------------|
| DR12 DOOR AND STOREFRONT, EXTERIOR, SWINGING, ALUMINUM AND GLASS | PD/MAIN ENTRY B2030 | Current Needs | \$13,108 |
| DR30 DOOR OPERATOR, OVERHEAD DOOR, COMMERCIAL, PADS | PD LOAD BAYS B2030 | Current Needs | \$3,670 |
| RR04 ROOF - 1-PLY, IRMA, BALLASTED | 1990 B3010 | Current Needs | \$52,880 |
| RR20 ROOF GUTTER AND LEADER - ALUMINUM OR GALVANIZED, COATED | 1990 B3010 | Current Needs | \$18,922 |
| DR01 DOOR AND FRAME, INTERIOR, NON-RATED | C1020 | Current Needs | \$385,716 |
| DR02 DOOR AND FRAME, INTERIOR, FIRE-RATED | C1020 | Current Needs | \$562,833 |
| DR04 DOOR, SLIDING SYSTEM, INTERIOR | JAIL C1020 | Current Needs | \$193,652 |
| DR24 DOOR LOCK, COMMERCIAL-GRADE | C1020 | Current Needs | \$246,553 |
| DR24 DOOR LOCK, COMMERCIAL-GRADE | C1020 | Current Needs | \$7,890 |
| DR26 DOOR PANIC HARDWARE | PD/MAIN ENTRY C1020 | Current Needs | \$4,166 |

**Facility Planning Costs
Facilities Renewal Plan
0001 : MUNICIPAL COMPLEX**

| | | | | | |
|------|--|-----------------|-------|---------------|-------------|
| DR29 | DOOR ACCESS CONTROL SYSTEM | POLICE DEPT | C1020 | Current Needs | \$39,022 |
| IW03 | WALL FINISH - TILE, CERAMIC / STONE, STANDARD | | C3010 | Current Needs | \$432,666 |
| IW09 | WALL FINISH - WALL COVERING, ROLL | | C3010 | Current Needs | \$242,546 |
| IF01 | FLOORING - CARPET, TILE OR ROLL, STANDARD | | C3020 | Current Needs | \$196,577 |
| IF03 | FLOORING - VINYL COMPOSITION TILE, STANDARD | | C3020 | Current Needs | \$298,994 |
| IF04 | FLOORING - VINYL SHEET, STANDARD | | C3020 | Current Needs | \$40,925 |
| IF06 | FLOORING - TILE, CERAMIC / STONE / QUARRY STANDARD | | C3020 | Current Needs | \$127,260 |
| IC04 | CEILING FINISH - PAINTED OR STAINED, STANDARD | | C3030 | Current Needs | \$26,819 |
| VT01 | ELEVATOR MODERNIZATION - TRACTION - LOW RISE | ELEVATOR A & B | D1010 | Current Needs | \$470,848 |
| VT01 | ELEVATOR MODERNIZATION - TRACTION - LOW RISE | SEYBOLT | D1010 | Current Needs | \$235,424 |
| FX02 | PLUMBING FIXTURE - LAVATORY, WALL HUNG | 1950 | D2010 | Current Needs | \$9,434 |
| FX02 | PLUMBING FIXTURE - LAVATORY, WALL HUNG | 1962 | D2010 | Current Needs | \$5,896 |
| FX04 | PLUMBING FIXTURE - SINK, KITCHEN | 1950 | D2010 | Current Needs | \$1,878 |
| FX04 | PLUMBING FIXTURE - SINK, KITCHEN | 1962 | D2010 | Current Needs | \$5,633 |
| FX06 | PLUMBING FIXTURE - SINK, SERVICE/LAUNDRY/UTILITY | 1950 | D2010 | Current Needs | \$4,709 |
| FX06 | PLUMBING FIXTURE - SINK, SERVICE/LAUNDRY/UTILITY | 1962 | D2010 | Current Needs | \$4,709 |
| FX08 | PLUMBING FIXTURE - SHOWER VALVE AND HEAD | 1962 | D2010 | Current Needs | \$1,528 |
| FX09 | PLUMBING FIXTURE - BATHTUB WITH FIXTURES | 1950 | D2010 | Current Needs | \$5,886 |
| FX12 | PLUMBING FIXTURE - WATER CLOSET, TANKLESS | 1950 | D2010 | Current Needs | \$15,250 |
| FX12 | PLUMBING FIXTURE - WATER CLOSET, TANKLESS | 1962 | D2010 | Current Needs | \$8,472 |
| PS14 | SUPPLY PIPING SYSTEM - OFFICE | 1950 | D2020 | Current Needs | \$91,491 |
| PS14 | SUPPLY PIPING SYSTEM - OFFICE | 1962 | D2020 | Current Needs | \$180,893 |
| PD14 | DRAIN PIPING SYSTEM - OFFICE | 1950 | D2030 | Current Needs | \$136,937 |
| PD14 | DRAIN PIPING SYSTEM - OFFICE | 1962 | D2030 | Current Needs | \$270,748 |
| HU01 | CONDENSER - REFRIGERANT, AIR-COOLED (<=10 TON) | FIRING RANGE | D3030 | Current Needs | \$3,972 |
| HU08 | EVAPORATOR UNIT, NO HEAT (2-3 TON) | IT ROOM | D3030 | Current Needs | \$4,896 |
| FN18 | FAN - CENTRIFUGAL ROOF EXHAUST, 1/4" SP (10"-18" DIAMETER) | ROOF EX-4 | D3040 | Current Needs | \$3,282 |
| FN18 | FAN - CENTRIFUGAL ROOF EXHAUST, 1/4" SP (10"-18" DIAMETER) | ROOF EX-5 | D3040 | Current Needs | \$3,282 |
| FN19 | FAN - CENTRIFUGAL ROOF EXHAUST, 1/4" SP (20"-22" DIAMETER) | COUNCIL CHAMBER | D3040 | Current Needs | \$5,977 |
| FN25 | FAN - PROPELLER WITH LOUVER, 1/4" SP (<=0.5 HP) | RESTROOM | D3040 | Current Needs | \$19,378 |
| FN28 | FAN - PROPELLER WITH LOUVER, 1/4" SP (1.5-2 HP) | SEYBOLT | D3040 | Current Needs | \$3,131 |
| FN33 | FAN - UTILITY SET, 1/4" SP (1.25-4 HP) | EXH FAN 5 | D3040 | Current Needs | \$10,638 |
| HV14 | HVAC DISTRIBUTION NETWORKS - OFFICE | CITY HALL | D3040 | Current Needs | \$1,608,953 |

**Facility Planning Costs
Facilities Renewal Plan
0001 : MUNICIPAL COMPLEX**

| | | | | | |
|------|--|----------------|-------|---------------|-----------|
| HV14 | HVAC DISTRIBUTION NETWORKS - OFFICE | SEYBOLT | D3040 | Current Needs | \$743,735 |
| BA14 | HVAC CONTROLS SYSTEM - OFFICE | CITY HALL | D3060 | Current Needs | \$251,024 |
| BA14 | HVAC CONTROLS SYSTEM - OFFICE | SEYBOLT | D3060 | Current Needs | \$116,035 |
| FA01 | FIRE ALARM PANEL, DIALER, BATTERY, & CHARGER | GENERATOR RM | D4030 | Current Needs | \$35,305 |
| FA02 | FIRE ALARM SYSTEM - DEVICES | CITY HALL | D4030 | Current Needs | \$242,029 |
| FA02 | FIRE ALARM SYSTEM - DEVICES | SEYBOLT | D4030 | Current Needs | \$111,877 |
| SE14 | ELECTRICAL DISTRIBUTION NETWORK - OFFICE | 1950 | D5010 | Current Needs | \$492,218 |
| SE14 | ELECTRICAL DISTRIBUTION NETWORK - OFFICE | 1962 | D5010 | Current Needs | \$973,196 |
| SG04 | MAIN SWITCHBOARD W/BREAKERS (800-1200 AMP) | MDP-2 | D5010 | Current Needs | \$78,519 |
| SG06 | MAIN SWITCHBOARD W/BREAKERS (1600-2500 AMP) | MDP-1 | D5010 | Current Needs | \$183,763 |
| EL01 | EXIT SIGN - CENTRAL POWER | OLD | D5090 | Current Needs | \$15,159 |
| EL04 | EMERGENCY LIGHT - UNITARY WITH BATTERY BACK-UP | OLD | D5090 | Current Needs | \$5,816 |
| GN02 | GENERATOR - DIESEL (<30-100KW) | CUMMINS MARINE | D5090 | Current Needs | \$34,347 |
| CW01 | CASEWORK - WOOD BASE AND WALL, TOP, STANDARD | | E2010 | Current Needs | \$585,632 |
| CW03 | KITCHENETTE UNIT WITH CABINETRY AND AMENITIES | | E2010 | Current Needs | \$43,549 |
| HU01 | CONDENSER - REFRIGERANT, AIR-COOLED (<=10 TON) | FIRING RANGE | D3030 | Current Needs | \$5,958 |
| HU01 | CONDENSER - REFRIGERANT, AIR-COOLED (<=10 TON) | IT ROOM | D3030 | Current Needs | \$5,958 |
| AH02 | AIR HANDLING UNIT - INDOOR (1.25-1.75 HP) | ACS-4 | D3040 | Current Needs | \$12,664 |
| AH02 | AIR HANDLING UNIT - INDOOR (1.25-1.75 HP) | ACS-5 | D3040 | Current Needs | \$12,664 |
| AH03 | AIR HANDLING UNIT - INDOOR (1.75-2.75 HP) | ACS-3 | D3040 | Current Needs | \$16,909 |
| AH03 | AIR HANDLING UNIT - INDOOR (1.75-2.75 HP) | ACS-6 | D3040 | Current Needs | \$16,909 |
| AH03 | AIR HANDLING UNIT - INDOOR (1.75-2.75 HP) | HV-3 | D3040 | Current Needs | \$16,909 |
| AH03 | AIR HANDLING UNIT - INDOOR (1.75-2.75 HP) | PHONE ROOM | D3040 | Current Needs | \$16,909 |
| AH04 | AIR HANDLING UNIT - INDOOR (2.75-3.25 HP) | ACS-7 | D3040 | Current Needs | \$20,676 |
| AH04 | AIR HANDLING UNIT - INDOOR (2.75-3.25 HP) | HOLDING CELLS | D3040 | Current Needs | \$20,676 |
| AH04 | AIR HANDLING UNIT - INDOOR (2.75-3.25 HP) | HV-1 | D3040 | Current Needs | \$20,676 |
| AH05 | AIR HANDLING UNIT - INDOOR (3.25-6 HP) | HV-2 | D3040 | Current Needs | \$36,973 |
| AH18 | AIR HANDLING UNIT - OUTDOOR PACKAGE (5-8 HP) | FIRING RANGE | D3040 | Current Needs | \$106,551 |
| PH01 | PUMP - ELECTRIC (<=10 HP) | P-1 | D3040 | Current Needs | \$11,798 |
| PH01 | PUMP - ELECTRIC (<=10 HP) | P-2 | D3040 | Current Needs | \$11,798 |
| PH01 | PUMP - ELECTRIC (<=10 HP) | P-3 | D3040 | Current Needs | \$11,798 |
| PH01 | PUMP - ELECTRIC (<=10 HP) | SEYBOLT | D3040 | Current Needs | \$2,950 |
| PH01 | PUMP - ELECTRIC (<=10 HP) | SEYBOLT | D3040 | Current Needs | \$2,950 |

**Facility Planning Costs
Facilities Renewal Plan
0001 : MUNICIPAL COMPLEX**

| | | | | | |
|------|---|-----------------|-------|---------------|-----------|
| HU30 | PACKAGE HVAC UNIT, DX, GAS OR ELECTRIC HEAT, SINGLE-ZONE (<= 5 TON) | SERT AHU | D3050 | Current Needs | \$18,575 |
| HU32 | PACKAGE HVAC UNIT, DX, GAS OR ELECTRIC HEAT, SINGLE-ZONE (9-35 TON) | COUNCIL CHAMBER | D3050 | Current Needs | \$58,948 |
| FS02 | FM200 OR INERGEN FIRE SUPPRESSION | 3RD FLOOR IT | D4090 | Current Needs | \$13,326 |
| FS02 | FM200 OR INERGEN FIRE SUPPRESSION | VAULT | D4090 | Current Needs | \$26,653 |
| LE04 | LIGHTING - EXTERIOR, STANCHION LUMINAIRE, 12-FOOT | | D5020 | Current Needs | \$5,830 |
| LE07 | LIGHTING - EXTERIOR, WALL FLOOD (SV, MH, ID, LED) | | D5020 | Current Needs | \$13,887 |
| LE08 | LIGHTING - EXTERIOR, WALL LANTERN or FLOOD (INC, CFL, LED) | | D5020 | Current Needs | \$3,727 |
| LE08 | LIGHTING - EXTERIOR, WALL LANTERN or FLOOD (INC, CFL, LED) | | D5020 | Current Needs | \$414 |
| LI14 | LIGHTING SYSTEM, INTERIOR - OFFICE | 1950 | D5020 | Current Needs | \$291,712 |
| LI14 | LIGHTING SYSTEM, INTERIOR - OFFICE | 1962 | D5020 | Current Needs | \$576,762 |
| GN11 | SWITCH - AUTO TRANSFER, 208 OR 240 V (>100 AMP) | EPG 01 08 | D5090 | Current Needs | \$4,795 |
| GN11 | SWITCH - AUTO TRANSFER, 208 OR 240 V (>100 AMP) | ONAN | D5090 | Current Needs | \$9,590 |
| IW01 | WALL FINISH - PAINT, STANDARD | | C3010 | 2015 | \$394,771 |
| IF15 | FLOORING - FLUID APPLIED, PAINT OR CLEAR SEAL | | C3020 | 2015 | \$12,583 |
| LI14 | LIGHTING SYSTEM, INTERIOR - OFFICE | 1989 | D5020 | 2015 | \$133,447 |
| EW01 | WALL, EXTERIOR, MASONRY POINTING | 1950S BLDG | B2010 | 2017 | \$89,768 |
| EW01 | WALL, EXTERIOR, MASONRY POINTING | 1962 BLDG | B2010 | 2017 | \$105,609 |
| EW01 | WALL, EXTERIOR, MASONRY POINTING | SEYBOLT | B2010 | 2017 | \$54,917 |
| EW12 | WALL, EXTERIOR, PANEL JOINT RESTORATION | PENTHOUSE | B2010 | 2017 | \$38,229 |
| SI06 | ASPHALT VEHICULAR PAVING - SEALCOAT AND STRIPE | | G2020 | 2017 | \$3,413 |
| SI01 | CONCRETE PEDESTRIAN PAVING - JOINT MAINTENANCE | | G2030 | 2017 | \$1,224 |
| DR19 | DOOR, EXTERIOR, OVERHEAD ROLLING METAL, LOCK | PD LOAD BAYS | B2030 | 2018 | \$28,936 |
| IC01 | CEILING FINISH - SUSPENDED ACOUSTICAL TILE, STANDARD | | C3030 | 2018 | \$578,329 |
| UP01 | UNINTERRUPTIBLE POWER SUPPLY - 120/208 VOLTS | EATON 9355 | D5090 | 2018 | \$68,604 |
| GN02 | GENERATOR - DIESEL (<30-100KW) | ONAN | D5090 | 2019 | \$33,488 |
| BF04 | BACKFLOW PREVENTER (3-4 INCHES) | DOMESTIC | D2020 | 2020 | \$7,392 |
| BF05 | BACKFLOW PREVENTER (4-6 INCHES) | SPRINKLER | D2020 | 2020 | \$10,788 |
| VT04 | ELEVATOR CAB RENOVATION - PASSENGER | ELEVATOR A & B | D1010 | 2022 | \$106,360 |
| VT04 | ELEVATOR CAB RENOVATION - PASSENGER | SEYBOLT | D1010 | 2022 | \$53,180 |
| AH46 | HUMIDIFIER, ELECTRIC, POINT-OF-USE | VAPOR LOGIC | D3040 | 2023 | \$5,807 |
| IW01 | WALL FINISH - PAINT, STANDARD | UPPER FLOOR | C3010 | 2024 | \$43,866 |
| FX01 | PLUMBING FIXTURE - LAVATORY, COUNTER | 1989 | D2010 | 2024 | \$3,526 |
| FX02 | PLUMBING FIXTURE - LAVATORY, WALL HUNG | 1989 | D2010 | 2024 | \$27,122 |

**Facility Planning Costs
Facilities Renewal Plan
0001 : MUNICIPAL COMPLEX**

| | | | | | |
|------|---|------|-------|------|---------------------|
| FX04 | PLUMBING FIXTURE - SINK, KITCHEN | 1989 | D2010 | 2024 | \$7,511 |
| FX06 | PLUMBING FIXTURE - SINK, SERVICE/LAUNDRY/UTILITY | 1989 | D2010 | 2024 | \$4,709 |
| FX08 | PLUMBING FIXTURE - SHOWER VALVE AND HEAD | 1989 | D2010 | 2024 | \$10,695 |
| FX10 | PLUMBING FIXTURE - URINAL | 1989 | D2010 | 2024 | \$9,353 |
| FX12 | PLUMBING FIXTURE - WATER CLOSET, TANKLESS | 1989 | D2010 | 2024 | \$44,056 |
| FX13 | PLUMBING FIXTURE - COMBINATION TOILET/SINK, STAINLESS STL, INSTITUTIONAL | 1989 | D2010 | 2024 | \$12,647 |
| PS14 | SUPPLY PIPING SYSTEM - OFFICE | 1989 | D2020 | 2024 | \$80,160 |
| | | | | | \$13,266,082 |

All costs shown as Present Value

Facility Planning Costs
Facility Condition Assessment
Project Classification
0001 : MUNICIPAL COMPLEX

| Cat. Code | Project Number | Priority Sequence | Project Classification | Priority Class | Project Title | Total Cost |
|-------------------------------------|-----------------------|--------------------------|-------------------------------|-----------------------|---|-------------------|
| ES4A | 0001ES01 | 13 | Corrective Action | 3 | REPAIR TILE ROOF | 34,054 |
| Totals for Corrective Action | | | | | | 34,054 |
| FS5C | 0001FS03 | 1 | Plant Adaption | 1 | ELIMINATE FIRE RATING COMPROMISES | 3,316 |
| FS5C | 0001FS02 | 2 | Plant Adaption | 1 | ELEVATOR LOBBY CORRECTIONS | 101,209 |
| FS5E | 0001FS05 | 3 | Plant Adaption | 1 | INSTALL COMPLIANT LADDER WITH SAFETY CAGE | 2,541 |
| FS3D | 0001FS01 | 4 | Plant Adaption | 2 | REPLACE HALON FIRE SUPPRESSION SYSTEM | 38,945 |
| FS5E | 0001FS04 | 5 | Plant Adaption | 2 | REPLACE SOUTH STAIR WITH NEW SECONDARY EGRESS STAIR | 123,046 |
| AC3A | 0001AC01 | 6 | Plant Adaption | 2 | INTERIOR PATH OF TRAVEL ACCESSIBILITY UPGRADES | 111,428 |
| AC3E | 0001AC04 | 7 | Plant Adaption | 2 | RESTROOM ACCESSIBILITY UPGRADES | 465,910 |
| AC3E | 0001AC05 | 8 | Plant Adaption | 2 | LOCKER ROOM ACCESSIBILITY UPGRADES | 184,637 |
| AC3C | 0001AC03 | 9 | Plant Adaption | 2 | INTERIOR DOOR ACCESSIBILITY UPGRADES | 287,040 |
| AC3B | 0001AC06 | 10 | Plant Adaption | 2 | STAIR AND RAILING SAFETY UPGRADES | 254,436 |
| HV8A | 0001HV01 | 11 | Plant Adaption | 2 | INSTALL REFRIGERATION SAFETY SYSTEMS AND EQUIPMENT | 16,601 |
| AC4A | 0001AC02 | 12 | Plant Adaption | 3 | INTERIOR AMENITY ACCESSIBILITY UPGRADES | 154,368 |
| Totals for Plant Adaption | | | | | | 1,743,476 |
| Grand Total: | | | | | | 1,777,530 |

Facility Planning Costs
Facility Condition Assessment
Category/System Code
 0001 : MUNICIPAL COMPLEX

| Cat. Code | Project Number | Pri Cls | Pri Seq | Project Title | Construction Cost | Professional Fee | Total Cost |
|--|----------------|---------|---------|---|-------------------|------------------|------------------|
| AC3A | 0001AC01 | 2 | 6 | INTERIOR PATH OF TRAVEL ACCESSIBILITY UPGRADES | 96,059 | 15,369 | 111,428 |
| AC3E | 0001AC04 | 2 | 7 | RESTROOM ACCESSIBILITY UPGRADES | 401,646 | 64,263 | 465,910 |
| AC3E | 0001AC05 | 2 | 8 | LOCKER ROOM ACCESSIBILITY UPGRADES | 159,170 | 25,467 | 184,637 |
| AC3C | 0001AC03 | 2 | 9 | INTERIOR DOOR ACCESSIBILITY UPGRADES | 247,448 | 39,592 | 287,040 |
| AC3B | 0001AC06 | 2 | 10 | STAIR AND RAILING SAFETY UPGRADES | 219,341 | 35,095 | 254,436 |
| AC4A | 0001AC02 | 3 | 12 | INTERIOR AMENITY ACCESSIBILITY UPGRADES | 133,076 | 21,292 | 154,368 |
| Totals for System Code ACCESSIBILITY | | | | | 1,256,740 | 201,078 | 1,457,818 |
| ES4A | 0001ES01 | 3 | 13 | REPAIR TILE ROOF | 29,357 | 4,697 | 34,054 |
| Totals for System Code EXTERIOR | | | | | 29,357 | 4,697 | 34,054 |
| FS5C | 0001FS03 | 1 | 1 | ELIMINATE FIRE RATING COMPROMISES | 2,859 | 457 | 3,316 |
| FS5C | 0001FS02 | 1 | 2 | ELEVATOR LOBBY CORRECTIONS | 87,249 | 13,960 | 101,209 |
| FS5E | 0001FS05 | 1 | 3 | INSTALL COMPLIANT LADDER WITH SAFETY CAGE | 2,190 | 350 | 2,541 |
| FS3D | 0001FS01 | 2 | 4 | REPLACE HALON FIRE SUPPRESSION SYSTEM | 33,574 | 5,372 | 38,945 |
| FS5E | 0001FS04 | 2 | 5 | REPLACE SOUTH STAIR WITH NEW SECONDARY EGRESS STAIR | 106,074 | 16,972 | 123,046 |
| Totals for System Code FIRE/LIFE SAFETY | | | | | 231,946 | 37,111 | 269,057 |
| HV8A | 0001HV01 | 2 | 11 | INSTALL REFRIGERATION SAFETY SYSTEMS AND EQUIPMENT | 14,311 | 2,290 | 16,601 |
| Totals for System Code HVAC | | | | | 14,311 | 2,290 | 16,601 |
| Grand Total: | | | | | 1,532,353 | 245,176 | 1,777,530 |

FACILITY CONDITION ASSESSMENT

SECTION 3

SPECIFIC PROJECT DETAILS

Specific Project Details
Facility Condition Assessment
Section Three

Project Description

| | | | |
|---------------------------|--------------------------------|-------------------|-----------------------------------|
| Project Number: | 0001FS03 | Title: | ELIMINATE FIRE RATING COMPROMISES |
| Priority Sequence: | 1 | | |
| Priority Class: | 1 | | |
| Category Code: | FS5C | System: | FIRE/LIFE SAFETY |
| | | Component: | EGRESS PATH |
| | | Element: | SEPARATION RATING |
| Building Code: | 0001 | | |
| Building Name: | MUNICIPAL COMPLEX | | |
| Subclass/Savings: | Not Applicable | | |
| Code Application: | IBC | 711.3 | |
| Project Class: | Plant Adaption | | |
| Project Date: | 01/23/2014 | | |
| Project Location: | Floor-wide: Floor(s) 1,2,3,4,B | | |

Project Description

Structural fire separations are not maintained according to code requirements for new construction in many areas of this facility, mainly in the basement level of the complex. Although only these instances were noted, other fire separation compromises may be present. It is recommended that the entire complex be surveyed for similar problem areas, especially in conditions and spaces that are similar to those that were observed. Moderate structural separation repairs and intumescent passive firestopping should be accomplished promptly.

Specific Project Details
Facility Condition Assessment
Section Three

Project Cost

Project Number: 0001FS03

Task Cost Estimate

| Task Description | Unit | Qty | Material Unit Cost | Total Material Cost | Labor Unit Cost | Total Labor Cost | Total Cost |
|---|-------------|------------|---------------------------|----------------------------|------------------------|-------------------------|-------------------|
| Moderate passive firestopping and structural separation repairs | SF | 10,000 | \$0.07 | \$700 | \$0.18 | \$1,800 | \$2,500 |
| Project Totals: | | | | \$700 | | \$1,800 | \$2,500 |

| | | |
|--|---|-----------------------|
| Material/Labor Cost | | \$2,500 |
| Material Index | | 97.30 |
| Labor Index | | 94.50 |
| Material/Labor Indexed Cost | | <u>\$2,382</u> |
| General Contractor Mark Up at 20.0% | + | \$476 |
| Inflation | + | <u>\$0</u> |
| Construction Cost | | <u>\$2,859</u> |
| Professional Fees at 16.0% | + | <u>\$457</u> |
| Total Project Cost | | <u><u>\$3,316</u></u> |

Specific Project Details
Facility Condition Assessment
Section Three

Project Description

| | | | |
|---------------------------|-------------------------------|-------------------|----------------------------|
| Project Number: | 0001FS02 | Title: | ELEVATOR LOBBY CORRECTIONS |
| Priority Sequence: | 2 | | |
| Priority Class: | 1 | | |
| Category Code: | FS5C | System: | FIRE/LIFE SAFETY |
| | | Component: | EGRESS PATH |
| | | Element: | SEPARATION RATING |
| Building Code: | 0001 | | |
| Building Name: | MUNICIPAL COMPLEX | | |
| Subclass/Savings: | Not Applicable | | |
| Code Application: | IBC | 713 | |
| Project Class: | Plant Adaption | | |
| Project Date: | 01/23/2014 | | |
| Project Location: | Area Wide: Floor(s) 1,2,3,4,B | | |

Project Description

The elevator lobbies do not have rated vestibules. The present floor plan arrangement has the elevator lobbies opening into the existing hall corridors. IBC 2000 states that elevators opening into a fire resistant corridor shall be provided with an elevator lobby at each floor containing such a corridor. The lobby should completely separate the elevators from the corridor with rated partitions. Elevator lobbies need to have at least one means of egress and contain smoke detectors. The construction of fire resistant barriers with automatically closing fire doors between the elevator lobbies and the corridors is recommended to provide the required separation and protection.

Specific Project Details
Facility Condition Assessment
Section Three

Project Cost

Project Number: 0001FS02

Task Cost Estimate

| Task Description | Unit | Qty | Material Unit Cost | Total Material Cost | Labor Unit Cost | Total Labor Cost | Total Cost |
|--|-------------|------------|---------------------------|----------------------------|------------------------|-------------------------|-------------------|
| Rated partition, door assembly, panic hardware, holdbacks, closers, and smoke detector (assumes 208 square feet of rated partition per assembly) | SYS | 10 | \$3,666 | \$36,659 | \$3,919 | \$39,194 | \$75,853 |
| Project Totals: | | | | \$36,659 | | \$39,194 | \$75,853 |

| | | |
|--|---|-------------------------|
| Material/Labor Cost | | \$75,853 |
| Material Index | | 97.30 |
| Labor Index | | 94.50 |
| Material/Labor Indexed Cost | | <u>\$72,707</u> |
| General Contractor Mark Up at 20.0% | + | \$14,541 |
| Inflation | + | <u>\$0</u> |
| Construction Cost | | <u>\$87,249</u> |
| Professional Fees at 16.0% | + | <u>\$13,960</u> |
| Total Project Cost | | <u><u>\$101,209</u></u> |

Specific Project Details
Facility Condition Assessment
Section Three

Project Description

| | | | |
|---------------------------|-----------------------|-------------------|---|
| Project Number: | 0001FS05 | Title: | INSTALL COMPLIANT LADDER WITH SAFETY CAGE |
| Priority Sequence: | 3 | | |
| Priority Class: | 1 | | |
| Category Code: | FS5E | System: | FIRE/LIFE SAFETY |
| | | Component: | EGRESS PATH |
| | | Element: | STAIRS AND RAILING |
| Building Code: | 0001 | | |
| Building Name: | MUNICIPAL COMPLEX | | |
| Subclass/Savings: | Not Applicable | | |
| Code Application: | OSHA | 1910.27 | |
| Project Class: | Plant Adaption | | |
| Project Date: | 01/23/2014 | | |
| Project Location: | Item Only: Floor(s) R | | |

Project Description

The vertical access ladder to the mechanical penthouse roof on the 1962 building lacks an OSHA compliant safety cage and platform. For the protection of personnel accessing the penthouse, install a new ladder, cage, and platform.

Specific Project Details
Facility Condition Assessment
Section Three

Project Cost

Project Number: 0001FS05

Task Cost Estimate

| Task Description | Unit | Qty | Material Unit Cost | Total Material Cost | Labor Unit Cost | Total Labor Cost | Total Cost |
|----------------------------------|-------------|------------|---------------------------|----------------------------|------------------------|-------------------------|-------------------|
| Vertical safety ladder with cage | LF | 20 | \$44.59 | \$892 | \$50.66 | \$1,013 | \$1,905 |
| Project Totals: | | | | \$892 | | \$1,013 | \$1,905 |

| | | |
|--|---|-----------------------|
| Material/Labor Cost | | \$1,905 |
| Material Index | | 97.30 |
| Labor Index | | 94.50 |
| Material/Labor Indexed Cost | | <u>\$1,825</u> |
| General Contractor Mark Up at 20.0% | + | \$365 |
| Inflation | + | <u>\$0</u> |
| Construction Cost | | <u>\$2,190</u> |
| Professional Fees at 16.0% | + | <u>\$350</u> |
| Total Project Cost | | <u><u>\$2,541</u></u> |

Specific Project Details
Facility Condition Assessment
Section Three

Project Description

| | | | |
|---------------------------|-------------------------|-------------------|---------------------------------------|
| Project Number: | 0001FS01 | Title: | REPLACE HALON FIRE SUPPRESSION SYSTEM |
| Priority Sequence: | 4 | | |
| Priority Class: | 2 | | |
| Category Code: | FS3D | System: | FIRE/LIFE SAFETY |
| | | Component: | SUPPRESSION |
| | | Element: | OTHER |
| Building Code: | 0001 | | |
| Building Name: | MUNICIPAL COMPLEX | | |
| Subclass/Savings: | Not Applicable | | |
| Code Application: | NFPA | 2001 | |
| Project Class: | Plant Adaption | | |
| Project Date: | 01/23/2014 | | |
| Project Location: | Room Only: Floor(s) 2,3 | | |

Project Description

Halon is no longer being produced in the United States due to environmental concerns. In the event of a discharge, the systems serving the IT and Archives rooms would likely have to be retrofitted or replaced with an approved extinguishing agent. This project provides a budget for replacement with such a system.

Specific Project Details
Facility Condition Assessment
Section Three

Project Cost

Project Number: 0001FS01

Task Cost Estimate

| Task Description | Unit | Qty | Material Unit Cost | Total Material Cost | Labor Unit Cost | Total Labor Cost | Total Cost |
|--|-------------|------------|---------------------------|----------------------------|------------------------|-------------------------|-------------------|
| FM200 or Inergen fire suppression system upgrade | CF | 7,200 | \$2.43 | \$17,496 | \$1.61 | \$11,592 | \$29,088 |
| Project Totals: | | | | \$17,496 | | \$11,592 | \$29,088 |

| | | |
|--|---|------------------------|
| Material/Labor Cost | | \$29,088 |
| Material Index | | 97.30 |
| Labor Index | | 94.50 |
| Material/Labor Indexed Cost | | <u>\$27,978</u> |
| General Contractor Mark Up at 20.0% | + | \$5,596 |
| Inflation | + | <u>\$0</u> |
| Construction Cost | | <u>\$33,574</u> |
| Professional Fees at 16.0% | + | <u>\$5,372</u> |
| Total Project Cost | | <u><u>\$38,945</u></u> |

Specific Project Details
Facility Condition Assessment
Section Three

Project Description

| | | | |
|---------------------------|-------------------------------|-------------------|--|
| Project Number: | 0001FS04 | Title: | REPLACE SOUTH STAIR WITH NEW SECONDARY EGRESS STAIR |
| Priority Sequence: | 5 | | |
| Priority Class: | 2 | | |
| Category Code: | FS5E | System: | FIRE/LIFE SAFETY |
| | | Component: | EGRESS PATH |
| | | Element: | STAIRS AND RAILING |
| Building Code: | 0001 | | |
| Building Name: | MUNICIPAL COMPLEX | | |
| Subclass/Savings: | Not Applicable | | |
| Code Application: | IBC | 1003.3 | |
| Project Class: | Plant Adaption | | |
| Project Date: | 01/23/2014 | | |
| Project Location: | Item Only: Floor(s) 1,2,3,4,B | | |

Project Description

The exterior enclosed emergency egress stair at the south end of the Seybolt Building is constructed of metal grating treads, has non-compliant handrails and guardrails, and is aging, with significant corrosion to welded joints and structural elements. Due to the extent of the compliance issues with this stair, along with its structural condition, it needs to be replaced with a compliant stairwell or stairway.

Specific Project Details
Facility Condition Assessment
Section Three

Project Cost

Project Number: 0001FS04

Task Cost Estimate

| Task Description | Unit | Qty | Material Unit Cost | Total Material Cost | Labor Unit Cost | Total Labor Cost | Total Cost |
|--|-------------|------------|---------------------------|----------------------------|------------------------|-------------------------|-------------------|
| Cement fill, metal pan egress stair with handrail, guardrail, and landings | FLR | 4 | \$16,700 | \$66,802 | \$6,190 | \$24,759 | \$91,561 |
| Project Totals: | | | | \$66,802 | | \$24,759 | \$91,561 |

| | | |
|--|---|-------------------------|
| Material/Labor Cost | | \$91,561 |
| Material Index | | 97.30 |
| Labor Index | | 94.50 |
| Material/Labor Indexed Cost | | <u>\$88,395</u> |
| General Contractor Mark Up at 20.0% | + | \$17,679 |
| Inflation | + | <u>\$0</u> |
| Construction Cost | | <u>\$106,074</u> |
| Professional Fees at 16.0% | + | <u>\$16,972</u> |
| Total Project Cost | | <u><u>\$123,046</u></u> |

Specific Project Details
Facility Condition Assessment
Section Three

Project Description

| | | | |
|---------------------------|--------------------------------|--------------------|---|
| Project Number: | 0001AC01 | Title: | INTERIOR PATH OF TRAVEL ACCESSIBILITY UPGRADES |
| Priority Sequence: | 6 | | |
| Priority Class: | 2 | | |
| Category Code: | AC3A | System: | ACCESSIBILITY |
| | | Component: | INTERIOR PATH OF TRAVEL |
| | | Element: | LIFTS/RAMPS/ELEVATORS |
| Building Code: | 0001 | | |
| Building Name: | MUNICIPAL COMPLEX | | |
| Subclass/Savings: | Not Applicable | | |
| Code Application: | ADAAG | 410, 405, 505, 407 | |
| Project Class: | Plant Adaption | | |
| Project Date: | 01/23/2014 | | |
| Project Location: | Floor-wide: Floor(s) 1,2,3,4,B | | |

Project Description

ADA legislation requires that goods and services offered in buildings be generally accessible to all persons. In multiple locations throughout the complex, elevation changes in the corridors are not easily navigable by someone in a wheelchair. It is recommended that a ramp with associated ADA compliant, painted metal handrails, or superior finish (where necessary), be installed at all such locations. Also install a wheelchair lift or stair climber at the entry to the Seybolt Building west lower level vestibule. The Seybolt Building elevator control systems lack accessible features. It is recommended that the controls be upgraded with a package consisting of a hands-free, two-way telephone, Braille signage, and audible signals. Steps and sloped floors throughout the complex do not have compliant handrails. It is recommended that all handrails be modified or replaced.

Specific Project Details
Facility Condition Assessment
Section Three

Project Cost

Project Number: 0001AC01

Task Cost Estimate

| Task Description | Unit | Qty | Material Unit Cost | Total Material Cost | Labor Unit Cost | Total Labor Cost | Total Cost |
|---|-------------|------------|---------------------------|----------------------------|------------------------|-------------------------|-------------------|
| Wheelchair ramp construction, including handrails | VFT | 4 | \$2,242 | \$8,969 | \$1,985 | \$7,941 | \$16,911 |
| Elevator accessibility package | EA | 1 | \$5,197 | \$5,197 | \$3,363 | \$3,363 | \$8,560 |
| Wall-mounted handrail system, painted | LF | 600 | \$56.65 | \$33,990 | \$39.70 | \$23,820 | \$57,810 |
| Project Totals: | | | | \$48,156 | | \$35,125 | \$83,281 |

| | | |
|--|---|-------------------------|
| Material/Labor Cost | | \$83,281 |
| Material Index | | 97.30 |
| Labor Index | | 94.50 |
| Material/Labor Indexed Cost | | <u>\$80,049</u> |
| General Contractor Mark Up at 20.0% | + | \$16,010 |
| Inflation | + | <u>\$0</u> |
| Construction Cost | | <u>\$96,059</u> |
| Professional Fees at 16.0% | + | <u>\$15,369</u> |
| Total Project Cost | | <u><u>\$111,428</u></u> |

Specific Project Details
Facility Condition Assessment
Section Three

Project Description

| | | | |
|---------------------------|-------------------------------|--------------------|---------------------------------|
| Project Number: | 0001AC04 | Title: | RESTROOM ACCESSIBILITY UPGRADES |
| Priority Sequence: | 7 | | |
| Priority Class: | 2 | | |
| Category Code: | AC3E | System: | ACCESSIBILITY |
| | | Component: | INTERIOR PATH OF TRAVEL |
| | | Element: | RESTROOMS/BATHROOMS |
| Building Code: | 0001 | | |
| Building Name: | MUNICIPAL COMPLEX | | |
| Subclass/Savings: | Not Applicable | | |
| Code Application: | ADAAG | 604, 605, 606, 608 | |
| Project Class: | Plant Adaption | | |
| Project Date: | 01/23/2014 | | |
| Project Location: | Room Only: Floor(s) 1,2,3,4,B | | |

Project Description

The restrooms throughout the complex are not fully compliant with ADA requirements. All restrooms should be properly equipped with handicapped accessible fixtures and accessories and have wheelchair accessible layouts. This would include new grab bars, water closets, urinals, lavatories, and mirrors.

Specific Project Details
Facility Condition Assessment
Section Three

Project Cost

Project Number: 0001AC04

Task Cost Estimate

| Task Description | Unit | Qty | Material Unit Cost | Total Material Cost | Labor Unit Cost | Total Labor Cost | Total Cost |
|--|-------------|------------|---------------------------|----------------------------|------------------------|-------------------------|-------------------|
| Grab bars (per stall) | SYS | 50 | \$159 | \$7,941 | \$374 | \$18,686 | \$26,627 |
| Mirror | EA | 40 | \$327 | \$13,080 | \$251 | \$10,044 | \$23,124 |
| ADA compliant signage | EA | 40 | \$59.56 | \$2,382 | \$17.52 | \$701 | \$3,083 |
| ADA compliant lavatory | EA | 40 | \$689 | \$27,577 | \$257 | \$10,267 | \$37,844 |
| ADA compliant toilet | EA | 48 | \$1,083 | \$51,984 | \$286 | \$13,737 | \$65,722 |
| High density polymer toilet partition modification | EA | 48 | \$1,810 | \$86,889 | \$1,121 | \$53,815 | \$140,704 |
| Roll-in shower | EA | 6 | \$3,679 | \$22,073 | \$4,788 | \$28,729 | \$50,802 |
| Project Totals: | | | | \$211,927 | | \$135,979 | \$347,906 |

| | | |
|--|---|--------------------------------|
| Material/Labor Cost | | \$347,906 |
| Material Index | | 97.30 |
| Labor Index | | 94.50 |
| Material/Labor Indexed Cost | | <u>\$334,705</u> |
| General Contractor Mark Up at 20.0% | + | \$66,941 |
| Inflation | + | <u>\$0</u> |
| Construction Cost | | <u>\$401,646</u> |
| Professional Fees at 16.0% | + | <u>\$64,263</u> |
| Total Project Cost | | <u><u>\$465,910</u></u> |

Specific Project Details
Facility Condition Assessment
Section Three

Project Description

| | | | |
|---------------------------|-----------------------|--------------------|---------------------------------------|
| Project Number: | 0001AC05 | Title: | LOCKER ROOM ACCESSIBILITY UPGRADES |
| Priority Sequence: | 8 | | |
| Priority Class: | 2 | | |
| Category Code: | AC3E | System: | ACCESSIBILITY |
| | | Component: | INTERIOR PATH OF TRAVEL |
| | | Element: | RESTROOMS/BATHROOMS |
| Building Code: | 0001 | | |
| Building Name: | MUNICIPAL COMPLEX | | |
| Subclass/Savings: | Not Applicable | | |
| Code Application: | ADAAG | 604, 605, 606, 608 | |
| Project Class: | Plant Adaption | | |
| Project Date: | 01/23/2014 | | |
| Project Location: | Room Only: Floor(s) B | | |

Project Description

The locker rooms in the basement level of the Police Department building are not fully accessible. Modifications to the restrooms, showers, and dressing facilities are recommended.

Specific Project Details
Facility Condition Assessment
Section Three

Project Cost

Project Number: 0001AC05

Task Cost Estimate

| Task Description | Unit | Qty | Material Unit Cost | Total Material Cost | Labor Unit Cost | Total Labor Cost | Total Cost |
|--|-------------|------------|---------------------------|----------------------------|------------------------|-------------------------|-------------------|
| Grab bars (per stall) | SYS | 12 | \$159 | \$1,906 | \$374 | \$4,485 | \$6,390 |
| Mirror | EA | 8 | \$327 | \$2,616 | \$251 | \$2,009 | \$4,625 |
| ADA compliant signage | EA | 3 | \$59.56 | \$179 | \$17.52 | \$53 | \$231 |
| ADA compliant lavatory | EA | 8 | \$689 | \$5,515 | \$257 | \$2,053 | \$7,569 |
| ADA compliant toilet | EA | 12 | \$1,083 | \$12,996 | \$286 | \$3,434 | \$16,430 |
| High density polymer toilet partition modification | EA | 12 | \$1,810 | \$21,722 | \$1,121 | \$13,454 | \$35,176 |
| Roll-in shower | EA | 8 | \$3,679 | \$29,430 | \$4,788 | \$38,306 | \$67,736 |
| Project Totals: | | | | \$74,365 | | \$63,793 | \$138,158 |

| | | |
|--|---|-------------------------|
| Material/Labor Cost | | \$138,158 |
| Material Index | | 97.30 |
| Labor Index | | 94.50 |
| Material/Labor Indexed Cost | | <u>\$132,641</u> |
| General Contractor Mark Up at 20.0% | + | \$26,528 |
| Inflation | + | <u>\$0</u> |
| Construction Cost | | <u>\$159,170</u> |
| Professional Fees at 16.0% | + | <u>\$25,467</u> |
| Total Project Cost | | <u><u>\$184,637</u></u> |

Specific Project Details
Facility Condition Assessment
Section Three

Project Description

| | | | |
|---------------------------|--------------------------------|-------------------|---|
| Project Number: | 0001AC03 | Title: | INTERIOR DOOR ACCESSIBILITY UPGRADES |
| Priority Sequence: | 9 | | |
| Priority Class: | 2 | | |
| Category Code: | AC3C | System: | ACCESSIBILITY |
| | | Component: | INTERIOR PATH OF TRAVEL |
| | | Element: | DOORS AND HARDWARE |
| Building Code: | 0001 | | |
| Building Name: | MUNICIPAL COMPLEX | | |
| Subclass/Savings: | Not Applicable | | |
| Code Application: | ADAAG | 309.4, 703.1 | |
| Project Class: | Plant Adaption | | |
| Project Date: | 01/23/2014 | | |
| Project Location: | Floor-wide: Floor(s) 1,2,3,4,B | | |

Project Description

The interior doors throughout the complex are in need of replacement. Should the replacement of the doors be delayed, the knob actuated hardware should be replaced. Accessibility legislation requires that door hardware be designed for operation by people with little or no ability to grasp objects with their hands. To comply with the intent of this legislation, it is recommended that lever handle hardware be installed on all doors that still have knobs. In addition, signage to the permanent spaces is not ADA compliant. It is recommended that all non-compliant room and directional signage be upgraded to conform to the appropriate accessibility standards. Compliant signage should meet specific size, graphical, Braille, height, and location requirements.

Specific Project Details
Facility Condition Assessment
Section Three

Project Cost

Project Number: 0001AC03

Task Cost Estimate

| Task Description | Unit | Qty | Material Unit Cost | Total Material Cost | Labor Unit Cost | Total Labor Cost | Total Cost |
|------------------------------|-------------|------------|---------------------------|----------------------------|------------------------|-------------------------|-------------------|
| ADA compliant signage | EA | 450 | \$59.56 | \$26,802 | \$17.52 | \$7,884 | \$34,686 |
| Lever actuated door hardware | EA | 375 | \$341 | \$127,763 | \$136 | \$51,180 | \$178,943 |
| Project Totals: | | | | \$154,565 | | \$59,064 | \$213,629 |

| | | |
|--|---|-------------------------|
| Material/Labor Cost | | \$213,629 |
| Material Index | | 97.30 |
| Labor Index | | 94.50 |
| Material/Labor Indexed Cost | | <u>\$206,207</u> |
| General Contractor Mark Up at 20.0% | + | \$41,241 |
| Inflation | + | <u>\$0</u> |
| Construction Cost | | <u>\$247,448</u> |
| Professional Fees at 16.0% | + | <u>\$39,592</u> |
| Total Project Cost | | <u><u>\$287,040</u></u> |

Specific Project Details
Facility Condition Assessment
Section Three

Project Description

| | | | |
|---------------------------|--------------------------------|-------------------|-----------------------------------|
| Project Number: | 0001AC06 | Title: | STAIR AND RAILING SAFETY UPGRADES |
| Priority Sequence: | 10 | | |
| Priority Class: | 2 | | |
| Category Code: | AC3B | System: | ACCESSIBILITY |
| | | Component: | INTERIOR PATH OF TRAVEL |
| | | Element: | STAIRS AND RAILINGS |
| Building Code: | 0001 | | |
| Building Name: | MUNICIPAL COMPLEX | | |
| Subclass/Savings: | Not Applicable | | |
| Code Application: | IBC | 1003.3 | |
| | ADAAG | 505 | |
| Project Class: | Plant Adaption | | |
| Project Date: | 01/23/2014 | | |
| Project Location: | Floor-wide: Floor(s) 1,2,3,4,B | | |

Project Description

Current accessibility legislation requires that stairs have graspable handrails on both sides, that the rails have a specific end geometry, and that the handrails continue horizontally at the landings. In addition, guardrails must prevent the passage of a 4 inch diameter sphere (6 inches in the triangle formed by the lower rail and tread/riser angle). Although the stairs are compliant with the code enforced at the time of construction until a major renovation occurs, they are deficient in handrail and guardrail design relative to current standards. Also, elevated surfaces at multiple locations around the building exterior have missing or inadequate guardrails. Future renovation efforts should include comprehensive railing upgrades.

Specific Project Details
Facility Condition Assessment
Section Three

Project Cost

Project Number: 0001AC06

Task Cost Estimate

| Task Description | Unit | Qty | Material Unit Cost | Total Material Cost | Labor Unit Cost | Total Labor Cost | Total Cost |
|--|-------------|------------|---------------------------|----------------------------|------------------------|-------------------------|-------------------|
| Wall-mounted handrail system per floor | FLR | 19 | \$642 | \$12,204 | \$584 | \$11,095 | \$23,299 |
| Switchback handrail/guardrail system per floor | FLR | 19 | \$1,455 | \$27,648 | \$934 | \$17,752 | \$45,400 |
| Railing system up to 42 inches high with pickets at 4 1/2 inches on center | LF | 750 | \$120 | \$90,218 | \$40.87 | \$30,653 | \$120,870 |
| Project Totals: | | | | \$130,070 | | \$59,499 | \$189,568 |

| | | |
|--|---|-------------------------|
| Material/Labor Cost | | \$189,568 |
| Material Index | | 97.30 |
| Labor Index | | 94.50 |
| Material/Labor Indexed Cost | | <u>\$182,784</u> |
| General Contractor Mark Up at 20.0% | + | \$36,557 |
| Inflation | + | <u>\$0</u> |
| Construction Cost | | <u>\$219,341</u> |
| Professional Fees at 16.0% | + | <u>\$35,095</u> |
| Total Project Cost | | <u><u>\$254,436</u></u> |

Specific Project Details
Facility Condition Assessment
Section Three

Project Description

| | | | |
|---------------------------|-----------------------|-------------------|--|
| Project Number: | 0001HV01 | Title: | INSTALL REFRIGERATION SAFETY SYSTEMS AND EQUIPMENT |
| Priority Sequence: | 11 | | |
| Priority Class: | 2 | | |
| Category Code: | HV8A | System: | HVAC |
| | | Component: | GENERAL |
| | | Element: | CFC COMPLIANCE |
| Building Code: | 0001 | | |
| Building Name: | MUNICIPAL COMPLEX | | |
| Subclass/Savings: | Not Applicable | | |
| Code Application: | Not Applicable | | |
| Project Class: | Plant Adaption | | |
| Project Date: | 01/23/2014 | | |
| Project Location: | Room Only: Floor(s) B | | |

Project Description

The room housing the chiller is not equipped with a refrigeration safety system to safely evacuate refrigerant in the event of a leak. Install an emergency ventilation system activated by a refrigerant leak detection system. This upgrade is necessary to comply with the latest ASHRAE Safety Code for Mechanical Refrigeration.

Specific Project Details
Facility Condition Assessment
Section Three

Project Cost

Project Number: 0001HV01

Task Cost Estimate

| Task Description | Unit | Qty | Material Unit Cost | Total Material Cost | Labor Unit Cost | Total Labor Cost | Total Cost |
|--|-------------|------------|---------------------------|----------------------------|------------------------|-------------------------|-------------------|
| Exhaust system, refrigerant leak detection and monitoring system, cut and patch (>100<=150 tons) | SYS | 1 | \$5,322 | \$5,322 | \$7,140 | \$7,140 | \$12,462 |
| Project Totals: | | | | \$5,322 | | \$7,140 | \$12,462 |

| | | |
|--|---|------------------------|
| Material/Labor Cost | | \$12,462 |
| Material Index | | 97.30 |
| Labor Index | | 94.50 |
| Material/Labor Indexed Cost | | <u>\$11,926</u> |
| General Contractor Mark Up at 20.0% | + | \$2,385 |
| Inflation | + | <u>\$0</u> |
| Construction Cost | | <u>\$14,311</u> |
| Professional Fees at 16.0% | + | <u>\$2,290</u> |
| Total Project Cost | | <u><u>\$16,601</u></u> |

Specific Project Details
Facility Condition Assessment
Section Three

Project Description

| | | | |
|---------------------------|--------------------------------|-------------------|--|
| Project Number: | 0001AC02 | Title: | INTERIOR AMENITY ACCESSIBILITY UPGRADES |
| Priority Sequence: | 12 | | |
| Priority Class: | 3 | | |
| Category Code: | AC4A | System: | ACCESSIBILITY |
| | | Component: | GENERAL |
| | | Element: | FUNCTIONAL SPACE MOD. |
| Building Code: | 0001 | | |
| Building Name: | MUNICIPAL COMPLEX | | |
| Subclass/Savings: | Not Applicable | | |
| Code Application: | ADAAG | 211, 602, 804 | |
| Project Class: | Plant Adaption | | |
| Project Date: | 01/23/2014 | | |
| Project Location: | Floor-wide: Floor(s) 1,2,3,4,B | | |

Project Description

Current legislation requires that building amenities be generally accessible to all persons. The configuration of the kitchenette cabinetry, service counters, and drinking fountains is a barrier to accessibility. Install wheelchair accessible kitchenette cabinetry, and a wheelchair accessible section should be incorporated into each non-compliant service counter. Also replace all single level drinking fountains with dual level, refrigerated units.

Specific Project Details
Facility Condition Assessment
Section Three

Project Cost

Project Number: 0001AC02

Task Cost Estimate

| Task Description | Unit | Qty | Material Unit Cost | Total Material Cost | Labor Unit Cost | Total Labor Cost | Total Cost |
|---|-------------|------------|---------------------------|----------------------------|------------------------|-------------------------|-------------------|
| ADA compliant kitchenette unit with base cabinetry, overhead cabinetry, and amenities | EA | 3 | \$5,849 | \$17,548 | \$2,046 | \$6,139 | \$23,687 |
| Dual level drinking fountain | EA | 15 | \$1,364 | \$20,461 | \$419 | \$6,289 | \$26,750 |
| Alcove construction for drinking fountain | EA | 10 | \$983 | \$9,834 | \$4,197 | \$41,973 | \$51,807 |
| ADA compliant service counter | LF | 50 | \$175 | \$8,759 | \$93.43 | \$4,672 | \$13,431 |
| Project Totals: | | | | \$56,602 | | \$59,072 | \$115,674 |

| | | |
|--|---|-------------------------|
| Material/Labor Cost | | \$115,674 |
| Material Index | | 97.30 |
| Labor Index | | 94.50 |
| Material/Labor Indexed Cost | | <u>\$110,896</u> |
| General Contractor Mark Up at 20.0% | + | \$22,179 |
| Inflation | + | <u>\$0</u> |
| Construction Cost | | <u>\$133,076</u> |
| Professional Fees at 16.0% | + | <u>\$21,292</u> |
| Total Project Cost | | <u><u>\$154,368</u></u> |

Specific Project Details
Facility Condition Assessment
Section Three

Project Description

| | | | |
|---------------------------|------------------------|-------------------|------------------|
| Project Number: | 0001ES01 | Title: | REPAIR TILE ROOF |
| Priority Sequence: | 13 | | |
| Priority Class: | 3 | | |
| Category Code: | ES4A | System: | EXTERIOR |
| | | Component: | ROOF |
| | | Element: | REPAIR |
| Building Code: | 0001 | | |
| Building Name: | MUNICIPAL COMPLEX | | |
| Subclass/Savings: | Not Applicable | | |
| Code Application: | Not Applicable | | |
| Project Class: | Corrective Action | | |
| Project Date: | 01/23/2014 | | |
| Project Location: | Floor-wide: Floor(s) R | | |

Project Description

Minor repairs, including the replacement of broken tiles, are needed on the 1929 and 1950s buildings roofs.

Specific Project Details
Facility Condition Assessment
Section Three

Project Cost

Project Number: 0001ES01

Task Cost Estimate

| Task Description | Unit | Qty | Material Unit Cost | Total Material Cost | Labor Unit Cost | Total Labor Cost | Total Cost |
|-----------------------------------|-------------|------------|---------------------------|----------------------------|------------------------|-------------------------|-------------------|
| Slate or similar tile roof system | SF | 1,000 | \$10.40 | \$10,400 | \$15.18 | \$15,180 | \$25,580 |
| Project Totals: | | | | \$10,400 | | \$15,180 | \$25,580 |

| | | |
|--|---|------------------------|
| Material/Labor Cost | | \$25,580 |
| Material Index | | 97.30 |
| Labor Index | | 94.50 |
| Material/Labor Indexed Cost | | <u>\$24,464</u> |
| General Contractor Mark Up at 20.0% | + | \$4,893 |
| Inflation | + | <u>\$0</u> |
| Construction Cost | | <u>\$29,357</u> |
| Professional Fees at 16.0% | + | <u>\$4,697</u> |
| Total Project Cost | | <u><u>\$34,054</u></u> |

FACILITY CONDITION ASSESSMENT

SECTION 4

LIFECYCLE COMPONENT INVENTORY

Asset Component Inventory
0001 : MUNICIPAL COMPLEX

| Uni-format | Component Description | Identifier | Qty | Units | Unit Cost | Cmplx Adj | Total Cost | Install Date | Life Exp | Lf Adj |
|------------|---|---------------|--------|-------|-------------|-----------|------------|--------------|----------|--------|
| B2010 | WALL, EXTERIOR, MASONRY POINTING | 1962 BLDG | 10,000 | SF | \$8.32 | 1.27 | \$105,609 | 1962 | 30 | 25 |
| B2010 | WALL, EXTERIOR, MASONRY POINTING | 1950S BLDG | 8,500 | SF | \$8.32 | 1.27 | \$89,768 | 1955 | 30 | 32 |
| B2010 | WALL, EXTERIOR, MASONRY POINTING | SEYBOLT | 5,200 | SF | \$8.32 | 1.27 | \$54,917 | 1929 | 30 | 58 |
| B2010 | WALL, EXTERIOR, PANEL JOINT RESTORATION | PENTHOUSE | 1,650 | SF | \$18.24 | 1.27 | \$38,229 | 1962 | 25 | 30 |
| B2010 | GLASS, WINDOW, ALUMINUM OR WOOD, STANDARD | | 4,850 | SF | \$140.32 | | \$680,566 | 2012 | 40 | |
| B2030 | DOOR AND FRAME, EXTERIOR, SWINGING, HOLLOW METAL | | 12 | LEAF | \$1,757.54 | | \$21,090 | 1988 | 40 | |
| B2030 | DOOR AND STOREFRONT, EXTERIOR, SWINGING, ALUMINUM AND GLASS | PD/MAIN ENTRY | 4 | LEAF | \$3,276.88 | | \$13,108 | 1988 | 25 | |
| B2030 | DOOR, EXTERIOR, OVERHEAD ROLLING METAL, LOCK | PD LOAD BAYS | 320 | SF | \$90.42 | | \$28,936 | 1988 | 30 | |
| B2030 | DOOR OPERATOR, OVERHEAD DOOR, COMMERCIAL, PADS | PD LOAD BAYS | 2 | EA | \$1,835.15 | | \$3,670 | 1988 | 15 | 10 |
| B3010 | ROOF - 1-PLY, ADHERED (EPDM, PIB, CSPE, PVC) | 2012 ADDITION | 2,800 | SF | \$6.22 | | \$17,423 | 2012 | 20 | |
| B3010 | ROOF - 1-PLY, IRMA, BALLASTED | 1990 | 5,600 | SF | \$9.44 | | \$52,880 | 1990 | 20 | 3 |
| B3010 | ROOF - 1-PLY, IRMA, BALLASTED | 2009 | 8,400 | SF | \$9.44 | | \$79,319 | 2009 | 20 | |
| B3010 | ROOF - TILE, SLATE OR SIMILAR | | 11,200 | SF | \$34.92 | | \$391,111 | 1955 | 70 | |
| B3010 | ROOF GUTTER AND LEADER - ALUMINUM OR GALVANIZED, COATED | 1990 | 1,150 | LF | \$16.45 | | \$18,922 | 1990 | 20 | 3 |
| B3010 | ROOF GUTTER AND LEADER - ALUMINUM OR GALVANIZED, COATED | 2009 | 1,410 | LF | \$16.45 | | \$23,200 | 2009 | 20 | |
| B3010 | ROOF GUTTER AND LEADER - ALUMINUM OR GALVANIZED, COATED | 2012 ADDITION | 810 | LF | \$16.45 | | \$13,328 | 2012 | 20 | |
| B3010 | ROOF GUTTER AND LEADER - COPPER, LEAD-COATED | SLATE TILE | 1,620 | LF | \$43.20 | | \$69,977 | 1955 | 70 | |
| C1020 | DOOR AND FRAME, INTERIOR, NON-RATED | | 200 | LEAF | \$1,928.58 | | \$385,716 | 1962 | 40 | 11 |
| C1020 | DOOR AND FRAME, INTERIOR, NON-RATED | FOURTH FLR | 40 | LEAF | \$1,928.58 | | \$77,143 | 2012 | 40 | |
| C1020 | DOOR AND FRAME, INTERIOR, FIRE-RATED | | 175 | LEAF | \$3,216.19 | | \$562,833 | 1962 | 40 | 11 |
| C1020 | DOOR AND FRAME, INTERIOR, FIRE-RATED | FOURTH FLR | 25 | LEAF | \$3,216.19 | | \$80,405 | 2012 | 40 | |
| C1020 | DOOR, SLIDING SYSTEM, INTERIOR | JAIL | 12 | EA | \$16,137.70 | | \$193,652 | 1988 | 15 | 10 |
| C1020 | DOOR LOCK, COMMERCIAL-GRADE | | 375 | EA | \$657.47 | | \$246,553 | 1962 | 20 | 31 |

Asset Component Inventory
0001 : MUNICIPAL COMPLEX

| Uni-format | Component Description | Identifier | Qty | Units | Unit Cost | Cmplx Adj | Total Cost | Install Date | Life Exp | Lf Adj |
|------------|--|----------------|---------|-------|--------------|-----------|------------|--------------|----------|--------|
| C1020 | DOOR LOCK, COMMERCIAL-GRADE | | 12 | EA | \$657.47 | | \$7,890 | 1988 | 20 | 5 |
| C1020 | DOOR PANIC HARDWARE | PD/MAIN ENTRY | 4 | EA | \$1,041.59 | | \$4,166 | 1988 | 20 | 5 |
| C1020 | DOOR ACCESS CONTROL SYSTEM | POLICE DEPT | 2 | EA | \$19,511.01 | | \$39,022 | 1988 | 15 | 10 |
| C3010 | WALL FINISH - PAINT, STANDARD | | 166,040 | SF | \$2.38 | | \$394,771 | 1988 | 12 | 15 |
| C3010 | WALL FINISH - PAINT, STANDARD | UPPER FLOOR | 18,450 | SF | \$2.38 | | \$43,866 | 2012 | 12 | |
| C3010 | WALL FINISH - TILE, CERAMIC / STONE, STANDARD | | 12,300 | SF | \$35.18 | | \$432,666 | 1962 | 30 | 21 |
| C3010 | WALL FINISH - WALL COVERING, ROLL | | 49,200 | SF | \$4.93 | | \$242,546 | 1962 | 20 | 31 |
| C3020 | FLOORING - CARPET, TILE OR ROLL, STANDARD | | 18,800 | SF | \$10.46 | | \$196,577 | 1988 | 12 | 13 |
| C3020 | FLOORING - CARPET, TILE OR ROLL, STANDARD | UPPER FLOOR | 2,090 | SF | \$10.46 | | \$21,854 | 2012 | 12 | 1 |
| C3020 | FLOORING - VINYL COMPOSITION TILE, STANDARD | | 50,130 | SF | \$5.96 | | \$298,994 | 1988 | 20 | 5 |
| C3020 | FLOORING - VINYL SHEET, STANDARD | | 4,180 | SF | \$9.79 | | \$40,925 | 1962 | 15 | 36 |
| C3020 | FLOORING - TILE, CERAMIC / STONE / QUARRY STANDARD | | 4,180 | SF | \$30.44 | | \$127,260 | 1962 | 30 | 21 |
| C3020 | FLOORING - FLUID APPLIED, PAINT OR CLEAR SEAL | | 4,180 | SF | \$3.01 | | \$12,583 | 1950 | 10 | 55 |
| C3030 | CEILING FINISH - SUSPENDED ACOUSTICAL TILE, STANDARD | | 60,150 | SF | \$9.61 | | \$578,329 | 1988 | 30 | |
| C3030 | CEILING FINISH - SUSPENDED ACOUSTICAL TILE, STANDARD | UPPER FLOOR | 6,680 | SF | \$9.61 | | \$64,227 | 2012 | 30 | |
| C3030 | CEILING FINISH - PAINTED OR STAINED, STANDARD | | 11,280 | SF | \$2.38 | | \$26,819 | 1988 | 24 | 1 |
| C3030 | CEILING FINISH - PAINTED OR STAINED, STANDARD | UPPER FLOOR | 1,250 | SF | \$2.38 | | \$2,972 | 2012 | 24 | |
| D1010 | ELEVATOR MODERNIZATION - TRACTION - LOW RISE | ELEVATOR A & B | 2 | EA | \$235,423.91 | | \$470,848 | 1962 | 25 | 26 |
| D1010 | ELEVATOR MODERNIZATION - TRACTION - LOW RISE | SEYBOLT | 1 | EA | \$235,423.91 | | \$235,424 | 1950 | 25 | 38 |
| D1010 | ELEVATOR CAB RENOVATION - PASSENGER | ELEVATOR A & B | 2 | EA | \$53,180.15 | | \$106,360 | 2007 | 12 | 3 |
| D1010 | ELEVATOR CAB RENOVATION - PASSENGER | SEYBOLT | 1 | EA | \$53,180.15 | | \$53,180 | 2007 | 12 | 3 |
| D2010 | PLUMBING FIXTURE - LAVATORY, COUNTER | 1989 | 3 | EA | \$1,175.27 | | \$3,526 | 1989 | 35 | |
| D2010 | PLUMBING FIXTURE - LAVATORY, WALL HUNG | 1950 | 8 | EA | \$1,179.21 | | \$9,434 | 1950 | 35 | 28 |
| D2010 | PLUMBING FIXTURE - LAVATORY, WALL HUNG | 1962 | 5 | EA | \$1,179.21 | | \$5,896 | 1962 | 35 | 16 |
| D2010 | PLUMBING FIXTURE - LAVATORY, WALL HUNG | 1989 | 23 | EA | \$1,179.21 | | \$27,122 | 1989 | 35 | |

Asset Component Inventory
0001 : MUNICIPAL COMPLEX

| Uni-format | Component Description | Identifier | Qty | Units | Unit Cost | Cmplx Adj | Total Cost | Install Date | Life Exp | Lf Adj |
|------------|--|--------------|--------|-------|-------------|-----------|------------|--------------|----------|--------|
| D2010 | PLUMBING FIXTURE - LAVATORY, WALL HUNG | 2011 | 2 | EA | \$1,179.21 | | \$2,358 | 2011 | 35 | |
| D2010 | PLUMBING FIXTURE - SINK, KITCHEN | 1950 | 1 | EA | \$1,877.71 | | \$1,878 | 1950 | 35 | 28 |
| D2010 | PLUMBING FIXTURE - SINK, KITCHEN | 1962 | 3 | EA | \$1,877.71 | | \$5,633 | 1962 | 35 | 16 |
| D2010 | PLUMBING FIXTURE - SINK, KITCHEN | 1989 | 4 | EA | \$1,877.71 | | \$7,511 | 1989 | 35 | |
| D2010 | PLUMBING FIXTURE - SINK, SERVICE/LAUNDRY/UTILITY | 1950 | 3 | EA | \$1,569.61 | | \$4,709 | 1950 | 35 | 28 |
| D2010 | PLUMBING FIXTURE - SINK, SERVICE/LAUNDRY/UTILITY | 1962 | 3 | EA | \$1,569.61 | | \$4,709 | 1962 | 35 | 16 |
| D2010 | PLUMBING FIXTURE - SINK, SERVICE/LAUNDRY/UTILITY | 1989 | 3 | EA | \$1,569.61 | | \$4,709 | 1989 | 35 | |
| D2010 | PLUMBING FIXTURE - SHOWER VALVE AND HEAD | 1962 | 1 | EA | \$1,527.93 | | \$1,528 | 1962 | 35 | 16 |
| D2010 | PLUMBING FIXTURE - SHOWER VALVE AND HEAD | 1989 | 7 | EA | \$1,527.93 | | \$10,695 | 1989 | 35 | |
| D2010 | PLUMBING FIXTURE - BATHTUB WITH FIXTURES | 1950 | 1 | EA | \$5,885.59 | | \$5,886 | 1950 | 35 | 28 |
| D2010 | PLUMBING FIXTURE - URINAL | 1989 | 5 | EA | \$1,870.67 | | \$9,353 | 1989 | 35 | |
| D2010 | PLUMBING FIXTURE - WATER CLOSET, TANKLESS | 1950 | 9 | EA | \$1,694.47 | | \$15,250 | 1950 | 35 | 28 |
| D2010 | PLUMBING FIXTURE - WATER CLOSET, TANKLESS | 1962 | 5 | EA | \$1,694.47 | | \$8,472 | 1962 | 35 | 16 |
| D2010 | PLUMBING FIXTURE - WATER CLOSET, TANKLESS | 1989 | 26 | EA | \$1,694.47 | | \$44,056 | 1989 | 35 | |
| D2010 | PLUMBING FIXTURE - WATER CLOSET, TANKLESS | 2011 | 2 | EA | \$1,694.47 | | \$3,389 | 2011 | 35 | |
| D2010 | PLUMBING FIXTURE - COMBINATION TOILET/SINK, STAINLESS STL, INSTITUTIONAL | 1989 | 5 | EA | \$2,529.47 | | \$12,647 | 1989 | 35 | |
| D2020 | BACKFLOW PREVENTER (3-4 INCHES) | DOMESTIC | 1 | EA | \$7,391.60 | | \$7,392 | 2010 | 10 | |
| D2020 | BACKFLOW PREVENTER (4-6 INCHES) | SPRINKLER | 1 | EA | \$10,788.44 | | \$10,788 | 2010 | 10 | |
| D2020 | SUPPLY PIPING SYSTEM - OFFICE | 1950 | 22,827 | SF | \$3.55 | 1.13 | \$91,491 | 1950 | 35 | 28 |
| D2020 | SUPPLY PIPING SYSTEM - OFFICE | 1962 | 50,000 | SF | \$3.55 | 1.02 | \$180,893 | 1962 | 35 | 16 |
| D2020 | SUPPLY PIPING SYSTEM - OFFICE | 1989 | 20,000 | SF | \$3.55 | 1.13 | \$80,160 | 1989 | 35 | |
| D2020 | WATER HEATER - COMMERCIAL, GAS (168-225 MBH INPUT) | LAARS | 200 | MBH | \$72.83 | | \$14,566 | 2010 | 25 | |
| D2020 | WATER HEATER - RESIDENTIAL, GAS (45-55 GAL) | GE | 50 | GAL | \$39.33 | | \$1,967 | 2002 | 20 | 3 |
| D2020 | WATER HEATER - RESIDENTIAL, ELECTRIC (>100 GAL) | STORAGE TANK | 120 | GAL | \$24.43 | 0.50 | \$1,466 | 2010 | 10 | 5 |

Asset Component Inventory

0001 : MUNICIPAL COMPLEX

| Uni-format | Component Description | Identifier | Qty | Units | Unit Cost | Cmplx Adj | Total Cost | Install Date | Life Exp | Lf Adj |
|------------|--|---------------|--------|-------|------------|-----------|------------|--------------|----------|--------|
| D2020 | WATER HEATER (ELECTRIC INSTANTANEOUS) | ROOM 446 | 1 | EA | \$852.00 | | \$852 | 2011 | 10 | 4 |
| D2030 | DRAIN PIPING SYSTEM - OFFICE | 1950 | 22,827 | SF | \$5.31 | 1.13 | \$136,937 | 1950 | 40 | 23 |
| D2030 | DRAIN PIPING SYSTEM - OFFICE | 1962 | 50,000 | SF | \$5.31 | 1.02 | \$270,748 | 1962 | 40 | 11 |
| D2030 | DRAIN PIPING SYSTEM - OFFICE | 1989 | 20,000 | SF | \$5.31 | 1.13 | \$119,978 | 1989 | 40 | |
| D3030 | CHILLER - WATER-COOLED CENTRIFUGAL OR SCREW (<=150 TONS) | CARRIER | 143 | TON | \$1,757.61 | | \$251,338 | 2009 | 30 | |
| D3030 | COOLING TOWER (126-200 TONS) | EVAPCO | 150 | TON | \$363.42 | | \$54,513 | 2009 | 30 | |
| D3030 | CONDENSER - REFRIGERANT, AIR-COOLED (<=10 TON) | TRANE | 3 | TON | \$1,985.87 | | \$5,958 | 2001 | 25 | |
| D3030 | CONDENSER - REFRIGERANT, AIR-COOLED (<=10 TON) | IT ROOM | 3 | TON | \$1,985.87 | | \$5,958 | 1989 | 25 | |
| D3030 | CONDENSER - REFRIGERANT, AIR-COOLED (<=10 TON) | DISPATCH | 3 | TON | \$1,985.87 | | \$5,958 | 2003 | 25 | |
| D3030 | CONDENSER - REFRIGERANT, AIR-COOLED (<=10 TON) | TRANE AHU | 5 | TON | \$1,985.87 | | \$9,929 | 2001 | 25 | |
| D3030 | CONDENSER - REFRIGERANT, AIR-COOLED (<=10 TON) | FIRING RANGE | 3 | TON | \$1,985.87 | | \$5,958 | 1989 | 25 | |
| D3030 | CONDENSER - REFRIGERANT, AIR-COOLED (<=10 TON) | FIRING RANGE | 2 | TON | \$1,985.87 | | \$3,972 | 1929 | 25 | 59 |
| D3030 | EVAPORATOR UNIT, NO HEAT (2-3 TON) | IT ROOM | 3 | TON | \$1,632.06 | | \$4,896 | 1989 | 20 | 4 |
| D3030 | DUCTLESS DX SPLIT SYSTEM (>2 TON) | DISPATCH | 3 | TON | \$1,293.17 | | \$3,880 | 2003 | 25 | |
| D3030 | DUCTLESS DX SPLIT SYSTEM (>2 TON) | IT | 3 | TON | \$1,293.17 | | \$3,880 | 2009 | 25 | |
| D3030 | PTAC, DX/ HP COOL, ELEC HEAT (0.5-1.25 TON) | EVIDENCE | 1 | TON | \$1,994.53 | | \$1,995 | 2000 | 25 | |
| D3040 | AIR HANDLING UNIT - INDOOR (1.25-1.75 HP) | ACS-4 | 2 | HP | \$6,332.15 | | \$12,664 | 1989 | 25 | |
| D3040 | AIR HANDLING UNIT - INDOOR (1.25-1.75 HP) | ACS-5 | 2 | HP | \$6,332.15 | | \$12,664 | 1989 | 25 | |
| D3040 | AIR HANDLING UNIT - INDOOR (1.75-2.75 HP) | PHONE ROOM | 2 | HP | \$8,454.39 | | \$16,909 | 1989 | 25 | |
| D3040 | AIR HANDLING UNIT - INDOOR (1.75-2.75 HP) | ACS-3 | 2 | HP | \$8,454.39 | | \$16,909 | 1989 | 25 | |
| D3040 | AIR HANDLING UNIT - INDOOR (1.75-2.75 HP) | ACS-6 | 2 | HP | \$8,454.39 | | \$16,909 | 1989 | 25 | |
| D3040 | AIR HANDLING UNIT - INDOOR (1.75-2.75 HP) | HV-3 | 2 | HP | \$8,454.39 | | \$16,909 | 1989 | 25 | |
| D3040 | AIR HANDLING UNIT - INDOOR (2.75-3.25 HP) | HOLDING CELLS | 3 | HP | \$6,892.03 | | \$20,676 | 1989 | 25 | |
| D3040 | AIR HANDLING UNIT - INDOOR (2.75-3.25 HP) | HV-1 | 3 | HP | \$6,892.03 | | \$20,676 | 1989 | 25 | |

Asset Component Inventory

0001 : MUNICIPAL COMPLEX

| Uni-format | Component Description | Identifier | Qty | Units | Unit Cost | Cmplx Adj | Total Cost | Install Date | Life Exp | Lf Adj |
|------------|---|-----------------|--------|-------|-------------|-----------|-------------|--------------|----------|--------|
| D3040 | AIR HANDLING UNIT - INDOOR (2.75-3.25 HP) | ACS-7 | 3 | HP | \$6,892.03 | | \$20,676 | 1989 | 25 | |
| D3040 | AIR HANDLING UNIT - INDOOR (3.25-6 HP) | HV-2 | 5 | HP | \$7,394.53 | | \$36,973 | 1989 | 25 | |
| D3040 | AIR HANDLING UNIT - INDOOR (3.25-6 HP) | TRANE | 5 | HP | \$7,394.53 | | \$36,973 | 2001 | 25 | |
| D3040 | AIR HANDLING UNIT - OUTDOOR PACKAGE (5-8 HP) | FIRING RANGE | 8 | HP | \$13,318.93 | | \$106,551 | 1989 | 25 | |
| D3040 | HUMIDIFIER, ELECTRIC, POINT-OF-USE | VAPOR LOGIC | 1 | EA | \$5,807.35 | | \$5,807 | 2003 | 20 | |
| D3040 | FAN - CENTRIFUGAL ROOF EXHAUST, 1/4" SP (10"-18" DIAMETER) | ROOF EX-4 | 1 | EA | \$3,281.82 | | \$3,282 | 1990 | 20 | 3 |
| D3040 | FAN - CENTRIFUGAL ROOF EXHAUST, 1/4" SP (10"-18" DIAMETER) | ROOF EX-5 | 1 | EA | \$3,281.82 | | \$3,282 | 1990 | 20 | 3 |
| D3040 | FAN - CENTRIFUGAL ROOF EXHAUST, 1/4" SP (20"-22" DIAMETER) | COUNCIL CHAMBER | 1 | EA | \$5,977.00 | | \$5,977 | 1990 | 20 | 3 |
| D3040 | FAN - PROPELLER WITH LOUVER, 1/4" SP (<=0.5 HP) | RESTROOM | 3 | HP | \$6,459.29 | | \$19,378 | 1989 | 20 | 4 |
| D3040 | FAN - PROPELLER WITH LOUVER, 1/4" SP (1.5-2 HP) | SEYBOLT | 2 | HP | \$1,565.40 | | \$3,131 | 1989 | 20 | 4 |
| D3040 | FAN - UTILITY SET, 1/4" SP (1.25-4 HP) | EXH FAN 5 | 3 | HP | \$3,546.14 | | \$10,638 | 1962 | 20 | 31 |
| D3040 | HVAC DISTRIBUTION NETWORKS - OFFICE | SEYBOLT | 28,004 | SF | \$24.82 | 1.07 | \$743,735 | 1929 | 40 | 44 |
| D3040 | HVAC DISTRIBUTION NETWORKS - OFFICE | CITY HALL | 64,823 | SF | \$24.82 | | \$1,608,953 | 1962 | 40 | 11 |
| D3040 | PUMP - ELECTRIC (<=10 HP) | P-1 | 8 | HP | \$1,474.79 | | \$11,798 | 1989 | 25 | |
| D3040 | PUMP - ELECTRIC (<=10 HP) | P-2 | 8 | HP | \$1,474.79 | | \$11,798 | 1989 | 25 | |
| D3040 | PUMP - ELECTRIC (<=10 HP) | P-3 | 8 | HP | \$1,474.79 | | \$11,798 | 1989 | 25 | |
| D3040 | PUMP - ELECTRIC (<=10 HP) | SEYBOLT | 2 | HP | \$1,474.79 | | \$2,950 | 1989 | 25 | |
| D3040 | PUMP - ELECTRIC (<=10 HP) | SEYBOLT | 2 | HP | \$1,474.79 | | \$2,950 | 1989 | 25 | |
| D3050 | PACKAGE HVAC UNIT, DX, GAS OR ELECTRIC HEAT, SINGLE-ZONE (<= 5 TON) | SERT AHU | 5 | TON | \$3,715.08 | | \$18,575 | 1989 | 25 | |
| D3050 | PACKAGE HVAC UNIT, DX, GAS OR ELECTRIC HEAT, SINGLE-ZONE (9-35 TON) | COUNCIL CHAMBER | 15 | TON | \$3,929.84 | | \$58,948 | 1989 | 25 | |
| D3060 | HVAC CONTROLS SYSTEM - OFFICE | SEYBOLT | 28,004 | SF | \$3.87 | 1.07 | \$116,035 | 1929 | 18 | 66 |
| D3060 | HVAC CONTROLS SYSTEM - OFFICE | CITY HALL | 64,823 | SF | \$3.87 | | \$251,024 | 1962 | 18 | 33 |
| D4010 | FIRE SPRINKLER SYSTEM | SEYBOLT | 28,004 | SF | \$12.01 | 1.07 | \$359,883 | 1950 | 80 | |
| D4010 | FIRE SPRINKLER SYSTEM | CITY HALL | 64,823 | SF | \$12.01 | | \$778,550 | 1962 | 80 | |

Asset Component Inventory
0001 : MUNICIPAL COMPLEX

| Uni-format | Component Description | Identifier | Qty | Units | Unit Cost | Cmplx Adj | Total Cost | Install Date | Life Exp | Lf Adj |
|------------|--|--------------|--------|-------|-------------|-----------|------------|--------------|----------|--------|
| D4030 | FIRE ALARM PANEL, DIALER, BATTERY, & CHARGER | GENERATOR RM | 1 | EA | \$35,304.58 | | \$35,305 | 1989 | 15 | 9 |
| D4030 | FIRE ALARM SYSTEM - DEVICES | SEYBOLT | 28,004 | SF | \$3.73 | 1.07 | \$111,877 | 1989 | 18 | 6 |
| D4030 | FIRE ALARM SYSTEM - DEVICES | CITY HALL | 64,823 | SF | \$3.73 | | \$242,029 | 1989 | 18 | 6 |
| D4090 | FM200 OR INERGEN FIRE SUPPRESSION | VAULT | 4,800 | CF | \$5.55 | | \$26,653 | 1989 | 25 | |
| D4090 | FM200 OR INERGEN FIRE SUPPRESSION | DISPATCH | 2,400 | CF | \$5.55 | | \$13,326 | 2003 | 25 | |
| D4090 | FM200 OR INERGEN FIRE SUPPRESSION | 3RD FLOOR IT | 2,400 | CF | \$5.55 | | \$13,326 | 1989 | 25 | |
| D5010 | ELECTRICAL DISTRIBUTION NETWORK - OFFICE | 1950 | 22,827 | SF | \$19.08 | 1.13 | \$492,218 | 1929 | 40 | 44 |
| D5010 | ELECTRICAL DISTRIBUTION NETWORK - OFFICE | 1962 | 50,000 | SF | \$19.08 | 1.02 | \$973,196 | 1950 | 40 | 23 |
| D5010 | ELECTRICAL DISTRIBUTION NETWORK - OFFICE | 1989 | 10,000 | SF | \$19.08 | 1.18 | \$225,171 | 1989 | 40 | |
| D5010 | ELECTRICAL DISTRIBUTION NETWORK - OFFICE | 2011 | 10,000 | SF | \$19.08 | 1.18 | \$225,171 | 2011 | 40 | |
| D5010 | MAIN SWITCHBOARD W/BREAKERS (800-1200 AMP) | MDP-2 | 1,200 | AMP | \$65.43 | | \$78,519 | 1975 | 20 | 18 |
| D5010 | MAIN SWITCHBOARD W/BREAKERS (1600-2500 AMP) | MDP-1 | 2,500 | AMP | \$73.51 | | \$183,763 | 1975 | 20 | 18 |
| D5020 | LIGHTING - EXTERIOR, STANCHION LUMINAIRE, 12-FOOT | | 3 | EA | \$1,943.35 | | \$5,830 | 1989 | 15 | 10 |
| D5020 | LIGHTING - EXTERIOR, WALL FLOOD (SV, MH, ID, LED) | | 15 | EA | \$925.79 | | \$13,887 | 1989 | 15 | 10 |
| D5020 | LIGHTING - EXTERIOR, WALL FLOOD (SV, MH, ID, LED) | | 2 | EA | \$925.79 | | \$1,852 | 2011 | 15 | |
| D5020 | LIGHTING - EXTERIOR, WALL LANTERN or FLOOD (INC, CFL, LED) | | 9 | EA | \$414.13 | | \$3,727 | 1962 | 15 | 37 |
| D5020 | LIGHTING - EXTERIOR, WALL LANTERN or FLOOD (INC, CFL, LED) | | 1 | EA | \$414.13 | | \$414 | 1989 | 15 | 10 |
| D5020 | LIGHTING SYSTEM, INTERIOR - OFFICE | 1950 | 22,827 | SF | \$11.31 | 1.13 | \$291,712 | 1929 | 20 | 65 |
| D5020 | LIGHTING SYSTEM, INTERIOR - OFFICE | 1962 | 50,000 | SF | \$11.31 | 1.02 | \$576,762 | 1950 | 20 | 44 |
| D5020 | LIGHTING SYSTEM, INTERIOR - OFFICE | 1989 | 10,000 | SF | \$11.31 | 1.18 | \$133,447 | 1989 | 20 | 6 |
| D5020 | LIGHTING SYSTEM, INTERIOR - OFFICE | 2011 | 10,000 | SF | \$11.31 | 1.18 | \$133,447 | 2011 | 20 | |
| D5090 | EXIT SIGN - CENTRAL POWER | OLD | 45 | EA | \$336.86 | | \$15,159 | 1989 | 20 | 4 |
| D5090 | EXIT SIGN - CENTRAL POWER | UPDATED | 15 | EA | \$336.86 | | \$5,053 | 2011 | 20 | |
| D5090 | EMERGENCY LIGHT - UNITARY WITH BATTERY BACK-UP | OLD | 10 | EA | \$581.59 | | \$5,816 | 1989 | 20 | 4 |

Asset Component Inventory

0001 : MUNICIPAL COMPLEX

| Uni-format | Component Description | Identifier | Qty | Units | Unit Cost | Cmplx Adj | Total Cost | Install Date | Life Exp | Lf Adj |
|------------|---|----------------|-------|-------|-------------|-----------|---------------------|--------------|----------|--------|
| D5090 | EMERGENCY LIGHT - UNITARY WITH BATTERY BACK-UP | UPDATED | 15 | EA | \$581.59 | | \$8,724 | 2011 | 20 | |
| D5090 | GENERATOR - DIESEL (<30-100KW) | CUMMINS MARINE | 40 | KW | \$858.66 | | \$34,347 | 1962 | 25 | 26 |
| D5090 | GENERATOR - DIESEL (<30-100KW) | ONAN | 39 | KW | \$858.66 | | \$33,488 | 1989 | 25 | 5 |
| D5090 | SWITCH - AUTO TRANSFER, 208 OR 240 V (>100 AMP) | EPG 01 08 | 200 | AMP | \$23.97 | | \$4,795 | 1989 | 25 | |
| D5090 | SWITCH - AUTO TRANSFER, 208 OR 240 V (>100 AMP) | ONAN | 400 | AMP | \$23.97 | | \$9,590 | 1989 | 25 | |
| D5090 | UNINTERRUPTIBLE POWER SUPPLY - 120/208 VOLTS | EATON 9355 | 1 | EA | \$68,603.91 | | \$68,604 | 2003 | 15 | |
| E2010 | CASEWORK - WOOD BASE AND WALL, TOP, STANDARD | | 1,200 | LF | \$488.03 | | \$585,632 | 1962 | 20 | 31 |
| E2010 | KITCHENETTE UNIT WITH CABINETRY AND AMENITIES | | 4 | EA | \$10,887.21 | | \$43,549 | 1962 | 20 | 31 |
| G2020 | ASPHALT VEHICULAR PAVING - SEALCOAT AND STRIPE | | 1,000 | SY | \$3.41 | | \$3,413 | 1988 | 7 | 22 |
| G2030 | CONCRETE PEDESTRIAN PAVING - JOINT MAINTENANCE | | 250 | LF | \$4.90 | | \$1,224 | 1988 | 7 | 22 |
| | | | | | | | \$17,078,874 | | | |

Recurring Component Renewal Schedule

0001 : MUNICIPAL COMPLEX

| Uniformat Code | Component Description | | Qty | Units | CN Replacement Cost | Year |
|----------------|---|----------------|--------|-------|---------------------|------|
| B2030 | DOOR OPERATOR, OVERHEAD DOOR, COMMERCIAL, PADS | PD LOAD BAYS | 2 | EA | \$3,670 | CN |
| B2030 | DOOR AND STOREFRONT, EXTERIOR, SWINGING, ALUMINUM AND GLASS | PD/MAIN ENTRY | 4 | LEAF | \$13,108 | CN |
| B3010 | ROOF - 1-PLY, IRMA, BALLASTED | 1990 | 5,600 | SF | \$52,880 | CN |
| B3010 | ROOF GUTTER AND LEADER - ALUMINUM OR GALVANIZED, COATED | 1990 | 1,150 | LF | \$18,922 | CN |
| C1020 | DOOR LOCK, COMMERCIAL-GRADE | | 375 | EA | \$246,553 | CN |
| C1020 | DOOR LOCK, COMMERCIAL-GRADE | | 12 | EA | \$7,890 | CN |
| C1020 | DOOR PANIC HARDWARE | PD/MAIN ENTRY | 4 | EA | \$4,166 | CN |
| C1020 | DOOR ACCESS CONTROL SYSTEM | POLICE DEPT | 2 | EA | \$39,022 | CN |
| C1020 | DOOR AND FRAME, INTERIOR, NON-RATED | | 200 | LEAF | \$385,716 | CN |
| C1020 | DOOR AND FRAME, INTERIOR, FIRE-RATED | | 175 | LEAF | \$562,833 | CN |
| C1020 | DOOR, SLIDING SYSTEM, INTERIOR | JAIL | 12 | EA | \$193,652 | CN |
| C3010 | WALL FINISH - TILE, CERAMIC / STONE, STANDARD | | 12,300 | SF | \$432,666 | CN |
| C3010 | WALL FINISH - WALL COVERING, ROLL | | 49,200 | SF | \$242,546 | CN |
| C3020 | FLOORING - CARPET, TILE OR ROLL, STANDARD | | 18,800 | SF | \$196,577 | CN |
| C3020 | FLOORING - VINYL COMPOSITION TILE, STANDARD | | 50,130 | SF | \$298,994 | CN |
| C3020 | FLOORING - VINYL SHEET, STANDARD | | 4,180 | SF | \$40,925 | CN |
| C3020 | FLOORING - TILE, CERAMIC / STONE / QUARRY STANDARD | | 4,180 | SF | \$127,260 | CN |
| C3030 | CEILING FINISH - PAINTED OR STAINED, STANDARD | | 11,280 | SF | \$26,819 | CN |
| D1010 | ELEVATOR MODERNIZATION - TRACTION - LOW RISE | ELEVATOR A & B | 2 | EA | \$470,848 | CN |
| D1010 | ELEVATOR MODERNIZATION - TRACTION - LOW RISE | SEYBOLT | 1 | EA | \$235,424 | CN |

Recurring Component Renewal Schedule

| | | | | | | |
|-------|--|---------------|--------|-----|-----------|----|
| D2010 | PLUMBING FIXTURE - LAVATORY, WALL HUNG | 1950 | 8 | EA | \$9,434 | CN |
| D2010 | PLUMBING FIXTURE - LAVATORY, WALL HUNG | 1962 | 5 | EA | \$5,896 | CN |
| D2010 | PLUMBING FIXTURE - SINK, KITCHEN | 1950 | 1 | EA | \$1,878 | CN |
| D2010 | PLUMBING FIXTURE - SINK, KITCHEN | 1962 | 3 | EA | \$5,633 | CN |
| D2010 | PLUMBING FIXTURE - SINK, SERVICE/LAUNDRY/UTILITY | 1950 | 3 | EA | \$4,709 | CN |
| D2010 | PLUMBING FIXTURE - SINK, SERVICE/LAUNDRY/UTILITY | 1962 | 3 | EA | \$4,709 | CN |
| D2010 | PLUMBING FIXTURE - SHOWER VALVE AND HEAD | 1962 | 1 | EA | \$1,528 | CN |
| D2010 | PLUMBING FIXTURE - BATHTUB WITH FIXTURES | 1950 | 1 | EA | \$5,886 | CN |
| D2010 | PLUMBING FIXTURE - WATER CLOSET, TANKLESS | 1950 | 9 | EA | \$15,250 | CN |
| D2010 | PLUMBING FIXTURE - WATER CLOSET, TANKLESS | 1962 | 5 | EA | \$8,472 | CN |
| D2020 | SUPPLY PIPING SYSTEM - OFFICE | 1950 | 22,827 | SF | \$91,491 | CN |
| D2020 | SUPPLY PIPING SYSTEM - OFFICE | 1962 | 50,000 | SF | \$180,893 | CN |
| D2030 | DRAIN PIPING SYSTEM - OFFICE | 1950 | 22,827 | SF | \$136,937 | CN |
| D2030 | DRAIN PIPING SYSTEM - OFFICE | 1962 | 50,000 | SF | \$270,748 | CN |
| D3030 | CONDENSER - REFRIGERANT, AIR-COOLED (<=10 TON) | IT ROOM | 3 | TON | \$5,958 | CN |
| D3030 | CONDENSER - REFRIGERANT, AIR-COOLED (<=10 TON) | FIRING RANGE | 3 | TON | \$5,958 | CN |
| D3030 | CONDENSER - REFRIGERANT, AIR-COOLED (<=10 TON) | FIRING RANGE | 2 | TON | \$3,972 | CN |
| D3030 | EVAPORATOR UNIT, NO HEAT (2-3 TON) | IT ROOM | 3 | TON | \$4,896 | CN |
| D3040 | AIR HANDLING UNIT - INDOOR (1.25-1.75 HP) | ACS-4 | 2 | HP | \$12,664 | CN |
| D3040 | AIR HANDLING UNIT - INDOOR (1.25-1.75 HP) | ACS-5 | 2 | HP | \$12,664 | CN |
| D3040 | AIR HANDLING UNIT - INDOOR (1.75-2.75 HP) | PHONE ROOM | 2 | HP | \$16,909 | CN |
| D3040 | AIR HANDLING UNIT - INDOOR (1.75-2.75 HP) | ACS-3 | 2 | HP | \$16,909 | CN |
| D3040 | AIR HANDLING UNIT - INDOOR (1.75-2.75 HP) | ACS-6 | 2 | HP | \$16,909 | CN |
| D3040 | AIR HANDLING UNIT - INDOOR (1.75-2.75 HP) | HV-3 | 2 | HP | \$16,909 | CN |
| D3040 | AIR HANDLING UNIT - INDOOR (2.75-3.25 HP) | HOLDING CELLS | 3 | HP | \$20,676 | CN |
| D3040 | AIR HANDLING UNIT - INDOOR (2.75-3.25 HP) | HV-1 | 3 | HP | \$20,676 | CN |
| D3040 | AIR HANDLING UNIT - INDOOR (2.75-3.25 HP) | ACS-7 | 3 | HP | \$20,676 | CN |

Recurring Component Renewal Schedule

| | | | | | | |
|-------|---|-----------------|--------|-----|-------------|----|
| D3040 | AIR HANDLING UNIT - INDOOR (3.25-6 HP) | HV-2 | 5 | HP | \$36,973 | CN |
| D3040 | AIR HANDLING UNIT - OUTDOOR PACKAGE (5-8 HP) | FIRING RANGE | 8 | HP | \$106,551 | CN |
| D3040 | FAN - CENTRIFUGAL ROOF EXHAUST, 1/4" SP (10"-18" DIAMETER) | ROOF EX-4 | 1 | EA | \$3,282 | CN |
| D3040 | FAN - CENTRIFUGAL ROOF EXHAUST, 1/4" SP (10"-18" DIAMETER) | ROOF EX-5 | 1 | EA | \$3,282 | CN |
| D3040 | FAN - CENTRIFUGAL ROOF EXHAUST, 1/4" SP (20"-22" DIAMETER) | COUNCIL CHAMBER | 1 | EA | \$5,977 | CN |
| D3040 | FAN - PROPELLER WITH LOUVER, 1/4" SP (<=0.5 HP) | RESTROOM | 3 | HP | \$19,378 | CN |
| D3040 | FAN - PROPELLER WITH LOUVER, 1/4" SP (1.5-2 HP) | SEYBOLT | 2 | HP | \$3,131 | CN |
| D3040 | FAN - UTILITY SET, 1/4" SP (1.25-4 HP) | EXH FAN 5 | 3 | HP | \$10,638 | CN |
| D3040 | HVAC DISTRIBUTION NETWORKS - OFFICE | SEYBOLT | 28,004 | SF | \$743,735 | CN |
| D3040 | HVAC DISTRIBUTION NETWORKS - OFFICE | CITY HALL | 64,823 | SF | \$1,608,953 | CN |
| D3040 | PUMP - ELECTRIC (<=10 HP) | P-1 | 8 | HP | \$11,798 | CN |
| D3040 | PUMP - ELECTRIC (<=10 HP) | P-2 | 8 | HP | \$11,798 | CN |
| D3040 | PUMP - ELECTRIC (<=10 HP) | P-3 | 8 | HP | \$11,798 | CN |
| D3040 | PUMP - ELECTRIC (<=10 HP) | SEYBOLT | 2 | HP | \$2,950 | CN |
| D3040 | PUMP - ELECTRIC (<=10 HP) | SEYBOLT | 2 | HP | \$2,950 | CN |
| D3050 | PACKAGE HVAC UNIT, DX, GAS OR ELECTRIC HEAT, SINGLE-ZONE (<= 5 TON) | SERT AHU | 5 | TON | \$18,575 | CN |
| D3050 | PACKAGE HVAC UNIT, DX, GAS OR ELECTRIC HEAT, SINGLE-ZONE (9-35 TON) | COUNCIL CHAMBER | 15 | TON | \$58,948 | CN |
| D3060 | HVAC CONTROLS SYSTEM - OFFICE | SEYBOLT | 28,004 | SF | \$116,035 | CN |
| D3060 | HVAC CONTROLS SYSTEM - OFFICE | CITY HALL | 64,823 | SF | \$251,024 | CN |
| D4030 | FIRE ALARM PANEL, DIALER, BATTERY, & CHARGER | GENERATOR RM | 1 | EA | \$35,305 | CN |
| D4030 | FIRE ALARM SYSTEM - DEVICES | SEYBOLT | 28,004 | SF | \$111,877 | CN |
| D4030 | FIRE ALARM SYSTEM - DEVICES | CITY HALL | 64,823 | SF | \$242,029 | CN |
| D4090 | FM200 OR INERGEN FIRE SUPPRESSION | VAULT | 4,800 | CF | \$26,653 | CN |
| D4090 | FM200 OR INERGEN FIRE SUPPRESSION | 3RD FLOOR IT | 2,400 | CF | \$13,326 | CN |
| D5010 | ELECTRICAL DISTRIBUTION NETWORK - OFFICE | 1950 | 22,827 | SF | \$492,218 | CN |
| D5010 | ELECTRICAL DISTRIBUTION NETWORK - OFFICE | 1962 | 50,000 | SF | \$973,196 | CN |

Recurring Component Renewal Schedule

| | | | | | | |
|-------|---|----------------|--------|-----|-----------|----|
| D5010 | MAIN SWITCHBOARD W/BREAKERS (800-1200 AMP) | MDP-2 | 1,200 | AMP | \$78,519 | CN |
| D5010 | MAIN SWITCHBOARD W/BREAKERS (1600-2500 AMP) | MDP-1 | 2,500 | AMP | \$183,763 | CN |
| D5020 | LIGHTING - EXTERIOR, STANCHION LUMINAIRE, 12-FOOT | | 3 | EA | \$5,830 | CN |
| D5020 | LIGHTING - EXTERIOR, WALL FLOOD (SV, MH, ID, LED) | | 15 | EA | \$13,887 | CN |
| D5020 | LIGHTING - EXTERIOR, WALL LANTERN or FLOOD (INC, CFL, LED) | | 9 | EA | \$3,727 | CN |
| D5020 | LIGHTING - EXTERIOR, WALL LANTERN or FLOOD (INC, CFL, LED) | | 1 | EA | \$414 | CN |
| D5020 | LIGHTING SYSTEM, INTERIOR - OFFICE | 1950 | 22,827 | SF | \$291,712 | CN |
| D5020 | LIGHTING SYSTEM, INTERIOR - OFFICE | 1962 | 50,000 | SF | \$576,762 | CN |
| D5090 | EXIT SIGN - CENTRAL POWER | OLD | 45 | EA | \$15,159 | CN |
| D5090 | EMERGENCY LIGHT - UNITARY WITH BATTERY BACK-UP | OLD | 10 | EA | \$5,816 | CN |
| D5090 | GENERATOR - DIESEL (<30-100KW) | CUMMINS MARINE | 40 | KW | \$34,347 | CN |
| D5090 | SWITCH - AUTO TRANSFER, 208 OR 240 V (>100 AMP) | EPG 01 08 | 200 | AMP | \$4,795 | CN |
| D5090 | SWITCH - AUTO TRANSFER, 208 OR 240 V (>100 AMP) | ONAN | 400 | AMP | \$9,590 | CN |
| E2010 | CASEWORK - WOOD BASE AND WALL, TOP, STANDARD | | 1,200 | LF | \$585,632 | CN |
| E2010 | KITCHENETTE UNIT WITH CABINETRY AND AMENITIES | | 4 | EA | \$43,549 | CN |

Current Needs Cost for Asset No. 0001

\$11,295,590

| Uniformat Code | Component Description | | Qty | Units | 2015 Replacement Cost | Year |
|-------------------|--|------|---------|-------|-----------------------------|------|
| D5020 | LIGHTING SYSTEM, INTERIOR - OFFICE | 1989 | 10,000 | SF | \$133,447 | 2015 |
| C3020 | FLOORING - FLUID APPLIED, PAINT OR CLEAR SEAL | | 4,180 | SF | \$12,583 | 2015 |
| C3010 | WALL FINISH - PAINT, STANDARD | | 166,040 | SF | \$394,771 | 2015 |

Projected Component Replacement Cost for Asset No. 0001 for 2015

\$540,801

Recurring Component Renewal Schedule

No Projected Component Replacement Cost for Asset No. 0001 for 2016

| Uniformat Code | Component Description | | Qty | Units | 2017 Replacement Cost | Year |
|---|--|------------|--------|-------|-----------------------|------|
| B2010 | WALL, EXTERIOR, MASONRY POINTING | 1962 BLDG | 10,000 | SF | \$112,041 | 2017 |
| B2010 | WALL, EXTERIOR, MASONRY POINTING | 1950S BLDG | 8,500 | SF | \$95,235 | 2017 |
| B2010 | WALL, EXTERIOR, MASONRY POINTING | SEYBOLT | 5,200 | SF | \$58,261 | 2017 |
| B2010 | WALL, EXTERIOR, PANEL JOINT RESTORATION | PENTHOUSE | 1,650 | SF | \$40,558 | 2017 |
| G2030 | CONCRETE PEDESTRIAN PAVING - JOINT MAINTENANCE | | 250 | LF | \$1,299 | 2017 |
| G2020 | ASPHALT VEHICULAR PAVING - SEALCOAT AND STRIPE | | 1,000 | SY | \$3,621 | 2017 |
| Projected Component Replacement Cost for Asset No. 0001 for 2017 | | | | | \$311,015 | |

| Uniformat Code | Component Description | | Qty | Units | 2018 Replacement Cost | Year |
|---|--|--------------|--------|-------|-----------------------|------|
| D5090 | UNINTERRUPTIBLE POWER SUPPLY - 120/208 VOLTS | EATON 9355 | 1 | EA | \$74,965 | 2018 |
| B2030 | DOOR, EXTERIOR, OVERHEAD ROLLING METAL, LOCK | PD LOAD BAYS | 320 | SF | \$31,619 | 2018 |
| C3030 | CEILING FINISH - SUSPENDED ACOUSTICAL TILE, STANDARD | | 60,150 | SF | \$631,956 | 2018 |
| Projected Component Replacement Cost for Asset No. 0001 for 2018 | | | | | \$738,540 | |

| Uniformat Code | Component Description | | Qty | Units | 2019 Replacement Cost | Year |
|---|--------------------------------|------|-----|-------|-----------------------|------|
| D5090 | GENERATOR - DIESEL (<30-100KW) | ONAN | 39 | KW | \$37,691 | 2019 |
| Projected Component Replacement Cost for Asset No. 0001 for 2019 | | | | | \$37,691 | |

Recurring Component Renewal Schedule

| Uniformat Code | Component Description | | Qty | Units | 2020 Replacement Cost | Year |
|---|---------------------------------|-----------|-----|-------|-----------------------|------|
| D2020 | BACKFLOW PREVENTER (3-4 INCHES) | DOMESTIC | 1 | EA | \$8,569 | 2020 |
| D2020 | BACKFLOW PREVENTER (4-6 INCHES) | SPRINKLER | 1 | EA | \$12,507 | 2020 |
| Projected Component Replacement Cost for Asset No. 0001 for 2020 | | | | | \$21,076 | |

No Projected Component Replacement Cost for Asset No. 0001 for 2021

| Uniformat Code | Component Description | | Qty | Units | 2022 Replacement Cost | Year |
|---|-------------------------------------|----------------|-----|-------|-----------------------|------|
| D1010 | ELEVATOR CAB RENOVATION - PASSENGER | ELEVATOR A & B | 2 | EA | \$130,810 | 2022 |
| D1010 | ELEVATOR CAB RENOVATION - PASSENGER | SEYBOLT | 1 | EA | \$65,405 | 2022 |
| Projected Component Replacement Cost for Asset No. 0001 for 2022 | | | | | \$196,215 | |

| Uniformat Code | Component Description | | Qty | Units | 2023 Replacement Cost | Year |
|---|------------------------------------|-------------|-----|-------|-----------------------|------|
| D3040 | HUMIDIFIER, ELECTRIC, POINT-OF-USE | VAPOR LOGIC | 1 | EA | \$7,357 | 2023 |
| Projected Component Replacement Cost for Asset No. 0001 for 2023 | | | | | \$7,357 | |

| Uniformat Code | Component Description | | Qty | Units | 2024 Replacement Cost | Year |
|----------------|--|------|-----|-------|-----------------------|------|
| D2010 | PLUMBING FIXTURE - LAVATORY, COUNTER | 1989 | 3 | EA | \$4,600 | 2024 |
| D2010 | PLUMBING FIXTURE - LAVATORY, WALL HUNG | 1989 | 23 | EA | \$35,388 | 2024 |
| D2010 | PLUMBING FIXTURE - SINK, KITCHEN | 1989 | 4 | EA | \$9,800 | 2024 |
| D2010 | PLUMBING FIXTURE - SINK, SERVICE/LAUNDRY/UTILITY | 1989 | 3 | EA | \$6,144 | 2024 |
| D2010 | PLUMBING FIXTURE - SHOWER VALVE AND HEAD | 1989 | 7 | EA | \$13,955 | 2024 |

Recurring Component Renewal Schedule


| | | | | | | |
|-------|--|-------------|--------|----|-----------|------|
| D2010 | PLUMBING FIXTURE - URINAL | 1989 | 5 | EA | \$12,204 | 2024 |
| D2010 | PLUMBING FIXTURE - WATER CLOSET, TANKLESS | 1989 | 26 | EA | \$57,483 | 2024 |
| D2010 | PLUMBING FIXTURE - COMBINATION TOILET/SINK, STAINLESS STL, INSTITUTIONAL | 1989 | 5 | EA | \$16,502 | 2024 |
| D2020 | SUPPLY PIPING SYSTEM - OFFICE | 1989 | 20,000 | SF | \$104,591 | 2024 |
| C3010 | WALL FINISH - PAINT, STANDARD | UPPER FLOOR | 18,450 | SF | \$57,235 | 2024 |
| G2030 | CONCRETE PEDESTRIAN PAVING - JOINT MAINTENANCE | | 250 | LF | \$1,598 | 2024 |
| G2020 | ASPHALT VEHICULAR PAVING - SEALCOAT AND STRIPE | | 1,000 | SY | \$4,454 | 2024 |

Projected Component Replacement Cost for Asset No. 0001 for 2024

\$323,954

Recurring Component Expenditure Projections

0001 : MUNICIPAL COMPLEX



Average Annual Renewal Cost per SqFt \$5.91

FACILITY CONDITION ASSESSMENT

SECTION 5

DRAWINGS
AND PROJECT LOCATIONS

NO CAD DRAWINGS ARE
AVAILABLE FOR THIS
BUILDING

FACILITY CONDITION ASSESSMENT

SECTION 6

PHOTOGRAPHS

Photo Log - Facility Condition Assessment
0001 : MUNICIPAL COMPLEX

| Photo ID No. | Description | Location | Date |
|--------------|--|-----------------------------------|------------|
| 0001001a | Aerial photo of site | View from above | 01/23/2014 |
| 0001001e | Single-cell cooling tower | Roof | 01/23/2014 |
| 0001002a | Asphalt drive damage | North of boiler building | 01/23/2014 |
| 0001002e | Corrosion in cooling tower support | Roof | 01/23/2014 |
| 0001003a | 2009 roof | 1950s east addition | 01/23/2014 |
| 0001003e | Gas-fired package unit for Council Chambers | Roof | 01/23/2014 |
| 0001004a | Mechanical penthouse | 1962 building roof | 01/23/2014 |
| 0001004e | Exhaust fan for Council Chambers | Roof | 01/23/2014 |
| 0001005a | Exterior of 1929 and 1950s buildings | West facade | 01/23/2014 |
| 0001005e | Traction elevator machine | Mechanical penthouse | 01/23/2014 |
| 0001006a | 1990 roof | Police Department roof | 01/23/2014 |
| 0001006e | Elevator controllers | Mechanical penthouse | 01/23/2014 |
| 0001007a | 2009 roof | 1962 building roof | 01/23/2014 |
| 0001007e | Utility set restroom exhaust fan | Mechanical penthouse | 01/23/2014 |
| 0001008a | 2009 roof | 1950s and 1962 building connector | 01/23/2014 |
| 0001008e | Leaking hot water unit heater and pendant incandescent light | Mechanical penthouse | 01/23/2014 |
| 0001009a | Exterior of 1929 and 1950s buildings | East facade | 01/23/2014 |
| 0001009e | Retired steam radiator, cast-iron drain and vent piping | Storage room | 01/23/2014 |
| 0001010a | Lack of guardrail at elevated parking | 1926 building addition, east side | 01/23/2014 |
| 0001010e | Typical exit sign, smoke detector, lay-in light, supply diffuser | Elevator lobby | 01/23/2014 |
| 0001011a | 1962 building exterior | East facade | 01/23/2014 |
| 0001011e | Original electrical panels | Electrical closet | 01/23/2014 |
| 0001012a | 1962 building exterior | East facade | 01/23/2014 |
| 0001012e | Fire pull station, exit sign, two-pipe fan coil | Fourth floor corridor | 01/23/2014 |
| 0001013a | Non-compliant guardrail at roof | 1962 building addition, east side | 01/23/2014 |
| 0001013e | Sprinkler head, supply diffuser | Fourth floor conference room | 01/23/2014 |
| 0001014a | 1962 building exterior | North facade | 01/23/2014 |
| 0001014e | Typical water closet with manual flush valve | Fourth floor restroom | 01/23/2014 |
| 0001015a | Exterior of 1962, 1950s, and 1929 buildings | West facade | 01/23/2014 |
| 0001015e | Typical lavatory | Fourth floor restroom | 01/23/2014 |
| 0001016a | Exterior of 1962 and 1950s buildings | West facade | 01/23/2014 |
| 0001016e | Aged stainless steel sink | Fourth floor, break room | 01/23/2014 |

Photo Log - Facility Condition Assessment
0001 : MUNICIPAL COMPLEX

| Photo ID No. | Description | Location | Date |
|--------------|---|---|------------|
| 0001017a | 1929 building exterior | West facade | 01/23/2014 |
| 0001017e | Typical service sink | Fourth floor, custodial closet | 01/23/2014 |
| 0001018a | Main entry | 1950s building | 01/23/2014 |
| 0001018e | Shower stall | Third floor, shower room | 01/23/2014 |
| 0001019a | Exterior of 1962 building | South facade | 01/23/2014 |
| 0001019e | Newer electrical panel | Second floor corridor | 01/23/2014 |
| 0001020a | Exterior of 1929 building | West facade | 01/23/2014 |
| 0001020e | Typical water closet with manual flush valve | Second floor, women's restroom | 01/23/2014 |
| 0001021a | Damaged wall | 1962 building, west stairwell | 01/23/2014 |
| 0001021e | Counter lavatory with manual faucets | Second floor, women's restroom | 01/23/2014 |
| 0001022a | Damaged wall | 1962 building, fourth floor, north wall | 01/23/2014 |
| 0001022e | Powered rooftop ventilator for holding cells | Lower level roof | 01/23/2014 |
| 0001023a | Damaged wall | 1962 building, fourth floor, north wall | 01/23/2014 |
| 0001023e | Powered rooftop ventilator for locker rooms | Lower level roof | 01/23/2014 |
| 0001024a | Damaged wall | 1929 building, corridor | 01/23/2014 |
| 0001024e | Packaged heat pump for SERT area | Lower level roof | 01/23/2014 |
| 0001025a | Damaged vinyl tile | 1950s building, restroom | 01/23/2014 |
| 0001025e | Roof-mounted HID light | Roof | 01/23/2014 |
| 0001026a | Non-compliant water fountain and lack of signage | 1962 building, fourth floor, elevator lobby | 01/23/2014 |
| 0001026e | Fire suppression controller for Archives | Second floor vault | 01/23/2014 |
| 0001027a | Non-compliant handrail and guardrail | 1962 building, fourth floor, east stair | 01/23/2014 |
| 0001027e | Ceiling exhaust fan, sprinkler head, lay-in light | First floor waiting area | 01/23/2014 |
| 0001028a | Non-compliant kitchenette | 1962 building | 01/23/2014 |
| 0001028e | Fire suppression controller for Dispatch | First floor, dispatch area | 01/23/2014 |
| 0001029a | Non-compliant service counter | 1962 building, tax office | 01/23/2014 |
| 0001029e | Humidifier | First floor, dispatch area | 01/23/2014 |
| 0001030a | Non-compliant shower | 1962 building, third floor | 01/23/2014 |
| 0001030e | Chemical fire suppression (Inergen) tanks | First floor, dispatch area | 01/23/2014 |
| 0001031a | Non-compliant break room sink in Police Department | 1962 building, basement | 01/23/2014 |
| 0001031e | Updated electrical panels | First floor, dispatch area | 01/23/2014 |
| 0001032a | Non-compliant Police Department women's locker room | 1962 building, basement | 01/23/2014 |
| 0001032e | Uninterruptible power supply (UPS) | First floor, dispatch area | 01/23/2014 |

Photo Log - Facility Condition Assessment
0001 : MUNICIPAL COMPLEX

| Photo ID No. | Description | Location | Date |
|--------------|---|-------------------------------|------------|
| 0001033a | Stair with non-compliant handrails and lacking wall rail | 1950 building, center stair | 01/23/2014 |
| 0001033e | Ductless split DX system fan coil | First floor, dispatch area | 01/23/2014 |
| 0001034a | Non-compliant service counter at main reception | 1950s building, main entry | 01/23/2014 |
| 0001034e | Ventilation unit for basement firing range | East exterior | 01/23/2014 |
| 0001035a | Non-compliant platform in Council Chambers | 1950s building addition | 01/23/2014 |
| 0001035e | Stainless steel sink for fingerprinting area | First floor, processing | 01/23/2014 |
| 0001036a | Knob door hardware and lack of ADA compliant signage | 1962 building | 01/23/2014 |
| 0001036e | Service sink for fingerprinting area | First floor, processing | 01/23/2014 |
| 0001037a | Non-compliant restroom | 1962 building | 01/23/2014 |
| 0001037e | Combination sink and toilet | Holding cell | 01/23/2014 |
| 0001038a | Non-compliant restroom | Typical | 01/23/2014 |
| 0001038e | How water unit heater and interior lighting | Sallyport | 01/23/2014 |
| 0001039a | Non-compliant restroom | 1962 building | 01/23/2014 |
| 0001039e | Air handling unit in ceiling plenum | First floor, processing | 01/23/2014 |
| 0001040a | Non-compliant service counter in Police Department public entry | 1962 building | 01/23/2014 |
| 0001040e | Aged emergency generator | First floor, generator room | 01/23/2014 |
| 0001041a | Non-compliant restroom | 1962 building, basement | 01/23/2014 |
| 0001041e | Diesel fuel storage tanks | First floor, generator room | 01/23/2014 |
| 0001042a | Knob door hardware and lack of ADA compliant signage | 1929 bldg | 01/23/2014 |
| 0001042e | Diesel fuel day tank | First floor, generator room | 01/23/2014 |
| 0001043a | Stair with non-compliant handrail and lacking wall rail | 1929 building, center stair | 01/23/2014 |
| 0001043e | Fire alarm control panel | First floor, electrical room | 01/23/2014 |
| 0001044a | Non-compliant emergency egress stair | 1929 building, south exterior | 01/23/2014 |
| 0001044e | Main distribution panel (MDP-2) | First floor, electrical room | 01/23/2014 |
| 0001045e | Step-up transformer | First floor, electrical room | 01/23/2014 |
| 0001046e | Automatic transfer switch | First floor, electrical room | 01/23/2014 |
| 0001047e | Air handling unit | First floor, phone room | 01/23/2014 |
| 0001048e | Main distribution panel (MDP-1) | First floor, electrical room | 01/23/2014 |
| 0001049e | Bell-and-spigot and partially updated no-hub drain piping | Basement corridor | 01/23/2014 |
| 0001050e | Plastic drain piping | Unexcavated area in basement | 01/23/2014 |
| 0001051e | Conduit, hot water piping, drain piping | Unexcavated area in basement | 01/23/2014 |

Photo Log - Facility Condition Assessment
0001 : MUNICIPAL COMPLEX

| Photo ID No. | Description | Location | Date |
|--------------|---|------------------------------|------------|
| 0001052e | Air handling unit | Basement, mechanical room | 01/23/2014 |
| 0001053e | Water-cooled chiller | Basement, mechanical room | 01/23/2014 |
| 0001054e | Air handling unit | Basement, mechanical room | 01/23/2014 |
| 0001055e | Air handling unit | Basement, mechanical room | 01/23/2014 |
| 0001056e | Aged service sink | Basement, mechanical room | 01/23/2014 |
| 0001057e | Condenser water and chilled/heating hot water pumps | Basement, mechanical room | 01/23/2014 |
| 0001058e | HVAC control panel | Basement, mechanical room | 01/23/2014 |
| 0001059e | Updated air handling unit with split DX coil | Basement, mechanical room | 01/23/2014 |
| 0001060e | Shower valves and heads | Men's locker room | 01/23/2014 |
| 0001061e | Water closet with manual flush valves | Men's locker room | 01/23/2014 |
| 0001062e | Lavatories with manual faucets | Men's locker room | 01/23/2014 |
| 0001063e | Urinals with manual flush valves | Men's locker room | 01/23/2014 |
| 0001064e | Shower stall | Women's locker room | 01/23/2014 |
| 0001065e | Domestic hot water boiler | Basement, mechanical room | 01/23/2014 |
| 0001066e | Backflow preventer on sprinkler main | Unexcavated area in basement | 01/23/2014 |
| 0001067e | Backflow preventer on domestic water main | Unexcavated area in basement | 01/23/2014 |
| 0001068e | Water meter | Unexcavated area in basement | 01/23/2014 |
| 0001069e | Water supply piping and retired hot water storage tank | Unexcavated area in basement | 01/23/2014 |
| 0001070e | New domestic hot water storage tank | Basement, mechanical room | 01/23/2014 |
| 0001071e | Domestic hot water circulation pump | Basement, mechanical room | 01/23/2014 |
| 0001072e | Emergency generator | Basement, generator room | 01/23/2014 |
| 0001073e | Automatic transfer switch | Basement, generator room | 01/23/2014 |
| 0001074e | Updated lighting, exit signs, sprinkler heads | Fourth floor corridor | 01/23/2014 |
| 0001075e | Air-cooled condensing units for IT room | Lower level roof | 01/23/2014 |
| 0001076e | Updated stainless steel sink | Fourth floor, break room | 01/23/2014 |
| 0001077e | Instantaneous water heater | Fourth floor restroom | 01/23/2014 |
| 0001078e | Battery pack emergency light, sprinkler piping, lay-in lighting | Fourth floor corridor | 01/23/2014 |
| 0001079e | Elevator control panel | Inside elevator in Seybolt | 01/23/2014 |
| 0001080e | Old battery pack emergency light | Seybolt stairwell | 01/23/2014 |
| 0001081e | Unit ventilator | Seybolt office | 01/23/2014 |
| 0001082e | Surface-mounted lighting, sprinkler piping, unit ventilator | Solarium | 01/23/2014 |
| 0001083e | Aged restroom fixtures | Seybolt, third floor | 01/23/2014 |

Photo Log - Facility Condition Assessment
0001 : MUNICIPAL COMPLEX

| Photo ID No. | Description | Location | Date |
|--------------|--|----------------------------|------------|
| 0001084e | Aged restroom fixtures | Seybolt, third floor | 01/23/2014 |
| 0001085e | Split DX system fan coil | Third floor, IT room | 01/23/2014 |
| 0001086e | Ductless split DX system fan coil and chemical fire suppression controller | Third floor, IT room | 01/23/2014 |
| 0001087e | Chemical fire suppression (Halon) tanks | Third floor, IT room | 01/23/2014 |
| 0001088e | Aged ceramic sink | Third floor, break room | 01/23/2014 |
| 0001089e | Outdated, recessed, canned lights with incandescent lamps | Council Chambers | 01/23/2014 |
| 0001090e | Heating/chilled water circulating pumps | Basement, mechanical room | 01/23/2014 |
| 0001091e | Traction elevator machine for Seybolt elevator | Basement, mechanical room | 01/23/2014 |
| 0001092e | Traction elevator controller for Seybolt elevator | Basement, mechanical room | 01/23/2014 |
| 0001093e | Fire sprinkler risers | Basement, mechanical room | 01/23/2014 |
| 0001094e | Air compressor for dry-pipe sprinkler system | Basement, mechanical room | 01/23/2014 |
| 0001095e | Aged service sink | Basement, laundry room | 01/23/2014 |
| 0001096e | Gas-fired water heater | Basement, laundry room | 01/23/2014 |
| 0001097e | Copper water supply piping | Basement, mechanical room | 01/23/2014 |
| 0001098e | HID wall-pack | Southwest exterior | 01/23/2014 |
| 0001099e | Aged incandescent exterior wall-pack | Southeast exterior | 01/23/2014 |
| 0001100e | Utility-owned transformer and switch | East exterior | 01/23/2014 |
| 0001101e | Through-wall air conditioning unit and HID wall-pack | East exterior | 01/23/2014 |
| 0001102e | Air-cooled condensing units | North exterior | 01/23/2014 |
| 0001103e | Aged, recessed, canned incandescent lights | Main entrance to City Hall | 01/23/2014 |
| 0001104e | Pole-mounted walkway lights | West exterior | 01/23/2014 |
| 0001105e | Aged, ornate light fixture | Entrance to Seybolt | 01/23/2014 |

Facility Condition Assessment - Photo Log



0001001A.jpg



0001001E.jpg



0001002A.jpg



0001002E.jpg



0001003A.jpg



0001003E.jpg



0001004A.jpg



0001004E.jpg



0001005A.jpg



0001005E.jpg



0001006A.jpg



0001006E.jpg




0001007A.jpg



0001007E.jpg



0001008A.jpg



0001008E.jpg



0001009A.jpg



0001009E.jpg



0001010A.jpg



0001010E.jpg

Facility Condition Assessment - Photo Log



0001011A.jpg



0001011E.jpg



0001012A.jpg



0001012E.jpg



0001013A.jpg



0001013E.jpg



0001014A.jpg



0001014E.jpg



0001015A.jpg



0001015E.jpg



0001016A.jpg



0001016E.jpg



0001017A.jpg



0001017E.jpg



0001018A.jpg



0001018E.jpg



0001019A.jpg



0001019E.jpg



0001020A.jpg



0001020E.jpg


Facility Condition Assessment - Photo Log



0001021A.jpg



0001021E.jpg



0001022A.jpg



0001022E.jpg



0001023A.jpg



0001023E.jpg



0001024A.jpg



0001024E.jpg



0001025A.jpg



0001025E.jpg



0001026A.jpg



0001026E.jpg



0001027A.jpg




0001027E.jpg



0001028A.jpg



0001028E.jpg



0001029A.jpg



0001029E.jpg



0001030A.jpg



0001030E.jpg

Facility Condition Assessment - Photo Log



0001031A.jpg



0001031E.jpg



0001032A.jpg



0001032E.jpg



0001033A.jpg



0001033E.jpg



0001034A.jpg



0001034E.jpg



0001035A.jpg



0001035E.jpg



0001036A.jpg



0001036E.jpg



0001037A.jpg



0001037E.jpg



0001038A.jpg



0001038E.jpg



0001039A.jpg



0001039E.jpg



0001040A.jpg



0001040E.jpg

Facility Condition Assessment - Photo Log



0001041A.jpg



0001041E.jpg



0001042A.jpg



0001042E.jpg



0001043A.jpg



0001043E.jpg



0001044A.jpg



0001044E.jpg



0001045E.jpg



0001046E.jpg



0001047E.jpg



0001048E.jpg



0001049E.jpg



0001050E.jpg



0001051E.jpg



0001052E.jpg



0001053E.jpg



0001054E.jpg



0001055E.jpg



0001056E.jpg

Facility Condition Assessment - Photo Log



0001057E.jpg



0001058E.jpg



0001059E.jpg



0001060E.jpg




0001061E.jpg



0001062E.jpg



0001063E.jpg



0001064E.jpg



0001065E.jpg



0001066E.jpg



0001067E.jpg



0001068E.jpg



0001069E.jpg



0001070E.jpg



0001071E.jpg



0001072E.jpg



0001073E.jpg



0001074E.jpg



0001075E.jpg



0001076E.jpg

Facility Condition Assessment - Photo Log



0001077E.jpg




0001078E.jpg



0001079E.jpg



0001080E.jpg



0001081E.jpg



0001082E.jpg



0001083E.jpg



0001084E.jpg



0001085E.jpg




0001086E.jpg



0001087E.jpg



0001088E.jpg



0001089E.jpg



0001090E.jpg



0001091E.jpg



0001092E.jpg



0001093E.jpg



0001094E.jpg



0001095E.jpg



0001096E.jpg

Facility Condition Assessment - Photo Log



0001097E.jpg



0001098E.jpg



0001099E.jpg



0001100E.jpg



0001101E.jpg



0001102E.jpg



0001103E.jpg



0001104E.jpg



0001105E.jpg

