




**NOTES**

-  Repoint brick and precast.
-  Repoint precast only.
- 1** to **7** Repair precast corner blocks at these locations.
-  Remove and replace precast horizontal band at this location.

<b>BID #1-23 CITY HALL MASONRY REPAIRS</b>			
<b>NO SCALE</b>	<b>WORK PLAN</b>	<b>REVISED 08 10 22</b>	<b>DJH</b>